



650 25th Street, N.W., Suite 100
Cleveland, Tennessee 37311
(423) 303-7101

Email: mail@santekenviro.com
Internet: www.santekenviro.com

July 26, 2017

Mr. Patrick Mulligan
Tennessee Department of Environment and Conservation
Division of Solid Waste Management
3711 Middlebrook Pike
Knoxville, TN 37921-5602

RE: Groundwater Monitoring Report – 1st Semi-Annual Event
Matlock Bend Landfill
SNL #53-103-0203

Dear Mr. Mulligan:

Please find enclosed a copy of the groundwater monitoring report generated from the first semi-annual groundwater event of 2017 at the Matlock Bend Landfill. This package includes data pertaining to site information, geologic summary, groundwater sampling, analytical laboratory reports, statistical analysis, and groundwater elevations and flow.

If you have any questions and/or comments, please feel free to call at (423) 303-7101.

Sincerely,

A handwritten signature in black ink that reads "Robert Hudson". A horizontal line extends from the end of the signature across the page.

Robert Hudson
Environmental Compliance Coordinator

Enclosure

cc: Steve Field, Loudon County Solid Waste Department Chairman
Matt Dillard, Executive V.P. of Operations, Santek
Ron E. Vail, P.E., Executive V.P. of Engineering, Santek
Raymond Givens, Landfill Manager, Santek

**MATLOCK BEND LANDFILL – PHASE I & PHASE II/IV UPGRADE
GROUNDWATER MONITORING REPORT
1st SEMI-ANNUAL EVENT - 2017**

SANTEK PROJECT NO. 200-1710.1



**PREPARED BY:
SANTEK WASTE SERVICES
650 25TH STREET NW, SUITE 100
CLEVELAND, TN 37311**

JULY 2017

TABLE OF CONTENTS

1.0	Introduction.....	1
1.1	Site Information	1
2.0	Sampling and Analytical Summary.....	1
3.0	Statistical Analysis	1
3.1	Statistical Analysis Method.....	1
3.2	Statistical Analysis Summary.....	2
4.0	Flow Direction and Rates.....	3
5.0	Conclusions and Recommendations.....	3
	Appendix A.....	Groundwater Monitoring Well Field Logs
	Appendix B	Groundwater Analytical Results
	Appendix C	Control Charts
	Appendix D	Groundwater Flow Rate Calculations
	• Groundwater Data Table	
	• Groundwater Flow Rate Calculations	
	Appendix E.....	Groundwater Potentiometric Contour Map
	Appendix F.....	Leachate
	• Leachate Field Log	
	• Leachate Analytical Results	
	• Leachate Control Chart	

1.0 INTRODUCTION

In accordance with the Tennessee Department of Environment and Conservation's Solid Waste Processing and Disposal Rule 0400-11-01-.04(7), Santek Waste Services, Inc. (Santek) is submitting the groundwater monitoring report for the first semi-annual event for 2017 at the Matlock Bend Landfill. The sampling and analytical were performed in accordance with the Tennessee Department of Environment and Conservation's Solid Waste Processing and Disposal Rules as well as the site's approved groundwater monitoring plan dated December 1996. The groundwater monitoring plan is incorporated in the landfill's Operations Plan. The site's groundwater monitoring network consists of six monitoring wells, three downgradient wells for Phase I, two downgradient wells for Phase II/IV, with one upgradient well for both phases. MW-4R is the upgradient well for Phase I and Phase II/IV. MW-01, MW-1A, and MW-02 are the downgradient wells for Phase I; MW-03 and MW-05 are the downgradient wells for Phase II/IV. In accordance with the TDEC groundwater report review dated September 30, 2016, Santek is now monitoring the facility as one unit with one upgradient monitoring location (MW-4R). However, once Phase I ends the post-closure care period on January 21, 2028, the downgradient monitoring wells associated with Phase I will no longer continue to be monitored. Santek contracted with Environmental Monitoring Services, LLC (EMS) to perform the sampling. Statistical analyses were performed by Santek. Santek contracted with Analytical Environmental Services, Inc. (AES) to perform all analytical testing.

1.1 SITE INFORMATION

The Matlock Bend Landfill is located approximately five miles west of Loudon, TN, at latitude N 35° 44' 48" and longitude W 84° 24' 43". The site consists of 35.3 constructed acres of ridge-top and sloped hillside topography bordering Tennessee Highway 72 for approximately 250 feet extending northward 4,800 feet.

2.0 SAMPLING AND ANALYTICAL

The groundwater sampling event was performed by EMS on May 25 & 26, 2017. All samples were analyzed for Appendix I constituents, as well as the required additional 14 parameters at the Phase I wells (MW-01, MW-1A, MW-02, and MW-03). All samples were submitted to AES for analysis. A duplicate was obtained from MW-1A. Field sampling logs are provided in Appendix A. Analytical results are provided in Appendix B.

3.0 STATISTICAL ANALYSIS

3.1 Statistical Analysis Method

Santek is submitting a control chart approach to satisfy the statistical analysis requirement. Well #4R is the upgradient (background) well. Wells #01, #1A, #02, #03 and #05 are the downgradient (compliance) wells. The Appendix I analytical results for this sampling event are used to compare the compliance wells to the background well concentrations for each constituent elevated above detection limit. Parameters not detected above the reporting limits are not included in the control chart comparison. Parameters detected above the reporting limits are compared to the average background concentration. The mean (average) for each well is determined by using the actual analytical value if it exceeds the detection limit, or by using the method detection limit (MDL) if the result was a nondetect. If the average background concentration is greater than the results for the compliance well, then no significant increase is indicated. If the average

background concentration is less than the results of the compliance well, then the Tennessee (TN) Regulatory Limits of the Tennessee Solid Waste regulations are used for additional comparison to indicate potentially elevated concentrations. If there is no published TN Regulatory Limit, the EPA Region 4 Screening Level is used.

Arsenic, beryllium, cobalt, lead, and thallium are exceptions as the average background concentrations for these parameters exceed the TN Regulatory Limit or EPA Region 4 Screening Level due to higher report limits during past sampling events. For these parameters, the TN Regulatory Limit or EPA Region 4 Screening Level will be used initially for comparison. If parameters are detected above these limits/levels, the detections will be compared to the background results obtained during the sampling event to indicate potentially elevated concentrations. Control charts are provided in Appendix C.

3.2 Statistical Analysis Summary

MW-01

There were no inorganic or organic constituents detected above the report limits during this event.

MW-1A

There were no inorganic or organic constituents detected above the report limits during this event.

MW-02

The control chart for MW-02 indicates cadmium and zinc are above the report limit. However, the results of these constituents do not exceed background well's average which establishes the groundwater protection standards at this well.

The control chart for MW-02 indicates beryllium is above the report limit. However, the result of this constituent does not exceed the TN Regulatory Limit which establishes the groundwater protection standards at this well.

MW-03

The control chart for MW-03 indicates thallium is above the report limit. However, the result of this constituent does not exceed the TN Regulatory Limit which establishes the groundwater protection standards at this well.

The control chart for MW-03 indicates cobalt is above the report limit and the EPA Region 4 Screening Level. However, the result of this constituent is below the background well result for cobalt during this event.

MW-4R

MW-4R is the upgradient (background) well.

MW-05

The control chart for MW-02 indicates zinc is above the report limit. However, the result of this constituent does not exceed the background well's average which establishes the groundwater protection standards at this well.

4.0 FLOW DIRECTION AND RATES

Phase I Geological Summary:

Geologic information of Phase I is based on a Hydrogeologic Evaluation dated January 18, 1984, by G.N. Pruitt (TNDSWM). Phase I is located on a discontinuous, highly dissected upland with elevations ranging from approximately 865 feet (MSL) to 1,020 feet (MSL). The evaluation indicates a thick cover of silty-clayey soil which covers the majority of the site, the absence of shallow groundwater, and the absence of perennial springs and streams. No bedrock outcrops were viewed on site; however, an exposed dolomite limestone ledge resides east of the southeast property boundary. This rock exposure appears to originate from either the uppermost part of the Longview dolomite formation or the lower portion of the Newalla dolomite formation, both belonging to the Knox Group. Phase I is located in the Valley and Ridge physiographic region consisting of northeast/southwest trending valleys and ridges.

Phase II/IV Geological Summary:

Geologic information for Phase II/IV is based on a Hydrogeologic Investigation Report prepared by Theta Engineering, Inc. dated January 11, 1996. Phase II/IV is located in the Valley and Ridge physiographic region consisting commonly of northeast/southwest trending valleys and ridges. This area consists of discontinuous, highly dissected upland with elevations ranging from approximately 865 feet to 1,020 feet. Bedrock formations include the Copper Ridge Dolomite Formation and the Longview Dolomite Formation, both of which belong to the Knox Group. The area is dominantly covered by silty-clayey soil originating from the Fullerton, Clarksville, and Nolichucky Series.

Groundwater Flow:

The overall groundwater flow of Phase I is towards the southwest and will eventually flow to the Tennessee River. The groundwater flow rate ranges from 2.25×10^{-3} ft/day at MW-1A to 3.39×10^{-3} ft/day at MW-02. Groundwater flow direction of Phase II/IV locally flows towards the northwest and will ultimately flow to the Tennessee River. The groundwater flow rate ranges from 2.60×10^{-3} ft/day at MW-03 to 5.81×10^{-3} ft/day at MW-05. Groundwater flow rate and direction have been determined for each well and are included in Appendix D. A groundwater potentiometric contour map along with the Phase I and Phase II/IV limits is included in Appendix E.

5.0 CONCLUSIONS AND RECOMMENDATIONS

The groundwater monitoring network at this site is adequately monitoring the uppermost aquifer and no changes are recommended at this time.

APPENDIX A

EMServices

Environmental Monitoring Services, LLC
Phone (770) 516-2081 Fax (678) 445-3276

May 31, 2017

Robert Hudson
Santek Waste Services
650 25th Street NW, Suite 100
Cleveland, TN 37311

RE: Groundwater monitoring at Loudon County Phase I Landfill

Robert,

On May 25th and 26th, we completed the semi-annual groundwater monitoring at the referenced site. The sampling activities were performed in accordance with the site's operating permit and EPA Region IV SESD SOP's.

After collecting the water level, we calculated the purge volume to three well volumes using a standard formula. At each well, purging continued until at least three well volumes were removed and the field parameters were stable, or until the well was dry. The purge water was captured in 5 gallon buckets to quantify the purge volumes.

We employed a submersible pump for the purging of wells MW-01, 1A, 02, and 03. The pump used was attached to Teflon-lined tubing. The tubing and pump were washed after sampling the well using a Liquinox soap solution followed by a water rinse.

The wells were sampled using the same pump used to purge the well. The VOC and fluoride samples were collected immediately. If turbidity was at an unacceptable level when purging was complete (all other parameters stable), the well was allowed to settle for several hours or overnight, but less than 24 hours. The wells that were initially purged and sampled with a submersible pump but had high turbidities later had metals samples collected using a new disposable poly bailer attached to new nylon string.

During the purging process, pH, conductivity, temperature and turbidity readings were collected and recorded in the logbook. Turbidity readings were again recorded at the time of metals sample collection if the well was allowed to settle. Field readings were recorded from the initial water pulled (0 gallons), well volume 1, well volume 2, well volume 2.5 and well volume 3. Stability was based on volume, rather than time (though the time between measurements fell within range of accepted guidance). The stability criteria used based on accepted guidance was at least 3 sets of readings within the following ranges: pH (± 0.1 SU), SC ($\pm 10\%$), Temperature ($\pm 1^{\circ}\text{C}$), and Turbidity (<10 NTU). If the measurements weren't stable as defined by the above criteria at the completion of purging 3 well volumes, purging continued and readings recorded generally every 0.5 well volume up to 5 well volumes. These readings were recorded from YSI Pro Plus's which were calibrated each morning. Turbidity readings were collected using a Hach DR-820 or a Hach 2100Q, which are zeroed periodically throughout the day. The Hach meters contain a factory calibration which is checked in-house using formazine standards.

"For all your environmental monitoring needs"

106A Hartwood Drive
Woodstock, GA 30189
inquiry@emservicesonline.com

Page 1 of 2

The samples were collected in containers provided by the laboratory. These containers were of types, sizes and preserved in a manner consistent with SW-846 and other guidance. Upon filling, the containers were placed on ice. The samples were delivered under chain of custody via lab courier to Analytical Environmental Services, (AES), located in Atlanta, Georgia.

We appreciate the opportunity to work with you on this project, and look forward to any feedback you have.

Respectfully,



Jeff Johnson

Attachments: Groundwater Field Data

FIELD SAMPLING LOG		WELL NO: MW-01
Location: Loudon County Landfill		Site: Matlock Bend Phase I
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) <u>5/25/17</u> (Time) <u>1107</u>	Purge End: (Date) <u>5/25/17</u> (Time) <u>1126</u>	
Purged by: <u>RKen</u>		
Depth Measurement Ref. Point* 830.87 ft		Well Casing. ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 45.00 (-) Orig. DTW: 3.82 (=) Wtr. Col. Thick: 41.18

2"=0.163 Gals./ft. (=) 6.71 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 20.14 Total Purge Gals.

GW elev. Ref. 830.87 ft. (-) DTW: 3.82 ft. = 827.05 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.86 (gallons per minute)

Weather: C (°F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1107	0.0	7.18	378	14.5	252		cloudy, no odor
1111	6.75	6.34	381	14.5	992		cloudy, no odor
1114	10.25	6.25	383	14.7	437		cloudy, no odor
1117	13.50	6.24	385	14.6	368		cloudy, no odor
1120	17.00	6.23	386	14.4	270		cloudy, no odor
1123	20.25	6.23	387	14.5	191		cloudy, no odor
1126	22.50	6.23	388	14.4	183		cloudy, no odor

Turbidity at metals sample collection: 9 NTU's 5/26/17 @ 0740

Comments: orange, cloudy, no odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: MW-1A
Location: Loudon County Landfill		Site: Matlock Bend Phase I
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) 5/25/17 (Time) 1019		Purge End: (Date) 5/25/17 (Time) 1032
Purged by: Rerry		
Depth Measurement Ref. Point* 805.13 ft		Well Casing. ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 38.00 (-) Orig. DTW: 7.63 (=) Wtr. Col. Thick: 30.37

2"=0.163 Gals./ft. (=) 4.95 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 14.85 Total Purge Gals.

GW elev. Ref. 805.13 ft. (-) DTW: 7.63 ft. = 797.50 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 1.25 (gallons per minute)

Weather: cloudy (55 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1019	0.0	5.80	571	14.2	57		cloudy, no odor
1022	5.00	5.89	693	14.6	90		cloudy, no odor
1024	7.50	5.99	730	14.2	97		cloudy, no odor
1026	10.00	6.05	755	14.1	200		cloudy, no odor
1028	12.50	6.09	763	14.2	321		cloudy, no odor
1030	15.00	6.11	767	14.2	502		Cloudy, no odor
1032	17.60	6.13	769	14.2	830		Cloudy, no odor

Turbidity at metals sample collection: 0 NTU's 5/26/17 @ 0748

Comments: Duplicate pulled here 5/25/17 @ 1700
cloudy, no odor 5/26/17 @ 1700

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: MW-02
Location: Loudon County Landfill		Site: Matlock Bend Phase I
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) <u>5-25-17</u> (Time) <u>1143</u>	Purge End: (Date) <u>5-25-17</u> (Time) <u>1159</u>	
Purged by: <u>J Muller</u>		
Depth Measurement Ref. Point* <u>825.20</u> ft	Well Casing. ID: <u>4"</u>	

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 43.10 (-) Orig. DTW: 7.33 (=) Wtr. Col. Thick: 35.77

$2'' = 0.653$ Gals./ft. (=) 5.83 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 17.49 Total Purge Gals.

GW elev. Ref. 825.20 ft. (-) DTW: 7.33 ft. = 817.87 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.67 (gallons per minute)

Weather: Cloudy (60 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
<u>1143</u>	<u>0</u>	<u>6.20</u>	<u>S1</u>	<u>15.1</u>	<u>0</u>		<u>clear, no odor</u>
<u>1154</u>	<u>6.00</u>	<u>4.09</u>	<u>S2</u>	<u>15.0</u>	<u>9</u>		<u>clear, no odor</u>
<u>1159</u>	<u>8.75</u>	<u>4.13</u>	<u>47</u>	<u>15.1</u>	<u>0</u>		<u>clear, no odor</u>

Turbidity at metals sample collection: 0 NTU's

Comments: purged dry at 1.5 wv clear, no odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: MW-03
Location: Loudon County Landfill		Site: Matlock Bend Phases I / II / IV
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) 5-25-17 (Time) 1043	Purge End: (Date) 5-25-17 (Time) 1059	
Purged by: J Muller		
Depth Measurement Ref. Point* 867.86 ft		Well Casing. ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 41.60 (-) Orig. DTW: 15.03 (=) Wtr. Col. Thick: 26.57

2"=0.163 Gals./ft. (=) 4.33 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 12.99 Total Purge Gals.

GW elev. Ref. 867.86 ft. (-) DTW: 15.03 ft. = 852.83 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.56 (gallons per minute)

Weather: cloudy (60°F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)	Comments
1043	0	4.99	269	15.0	4	clear no odor
1051	4.50	5.25	261	15.4	31	clear no odor
1059	6.50	5.27	276	15.5	7	clear no odor
	8.75					
	11.00					
	13.00					

Turbidity at metals sample collection: 7 NTU's

Comments: purged dry. at 1.5 wv clear, no odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: Equipment Blank	
Location: Loudon County Landfill		Site: Matlock Bend	
Client/Operator: Santek Waste Services, Inc.		Project No:	
Purge Start: (Date) <u>5/25/17</u> (Time) <u>1425</u>		Purge End: (Date) <u>-</u> (Time) <u>-</u>	
Purged by: <u>RKM</u>			
Depth Measurement Ref. Point*	N/A	ft	Well Csg. ID: N/A

Equipment Used to Measure (Make, Model, etc)

DTW N/A pH YSI Cond. YSI T° YSI

Measure Well TD: N/A (-) Orig. DTW: N/A (=) Wtr. Col. Thick: N/A

(x) 2"=0.163 Gals./ft. (=) N/A Gals./Csg. Vol. (x) 3 Csg. Vol. (=) N/A Total Purge
Gals.

GW elev. Ref. N/A ft. (-) DTW: N/A ft. = N/A ft.

Purge/Sample Method: Directly filling containers

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: N/A (gallons per minute)

Weather: cloudy (60 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments

Turbidity at metals sample collection: - NTU's

Comments: Lab provided DI Water

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

EMServices

Environmental Monitoring Services, LLC
Phone (770) 516-2081 Fax (678) 445-3276

May 31, 2017

Robert Hudson
Santek Waste Services
650 25th Street NW, Suite 100
Cleveland, TN 37311

RE: Groundwater monitoring at Loudon County Phase II/IV Landfill

Robert,

On May 25th and 26th, we completed the semi-annual groundwater monitoring at the referenced site. The sampling activities were performed in accordance with the site's operating permit and EPA Region IV SESD SOP's.

After collecting the water level, we calculated the purge volume to three well volumes using a standard formula. At each well, purging continued until at least three well volumes were removed and the field parameters were stable, or until the well was dry. The purge water was captured in 5 gallon buckets to quantify the purge volumes.

We employed a submersible pump for the purging of wells MW-03, 4R and 05. The pump used was attached to Teflon-lined tubing. The tubing and pump were washed after sampling the well using a Liquinox soap solution followed by a water rinse. We also collected a leachate sample via direct grab.

The wells were sampled using the same pump used to purge the well. The VOC and fluoride samples were collected immediately. If turbidity was at an unacceptable level when purging was complete (all other parameters stable), the well was allowed to settle for several hours or overnight, but less than 24 hours. The wells that were initially purged and sampled with a submersible pump but had high turbidities later had metals samples collected using a new disposable poly bailer attached to new nylon string.

During the purging process, pH, conductivity, temperature and turbidity readings were collected and recorded in the logbook. Turbidity readings were again recorded at the time of metals sample collection if the well was allowed to settle. Field readings were recorded from the initial water pulled (0 gallons), well volume 1, well volume 2, well volume 2.5 and well volume 3. Stability was based on volume, rather than time (though the time between measurements fell within range of accepted guidance). The stability criteria used based on accepted guidance was at least 3 sets of readings within the following ranges: pH (± 0.1 SU), SC ($\pm 10\%$), Temperature ($\pm 1^{\circ}\text{C}$), and Turbidity (<10 NTU). If the measurements weren't stable as defined by the above criteria at the completion of purging 3 well volumes, purging continued and readings recorded generally every 0.5 well volume up to 5 well volumes. These readings were recorded from YSI Pro Plus's which were calibrated each morning. Turbidity readings were collected using a Hach DR-820 or Hach

"For all your environmental monitoring needs"

106A Hartwood Drive
Woodstock, GA 30189
inquiry@emservicesonline.com

Page 1 of 2

2100Q, which are zeroed periodically throughout the day. The Hach meters contain a factory calibration which is checked in-house using formazine standards.

The samples were collected in containers provided by the laboratory. These containers were of types, sizes and preserved in a manner consistent with SW-846 and other guidance. Upon filling, the containers were placed on ice. The samples were delivered under chain of custody via lab courier to Analytical Environmental Services, (AES), located in Atlanta, Georgia.

We appreciate the opportunity to work with you on this project, and look forward to any feedback you have.

Respectfully,



Jeff Johnson

Attachments: Groundwater Field Data

FIELD SAMPLING LOG		WELL NO: MW-03
Location: Loudon County Landfill		Site: Matlock Bend Phases I / II / IV
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) <u>5-25-17</u> (Time) <u>1043</u>		Purge End: (Date) <u>5-25-17</u> (Time) <u>1059</u>
Purged by: <u>J Muller</u>		
Depth Measurement Ref. Point*	867.86	ft. Well Casing, ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 41.60 (-) Orig. DTW: 15.03 (=) Wtr. Col. Thick: 26.57

2"=0.163 Gals./ft. (=) 4.33 Gals./Csg. Vol. (x) .3 Csg. Vol. (=) 1.300 Total Purge Gals. 12.99

GW elev. Ref. 867.86 ft. (-) DTW: 15.03 ft. = 852.83 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.56 (gallons per minute)

Weather: cloudy (60 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1043	0	4.99	269	15.0	4	clear no odor	
1051	4.50	5.25	261	15.4	31	clear no odor	
1059	6.50	5.27	276	15.5	7	clear no odor	
	<u>8.75</u>						
	<u>11.00</u>						
	<u>13.00</u>						

Turbidity at metals sample collection: 7 NTU's

Comments: purged dry. at 1.5 wv clear, no odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: MW-4R
Location: Loudon County Landfill		Site: Matlock Bend Phases II/IV
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) 5/25/17 (Time) 1239		Purge End: (Date) 5/25/17 (Time) 1305
Purged by: J Muller, R Kerr		
Depth Measurement Ref. Point* 992.32 ft		Well Casing, ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 106.50 (-) Orig. DTW: 95.53 (=) Wtr. Col. Thick: 10.97

2"=0.163 Gals./ft. (=) 1.79 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 5.36 Total Purge Gals.

GW elev. Ref. 992.32 ft. (-) DTW: 95.53 ft. = 896.82 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.11 (gallons per minute)

Weather: cloudy (60 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1239	0	4.97	112	18.1	77		clear, no odor cloudy
1258	2.00	5.79	245	18.4	265		beige, no odor
1305	2.75	6.05	182	19.8	310		beige, no odor
	3.75						
	4.50						
	5.50						

Turbidity at metals sample collection: 20 NTU's 0740 metals collected

Comments: purged dry at 1.5wv beige, no odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

FIELD SAMPLING LOG		WELL NO: MW-05
Location: Loudon County Landfill		Site: Matlock Bend Phases II/IV
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) 5-25-17 (Time) 1322		Purge End: (Date) 5-25-17 (Time) 1410
Purged by: J Muller, R Kerr		
Depth Measurement Ref. Point* 936.84 ft		Well Casing. ID: 2"

Equipment Used to Measure (Make, Model, etc)

DTW Slope pH YSI Cond. YSI T° YSI

Measure Well TD: 172.71 (-) Orig. DTW: 83.82 (=) Wtr. Col. Thick: 88.89

(x) 2"=0.163 Gals./ft. (=) 14.49 Gals./Csg. Vol. (x) 3 Csg. Vol. (=) 43,47 Total Purge Gals.

GW elev. Ref. 936.84 ft. (-) DTW: 83.82 ft. = 853.02 ft.

Purge/Sample Method: Disposable Poly Bailer or SS Electric Submersible Pump

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: 0.91 (gallons per minute)

Weather: cloudy (65 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (µS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1322	0	6.65	226	16.0	22		clear, no odor
1338	14.50	7.22	230	16.3	28		clear, no odor
1346	21.75	7.34	236	16.3	60		cloudy, no odor
1354	29.00	7.37	230	16.3	18		clear, no odor
1402	36.25	7.39	230	16.3	8		clear, no odor
1410	43.50	7.38	230	16.3	5		clear, no odor

Turbidity at metals sample collection: 5 NTU's

Comments: clear, no odor

FIELD SAMPLING LOG		WELL NO: Equipment Blank
Location: Loudon County Landfill		Site: Matlock Bend
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) 5/25/17	(Time) 1425	Purge End: (Date) - (Time) -
Purged by: R Kerr		
Depth Measurement Ref. Point*	N/A	ft
		Well Csg. ID: N/A

Equipment Used to Measure (Make, Model, etc)

DTW N/A pH YSI Cond. YSI T° YSI

Measure Well TD: N/A (-) Orig. DTW: N/A (=) Wtr. Col. Thick: N/A

(x) 2"=0.163 Gals./ft. (=) N/A Gals./Csg. Vol. (x) 3 Csg. Vol. (=) N/A Total Purge Gals.

GW elev. Ref. N/A ft. (-) DTW: N/A ft. = N/A ft.

Purge/Sample Method: Directly filling containers

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: N/A (gallons per minute)

Weather: cloudy (60 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
-	-	-	-	-	-	-	-

Turbidity at metals sample collection: NTU's

Comments: Lab provided DI Water

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

APPENDIX B



ANALYTICAL ENVIRONMENTAL SERVICES, INC.

June 09, 2017

Robert Hudson
Santek Environmental Inc.
650 25th Street NW, Suite 100
Cleveland TN 37311

RE: Loudon County (Matlock Bend) Landfill Phase 1

Dear Robert Hudson:

Order No: 1705Q20

Analytical Environmental Services, Inc. received 10 samples on May 26, 2017 2:41 pm for the analyses presented in following report.

No problems were encountered during the analyses. Additionally, all results for the associated Quality Control samples were within EPA and/or AES established limits. Any discrepancies associated with the analyses contained herein will be noted and submitted in the form of a project Case Narrative.

AES's accreditations are as follows:

-NELAC/Florida State Laboratory ID E87582 for analysis of Non-Potable Water, Solid & Chemical Materials, and Drinking Water Microbiology, effective 07/01/16-06/30/17.

State of Georgia, Department of Natural Resources ID #800 for analysis of Drinking Water Metals, effective 07/01/16-06/30/17 and Total Coliforms and E. coli, effective 04/25/17-04/24/20.

-NELAC/Louisiana Agency Interest No. 100818 for or analysis of Non-Potable Water and Solid & Chemical Materials, effective 07/01/16-06/30/17.

-AIHA-LAP, LLC Laboratory ID: 100671 for Industrial Hygiene samples (Organics, Metals, PCM Asbestos, Gravimetric), Environmental Lead (Paint, Soil, Dust Wipes, Air), and Environmental Microbiology (Fungal) Direct Examination, effective until 09/01/17.

These results relate only to the items tested. This report may only be reproduced in full.

If you have any questions regarding these test results, please feel free to call.

Sincerely,

Chris Pafford
Project Manager



ANALYTICAL ENVIRONMENTAL SERVICES, INC

3785 Presidential Parkway, Atlanta GA 30340-3704

AES TEL: (770) 457-8177 / TOLL-FREE (800) 972-4889 / FAX: (770) 457-8188

CHAIN OF CUSTODY

Work Order:

1705Q20

Date: 5-26-17 Page 1 of 1

COMPANY: Santek Environmental Inc.		ADDRESS: 650 28th St NW, Ste 100, Cleveland, TN 37311		ANALYSIS REQUESTED								Visit our website www.aesatlanta.com to check on the status of your results, place bottle orders, etc.	No # of Containers				
PHONE: 423/303-7101		FAX:		TN App	VOC (820)												
SAMPLED BY: J Muller, R Kerr		SIGNATURE: <i>J Muller, R Kerr</i>		TN App	VOC (820)	TN App	TAC (K+S+Hg+ (Cr,Fe, Ni, K))	Diss. Nm	COD	TDS	C, Cl, NO ₃ , SO ₄			CN	TDC, NH ₃		
#	SAMPLE ID	SAMPLED		Composite	Matrix (See codes)	PRESERVATION (See codes)								REMARKS			
		DATE	TIME			Grab	H+I	I	N	I	S+I	I	I		NaOH/S+I		
1	MW-01	5-25-17	1126	X	GW	2	2	1	1	1	1	1	1		10		
2	↪	5-26-17	0740	X	GW			1							1		
3	MW-1A	5-25-17	1032	X	GW	2	2	1	1	1	1	1	1		10		
4	↪	5-26-17	0748	X	GW			1							1		
5	MW-02	5-25-17	1159	X	GW	2	2	1	1	1	1	1	1		11		
6	MW-03	5-25-17	1059	X	GW	2	2	1	1	1	1	1	1		11		
7	Duplicate	5-25-17	1700	X	GW	2	2	1	1	1	1	1	1		10		
8	↪	5-26-17	1700	X	GW			1							1		
9	Equipment Blank	5-25-17	1425	X	GW	2	2	1	1	1	1	1	1		11		
10	Trip Blank	5-25-17	0900	X	W	2	2	1	1	1	1	1	1		11		
11																	
12																	
13																	
14																	
RELINQUISHED BY		DATE/TIME		RECEIVED BY		DATE/TIME		PROJECT INFORMATION								RECEIPT	
1: <i>J Muller</i> 5/26/17 1800		1: <i>G桑顿</i> 5-26-17 1502						PROJECT NAME: Loudon County (Marlock Bend) Landfill Phase I								Total # of Containers 77	
2: <i>C桑顿</i> 5-26-17 2:41		2: <i>Robert Hudson</i> 5/26/17 241						PROJECT #: _____								<input checked="" type="checkbox"/> Turnaround Time Request	
3:		3:						SITE ADDRESS: 21712 Hwy 72 N, Loudon, TN 37774								<input type="radio"/> Standard 5 Business Days	
								SEND REPORT TO: Robert Hudson								<input type="radio"/> 2 Business Day Rush	
								INVOICE TO: (IF DIFFERENT FROM ABOVE)								<input type="radio"/> Next Business Day Rush	
								QUOTE #: _____ PO#: _____								<input type="radio"/> Same Day Rush (auth req.)	
																<input type="radio"/> Other _____	
																STATE PROGRAM (if any): TN	
																E-mail? <input checked="" type="checkbox"/> N; Fax? <input checked="" type="checkbox"/> Y	
																DATA PACKAGE: I <input checked="" type="checkbox"/> II <input type="checkbox"/> III <input type="checkbox"/> IV	

SAMPLES RECEIVED AFTER 3PM OR SATURDAY ARE CONSIDERED AS RECEIVED ON THE NEXT BUSINESS DAY; IF NO TAT IS MARKED ON COC AES WILL PROCEED AS STANDARD TAT.

SAMPLES ARE DISPOSED OF 30 DAYS AFTER COMPLETION OF REPORT UNLESS OTHER ARRANGEMENTS ARE MADE.

MATRIX CODES: A = Air GW = Groundwater SE = Sediment SW = Surface Water W = Water (Blanks) DW = Drinking Water (Blanks) O = Other (specify)

PRESERVATIVE CODES: H+I = Hydrochloric acid + ice I = Ice only N = Nitric acid S+I = Sulfuric acid + ice S/M+I = Sodium Bisulfate/Methanol + ice O = Other (specify) NA = None

White Copy - Original; Yellow Copy - Client

Client: Santek Environmental Inc.
Project: Loudon County (Matlock Bend) Landfill Phase I
Lab ID: 1705Q20

Case Narrative**Sample Receiving Nonconformance:**

Sample ID MW-03 as received did not meet specified pH range for the requested test methods 6020 and 7470 of <2. Lab attempted to adjust pH at receipt using the maximum allowable amount of preservative, however, the required pH was not obtained. The lab proceeded at the request of Robert Hudson via phone 05-26-17.

The turn around time on the Chain of Custody was listed as a 2 day rush, however the TAT was changed to standard per Robert Hudson via email 05-26-17.

Micro-extractable VOC Analysis by Method 8011:

Matrix spike duplicate analyses were not performed with Batch 243324 due to insufficient sample volume.

Total Organic Carbon Analysis by Method SM5310B:

Due to sample matrix, samples 1705Q20-001H, -003H, -005H, -006H, and -007H required dilution during preparation and/or analysis resulting in elevated reporting limits.



Clear

Save as

SAMPLE/COOLER RECEIPT CHECKLIST

1. Client Name: **Santek Environmental Inc.**AES Work Order Number: **1705Q20**2. Carrier: FedEx UPS USPS Client Courier Other

	Yes	No	N/A	Details	Comments
3. Shipping container/cooler received in good condition?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	damaged <input type="checkbox"/> leaking <input type="checkbox"/> other <input type="checkbox"/>	
4. Custody seals present on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
5. Custody seals intact on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
6. Temperature blanks present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
7. Cooler temperature(s) within limits of 0-6°C? [See item 13 and 14 for temperature recordings.]	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Cooling initiated for recently collected samples / ice present <input type="checkbox"/>	
8. Chain of Custody (COC) present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
9. Chain of Custody signed, dated, and timed when relinquished and received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
10. Sampler name and/or signature on COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
11. Were all samples received within holding time?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
12. TAT marked on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	If no TAT indicated, proceeded with standard TAT per Terms & Conditions. <input type="checkbox"/>	

13. Cooler 1 Temperature 2.3 °C Cooler 2 Temperature 1.8 °C Cooler 3 Temperature _____ °C Cooler 4 Temperature _____ °C

14. Cooler 5 Temperature _____ °C Cooler 6 Temperature _____ °C Cooler 7 Temperature _____ °C Cooler 8 Temperature _____ °C

15. Comments:

I certify that I have completed sections 1-15 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
16. Were sample containers intact upon receipt?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
17. Custody seals present on sample containers?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
18. Custody seals intact on sample containers?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
19. Do sample container labels match the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Incomplete info <input type="checkbox"/> illegible <input type="checkbox"/> no label <input type="checkbox"/> other <input type="checkbox"/>	
20. Are analyses requested indicated on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
21. Were all of the samples listed on the COC received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	samples received but not listed on COC <input type="checkbox"/> samples listed on COC not received <input type="checkbox"/>	
22. Was the sample collection date/time noted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
23. Did we receive sufficient sample volume for indicated analyses?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
24. Were samples received in appropriate containers?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
25. Were VOA samples received without headspace (< 1/4" bubble)?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
26. Were trip blanks submitted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	listed on COC <input checked="" type="checkbox"/> not listed on COC <input type="checkbox"/>	

27. Comments:

I certify that I have completed sections 16-27 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
28. Have containers needing chemical preservation been checked?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
29. Containers meet preservation guidelines?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
30. Was pH adjusted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE

I certify that I have completed sections 28-30 (dated initials).

AJ 5/26/17



ANALYTICAL ENVIRONMENTAL SERVICES, INC.

June 09, 2017

Robert Hudson
Santek Environmental Inc.
650 25th Street NW, Suite 100
Cleveland TN 37311

RE: Loudon County (Matlock Bend) Phase II/IV LF

Dear Robert Hudson:

Order No: 1705Q25

Analytical Environmental Services, Inc. received 6 samples on 5/26/2017 2:41:00 PM for the analyses presented in following report.

No problems were encountered during the analyses. Additionally, all results for the associated Quality Control samples were within EPA and/or AES established limits. Any discrepancies associated with the analyses contained herein will be noted and submitted in the form of a project Case Narrative.

AES's accreditations are as follows:

-NELAC/Florida State Laboratory ID E87582 for analysis of Non-Potable Water, Solid & Chemical Materials, and Drinking Water Microbiology, effective 07/01/16-06/30/17.

State of Georgia, Department of Natural Resources ID #800 for analysis of Drinking Water Metals, effective 07/01/16-06/30/17 and Total Coliforms and E. coli, effective 04/25/17-04/24/20.

-NELAC/Louisiana Agency Interest No. 100818 for or analysis of Non-Potable Water and Solid & Chemical Materials, effective 07/01/16-06/30/17.

-AIHA-LAP, LLC Laboratory ID: 100671 for Industrial Hygiene samples (Organics, Metals, PCM Asbestos, Gravimetric), Environmental Lead (Paint, Soil, Dust Wipes, Air), and Environmental Microbiology (Fungal) Direct Examination, effective until 09/01/17.

These results relate only to the items tested. This report may only be reproduced in full.

If you have any questions regarding these test results, please feel free to call.

Sincerely,

Chris Pafford
Project Manager



ANALYTICAL ENVIRONMENTAL SERVICES, INC

3080 Presidential Drive, Atlanta GA 30340-3704

AES

TEL.: (770) 457-8177 / TOLL-FREE (800) 972-4889 / FAX: (770) 457-8188

CHAIN OF CUSTODY

Work Order: 705025Date: 5-26-17 Page 1 of 1

COMPANY: <i>Sentek Environmental Inc.</i>		ADDRESS: 680 25th St NW, Ste 100 Cleveland, TN 37311		ANALYSIS REQUESTED										Visit our website www.aesatlanta.com to check on the status of your results, place bottle orders, etc.	No # of Containers					
PHONE: <u>423/303-7101</u>		FAX:		<input checked="" type="checkbox"/> IN App I <input checked="" type="checkbox"/> IN Vac (Bottle) <input checked="" type="checkbox"/> IN App II <input checked="" type="checkbox"/> IN Vac (Soil) <input checked="" type="checkbox"/> IN App III <input checked="" type="checkbox"/> IN Metal/Filter <input checked="" type="checkbox"/> IN App IV <input checked="" type="checkbox"/> IN Fluoride																
SAMPLED BY: <u>J Muller, RKen</u>		SIGNATURE: <i>RKen</i>		PRESERVATION (Sec codes)										REMARKS						
#	SAMPLE ID	SAMPLED		Grab	Composite	Matrix (See codes)	H	I	N	I										
		DATE	TIME																	
1	MW-03	5-25-17	1059	X		GW	2	2	1	1					shard w/ phase 1	6				
2	MW-4R	5-25-17	1305	X		GW	2	2		1						5				
3	L7	5-26-17	0740	X		GW			1							1				
4	MW-05	5-25-17	1410	X		GW	2	2	1	1						6				
5	Equipment Blank	5-25-17	1425	X		W	2	2	1	1						6				
6	Tip Blank	5-25-17	0900	X		U	2	2	1	1					shard w/ phase 1	6				
7																				
8																				
9																				
10																				
11																				
12																				
13																				
14																				
RELINQUISHED BY		DATE/TIME		RECEIVED BY		DATE/TIME		PROJECT INFORMATION										RECEIPT		
1: <i>J Muller</i> 5/26/17 1300		1: <i>C桑格</i> 5-26-17		2: <i>C桑格</i> 5-26-17		2: <i>John Hwang</i> 5/26/17 2441		PROJECT NAME: <i>Loudon County (McHale Bend) Phase II/IV LP</i>										Total # of Containers	30	
2: <i>C桑格</i> 5-26-17		2: <i>John Hwang</i> 5/26/17		3: <i>John Hwang</i> 5/26/17		3: <i>John Hwang</i> 5/26/17		PROJECT #: SITE ADDRESS: 21712 Hwy 72 N Loudon, TN 37774										Turnaround Time Request	Standard 5 Business Days	
3:								SEND REPORT TO: Robert Hudson										2 Business Day Rush	Next Business Day Rush	
SPECIAL INSTRUCTIONS/COMMENTS:		SHIPMENT METHOD		OUT / / VIA:		IN / / VIA:		INVOICE TO: (IF DIFFERENT FROM ABOVE)										Same Day Rush (auth req.)	Other _____	
		CLIENT FedEx UPS MAIL COURIER		GREYHOUND OTHER				QUOTE #: _____ PO#: _____										STATE PROGRAM (if any): <input checked="" type="checkbox"/> TU	E-mail? <input checked="" type="checkbox"/> Y/N; Fax? <input checked="" type="checkbox"/> Y/B	
																		DATA PACKAGE: I <input checked="" type="checkbox"/> II <input type="checkbox"/> III <input type="checkbox"/> IV		

SAMPLES RECEIVED AFTER 3PM OR ON SATURDAY ARE CONSIDERED RECEIVED THE NEXT BUSINESS DAY. IF TURNAROUND TIME IS NOT INDICATED, AES WILL PROCEED WITH STANDARD TAT OF SAMPLES.
SAMPLES ARE DISPOSED 30 DAYS AFTER REPORT COMPLETION UNLESS OTHER ARRANGEMENTS ARE MADE.

MATRIX CODES: A = Air GW = Groundwater SE = Sediment SO = Soil SW = Surface Water W = Water (Blanks) DW = Drinking Water (Blanks) O = Other (specify) WW = Waste Water

PRESERVATIVE CODES: H+I = Hydrochloric acid + ice I = Ice only N = Nitric acid S+I = Sulfuric acid + ice S/M+I = Sodium Bisulfate/Methanol + ice O = Other (specify) NA = None

White Copy - Original; Yellow Copy - Client

Client: Santeck Environmental Inc.
Project: Loudon County (Matlock Bend) Phase II/IV LF
Lab ID: 1705Q25

Case Narrative**Sample Receiving Nonconformance:**

The turn around time on the Chain of Custody was listed as a 2 day rush, however the TAT was changed to standard per Robert Hudson via email 05-26-17.

Micro-extractable VOC Analysis by Method 8011:

Matrix spike duplicate analyses were not performed with Batch 243325 due to insufficient sample volume.I

SAMPLE/COOLER RECEIPT CHECKLIST
[Clear](#)
[Save as](#)
1. Client Name: **Santek Environmental Inc.**AES Work Order Number: **1705Q25**2. Carrier: FedEx UPS USPS Client Courier Other _____

	Yes	No	N/A	Details	Comments
3. Shipping container/cooler received in good condition?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	damaged <input type="checkbox"/> leaking <input type="checkbox"/> other <input type="checkbox"/>	
4. Custody seals present on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
5. Custody seals intact on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
6. Temperature blanks present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
7. Cooler temperature(s) within limits of 0-6°C? [See item 13 and 14 for temperature recordings.]	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Cooling initiated for recently collected samples / ice present <input type="checkbox"/>	
8. Chain of Custody (COC) present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
9. Chain of Custody signed, dated, and timed when relinquished and received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
10. Sampler name and/or signature on COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
11. Were all samples received within holding time?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
12. TAT marked on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	If no TAT indicated, proceeded with standard TAT per Terms & Conditions. <input type="checkbox"/>	

13. Cooler 1 Temperature 3.0 °C Cooler 2 Temperature 1.8 °C Cooler 3 Temperature _____ °C Cooler 4 Temperature _____ °C

14. Cooler 5 Temperature _____ °C Cooler 6 Temperature _____ °C Cooler 7 Temperature _____ °C Cooler 8 Temperature _____ °C

15. Comments: _____

I certify that I have completed sections 1-15 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
16. Were sample containers intact upon receipt?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
17. Custody seals present on sample containers?	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>		
18. Custody seals intact on sample containers?	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>		
19. Do sample container labels match the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	incomplete info <input type="checkbox"/> illegible <input type="checkbox"/> no label <input type="checkbox"/> other <input type="checkbox"/>	
20. Are analyses requested indicated on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
21. Were all of the samples listed on the COC received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	samples received but not listed on COC <input type="checkbox"/> samples listed on COC not received <input type="checkbox"/>	
22. Was the sample collection date/time noted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
23. Did we receive sufficient sample volume for indicated analyses?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
24. Were samples received in appropriate containers?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
25. Were VOA samples received without headspace (< 1/4" bubble)?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
26. Were trip blanks submitted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	listed on COC <input checked="" type="checkbox"/> not listed on COC <input type="checkbox"/>	

27. Comments: _____

I certify that I have completed sections 16-27 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
28. Have containers needing chemical preservation been checked?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
29. Containers meet preservation guidelines?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
30. Was pH adjusted?	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE

I certify that I have completed sections 28-30 (dated initials).

AJ 5/26/17

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.	Client Sample ID: MW-01
Project Name: Loudon County (Matlock Bend) Landfill Phase 1	Collection Date: 5/25/2017 11:26:00 AM
Lab ID: 1705Q20-001	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	20.0		mg/L	R344664	20	05/31/2017 14:00	JM
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	270	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1					(E350.1)			
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 13:45	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.200		ug/L	243324	1	05/31/2017 12:42	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 12:42	AW
Surr: 4-Bromofluorobenzene	103	69.4-134	%REC		243324	1	05/31/2017 12:42	AW
Inorganic Anions by IC E300.0								
Chloride	20.1	1.00		mg/L	R344266	1	05/26/2017 19:25	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 19:25	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 19:25	JM
Sulfate	3.44	1.00		mg/L	R344266	1	05/26/2017 19:25	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	BRL	0.0100		mg/L	243633	1	06/05/2017 22:48	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 02:16	AR
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 02:16	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 02:16	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 02:16	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	MW-01
Project Name:	Loudon County (Matlock Bend) Landfill Phase I	Collection Date:	5/25/2017 11:26:00 AM
Lab ID:	1705Q20-001	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 02:16	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 02:16	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 02:16	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 02:16	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 02:16	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 02:16	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 02:16	AR
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 02:16	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 02:16	AR
Surr: 4-Bromofluorobenzene	89	66.1-129	%REC		243483	1	06/01/2017 02:16	AR
Surr: Dibromofluoromethane	92.2	83.6-123	%REC		243483	1	06/01/2017 02:16	AR
Surr: Toluene-d8	95.6	81.8-118	%REC		243483	1	06/01/2017 02:16	AR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

E Estimated (value above quantitation range)
S Spike Recovery outside limits due to matrix
Narr See case narrative
NC Not confirmed
< Less than Result value
J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.	Client Sample ID: MW-01
Project Name: Loudon County (Matlock Bend) Landfill Phase I	Collection Date: 5/26/2017 7:40:00 AM
Lab ID: 1705Q20-002	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Metals by ICP/MS SW6020B								
Calcium	47.2	0.100		mg/L	243302	1	06/08/2017 16:20	JR
Iron	0.273	0.100		mg/L	243302	1	06/08/2017 16:20	JR
Magnesium	28.5	0.100		mg/L	243302	1	06/08/2017 16:20	JR
Potassium	2.54	0.500		mg/L	243302	1	06/08/2017 16:20	JR
Sodium	9.40	0.500		mg/L	243302	1	06/08/2017 16:20	JR
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243660	1	06/06/2017 19:52	AS
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 00:48	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 19:34	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 00:48	JR
Beryllium	BRL	0.00100		mg/L	243302	1	06/02/2017 00:48	JR
Cadmium	BRL	0.00125		mg/L	243302	1	06/02/2017 00:48	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 00:48	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 00:48	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 01:46	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 00:48	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 00:48	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 00:48	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 00:48	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 00:48	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 00:48	JR
Zinc	BRL	0.0100		mg/L	243302	1	06/02/2017 00:48	JR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	MW-1A
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 10:32:00 AM
Lab ID:	1705Q20-003	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	20.0		mg/L	R344664	20	05/31/2017 14:56	JM
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	505	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1				(E350.1)				
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 13:47	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.196		ug/L	243324	1	05/31/2017 17:27	AW
1,2-Dibromoethane	BRL	0.049		ug/L	243324	1	05/31/2017 17:27	AW
Surr: 4-Bromofluorobenzene	97.7	69.4-134		%REC	243324	1	05/31/2017 17:27	AW
Inorganic Anions by IC E300.0								
Chloride	128	10.0		mg/L	R344266	10	05/26/2017 19:55	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 19:40	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 19:40	JM
Sulfate	36.2	1.00		mg/L	R344266	1	05/26/2017 19:40	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	BRL	0.0100		mg/L	243633	1	06/05/2017 22:55	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 02:43	AR
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 02:43	AR
1,2,3-Trichloropropene	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 02:43	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
1,2-Dichloropropene	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
1,4-Dichlorobenzene	BRL	.75		ug/L	243483	1	06/01/2017 02:43	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR

Qualifiers: * Value exceeds maximum contaminant level!

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	MW-1A
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 10:32:00 AM
Lab ID:	1705Q20-003	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B		(SW5030B)						
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 02:43	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 02:43	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 02:43	AR
Tetraehloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 02:43	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 02:43	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 02:43	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 02:43	AR
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 02:43	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 02:43	AR
Surr: 4-Bromofluorobenzene	88.6	66.1-129	%REC		243483	1	06/01/2017 02:43	AR
Surr: Dibromofluoromethane	96	83.6-123	%REC		243483	1	06/01/2017 02:43	AR
Surr: Toluene-d8	97.4	81.8-118	%REC		243483	1	06/01/2017 02:43	AR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	MW-1A
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/26/2017 7:48:00 AM
Lab ID:	1705Q20-004	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Metals by ICP/MS SW6020B								
Calcium	76.6	0.500		mg/L	243302	5	06/08/2017 16:57	JR
Iron	BRL	0.100		mg/L	243302	1	06/08/2017 16:26	JR
Magnesium	28.4	0.100		mg/L	243302	1	06/08/2017 16:26	JR
Potassium	15.3	0.500		mg/L	243302	1	06/08/2017 16:26	JR
Sodium	46.6	0.500		mg/L	243302	1	06/08/2017 16:26	JR
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243660	1	06/06/2017 20:02	AS
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 00:55	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 19:59	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 00:55	JR
Beryllium	BRL	0.00100		mg/L	243302	1	06/02/2017 00:55	JR
Cadmium	BRL	0.00125		mg/L	243302	1	06/02/2017 00:55	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 00:55	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 00:55	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 01:50	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 00:55	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 00:55	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 00:55	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 00:55	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 00:55	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 00:55	JR
Zinc	BRL	0.0100		mg/L	243302	1	06/02/2017 00:55	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
BRL	Below reporting limit	S Spike Recovery outside limits due to matrix
H	Holding times for preparation or analysis exceeded	Narr Sea case narrative
N	Analyte not NELAC certified	NC Not confirmed
B	Analyte detected in the associated method blank	< Less than Result value
>	Greater than Result value	J Estimated value detected below Reporting Limit

Client: Santek Environmental Inc.	Client Sample ID: DUPLICATE
Project Name: Loudon County (Matlock Bend) Landfill Phase 1	Collection Date: 5/25/2017 5:00:00 PM
Lab ID: 1705Q20-007	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	20.0		mg/L	R344664	20	05/31/2017 15:51	JM
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	487	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1				(E350.1)				
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 13:56	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.200		ug/L	243324	1	05/31/2017 18:52	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 18:52	AW
Surr: 4-Bromofluorobenzene	104	69.4-134		%REC	243324	1	05/31/2017 18:52	AW
Inorganic Anions by IC E300.0								
Chloride	126	10.0		mg/L	R344266	10	05/30/2017 15:49	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 20:39	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 20:39	JM
Sulfate	35.3	1.00		mg/L	R344266	1	05/26/2017 20:39	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	BRL	0.0100		mg/L	243633	1	06/05/2017 23:33	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 04:04	AR
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 04:04	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 04:04	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 04:04	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

E Estimated (value above quantitation range)
S Spike Recovery outside limits due to matrix
Narr See case narrative
NC Not confirmed
< Less than Result value
J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	DUPLICATE
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 5:00:00 PM
Lab ID:	1705Q20-007	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B		(SW5030B)						
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 04:04	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 04:04	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 04:04	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 04:04	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 04:04	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:04	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 04:04	AR
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 04:04	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 04:04	AR
Surr: 4-Bromofluorobenzene	88.1	66.1-129	%REC		243483	1	06/01/2017 04:04	AR
Surr: Dibromofluoromethane	92.8	83.6-123	%REC		243483	1	06/01/2017 04:04	AR
Surr: Toluene-d8	96.6	81.8-118	%REC		243483	1	06/01/2017 04:04	AR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

- E Estimated (value above quantitation range)
- S Spike Recovery outside limits due to matrix
- Narr See case narrative
- NC Not confirmed
- < Less than Result value
- J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	DUPLICATE
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/26/2017 5:00:00 PM
Lab ID:	1705Q20-008	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Metals by ICP/MS SW6020B								
Calcium	85.9	0.500		mg/L	243302	5	06/08/2017 17:04	JR
Iron	BRL	0.100		mg/L	243302	1	06/08/2017 16:39	JR
Magnesium	28.8	0.100		mg/L	243302	1	06/08/2017 16:39	JR
Potassium	15.9	0.500		mg/L	243302	1	06/08/2017 16:39	JR
Sodium	47.6	0.500		mg/L	243302	1	06/08/2017 16:39	JR
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243360	1	06/06/2017 20:12	AS
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 01:07	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 20:12	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 01:07	JR
Beryllium	BRL	0.00100		mg/L	243302	1	06/02/2017 01:07	JR
Cadmium	BRL	0.00125		mg/L	243302	1	06/02/2017 01:07	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 01:07	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 01:07	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 01:57	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 01:07	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 01:07	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 01:07	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 01:07	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 01:07	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 01:07	JR
Zinc	BRL	0.0100		mg/L	243302	1	06/02/2017 01:07	JR

Qualifiers:	*	Value exceeds maximum contaminant level	E	Estimated (value above quantitation range)
	BRL	Below reporting limit	S	Spike Recovery outside limits due to matrix
	H	Holding times for preparation or analysis exceeded	Narr	See case narrative
	N	Analyte not NELAC certified	NC	Not confirmed
	B	Analyte detected in the associated method blank	<	Less than Result value
	>	Greater than Result value	J	Estimated value detected below Reporting Limit

Client: Santek Environmental Inc.	Client Sample ID: MW-02
Project Name: Loudon County (Matlock Bend) Landfill Phase I	Collection Date: 5/25/2017 11:59:00 AM
Lab ID: 1705Q20-005	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	10.0		mg/L	R344664	10	05/31/2017 15:14	JM
Total Metals by ICP/MS SW6020B								
Calcium	1.92	0.100		mg/L	243302	1	06/08/2017 16:32	JR
Iron	0.265	0.100		mg/L	243302	1	06/08/2017 16:32	JR
Magnesium	1.36	0.100		mg/L	243302	1	06/08/2017 16:32	JR
Potassium	2.43	0.500		mg/L	243302	1	06/08/2017 16:32	JR
Sodium	2.15	0.500		mg/L	243302	1	06/08/2017 16:32	JR
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	63	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1								
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 13:49	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.199		ug/L	243324	1	05/31/2017 17:55	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 17:55	AW
Surr: 4-Bromofluorobenzene	101	69.4-134	%REC	243324	1	05/31/2017 17:55	AW	
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243660	1	06/06/2017 20:05	AS
Inorganic Anions by IC E300.0								
Chloride	2.58	1.00		mg/L	R344266	1	05/26/2017 20:09	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 20:09	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 20:09	JM
Sulfate	BRL	1.00		mg/L	R344266	1	05/26/2017 20:09	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	0.0989	0.0100		mg/L	243633	1	06/05/2017 23:20	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	17.2	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 03:10	AR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	MW-02
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 11:59:00 AM
Lab ID:	1705Q20-005	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 03:10	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 03:10	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 03:10	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Carhon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 03:10	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 03:10	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 03:10	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 03:10	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 03:10	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 03:10	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 03:10	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client: Santek Environmental Inc.	Client Sample ID: MW-02
Project Name: Loudon County (Matlock Bend) Landfill Phase 1	Collection Date: 5/25/2017 11:59:00 AM
Lab ID: 1705Q20-005	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 03:10	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 03:10	AR
Surr: 4-Bromofluorobenzene	87.9	66.1-129	%REC		243483	1	06/01/2017 03:10	AR
Surr: Dibromofluoromethane	94.8	83.6-123	%REC		243483	1	06/01/2017 03:10	AR
Surr: Toluene-d8	97.2	81.8-118	%REC		243483	1	06/01/2017 03:10	AR
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 01:01	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 20:05	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 01:01	JR
Beryllium	0.00170	0.00100		mg/L	243302	1	06/02/2017 01:01	JR
Cadmium	0.00145	0.00125		mg/L	243302	1	06/02/2017 01:01	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 01:01	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 01:01	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 01:53	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 01:01	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 01:01	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 01:01	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 01:01	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 01:01	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 01:01	JR
Zinc	0.0406	0.0100		mg/L	243302	1	06/02/2017 01:01	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
BRL	Below reporting limit	S Spike Recovery outside limits due to matrix
H	Holding times for preparation or analysis exceeded	Narr See case narrative
N	Analyte not NELAC certified	NC Not confirmed
B	Analyte detected in the associated method blank	< Less than Result value
>	Greater than Result value	J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	MW-03
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 10:59:00 AM
Lab ID:	1705Q20-006	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	20.0		mg/L	R344664	20	05/31/2017 15:33	JM
Total Metals by ICP/MS SW6020B								
Calcium	12.3	0.100		mg/L	243390	1	06/08/2017 13:57	JR
Iron	0.139	0.100		mg/L	243390	1	06/08/2017 13:57	JR
Magnesium	4.29	0.100		mg/L	243390	1	06/08/2017 13:57	JR
Potassium	5.07	0.500		mg/L	243390	1	06/08/2017 13:57	JR
Sodium	42.3	0.500		mg/L	243390	1	06/08/2017 13:57	JR
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	155	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1								
Nitrogen, Ammonia (As N)	4.57	0.200		mg/L	243542	1	06/02/2017 13:54	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.199		ug/L	243324	1	05/31/2017 18:23	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 18:23	AW
Surr: 4-Bromofluorobenzene	99.9	69.4-134	%REC	243324	1	05/31/2017 18:23	AW	
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243660	1	06/06/2017 20:08	AS
Inorganic Anions by IC E300.0								
Chloride	44.6	1.00		mg/L	R344266	1	05/26/2017 20:24	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 20:24	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 20:24	JM
Sulfate	26.7	1.00		mg/L	R344266	1	05/26/2017 20:24	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	1.69	0.0100		mg/L	243633	1	06/05/2017 23:26	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 03:37	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santeck Environmental Inc.	Client Sample ID: MW-03
Project Name: Loudon County (Matlock Bend) Landfill Phase 1	Collection Date: 5/25/2017 10:59:00 AM
Lab ID: 1705Q20-006	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 03:37	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 03:37	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 03:37	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Bromonethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 03:37	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 03:37	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 03:37	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 03:37	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 03:37	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 03:37	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 03:37	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client: Santeck Environmental Inc.	Client Sample ID: MW-03
Project Name: Loudon County (Matlock Bend) Landfill Phase 1	Collection Date: 5/25/2017 10:59:00 AM
Lab ID: 1705Q20-006	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 03:37	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 03:37	AR
Sur: 4-Bromofluorobenzene	89.1	66.1-129		%REC	243483	1	06/01/2017 03:37	AR
Sur: Dibromofluoromethane	94.6	83.6-123		%REC	243483	1	06/01/2017 03:37	AR
Sur: Toluene-d8	98.2	81.8-118		%REC	243483	1	06/01/2017 03:37	AR
APPENDIX I METALS SW6020B (SW3005A)								
Antimony	BRL	0.00150		mg/L	243390	1	06/02/2017 02:59	JR
Arsenie	BRL	0.00250		mg/L	243390	1	06/02/2017 02:59	JR
Barium	BRL	0.500		mg/L	243390	1	06/02/2017 02:59	JR
Beryllium	BRL	0.00100		mg/L	243390	1	06/02/2017 02:59	JR
Cadmium	BRL	0.00125		mg/L	243390	1	06/02/2017 02:59	JR
Chromium	BRL	0.0250		mg/L	243390	1	06/02/2017 02:59	JR
Cobalt	0.0110	0.00500		mg/L	243390	1	06/02/2017 02:59	JR
Copper	BRL	0.00500		mg/L	243390	1	06/02/2017 02:59	JR
Lead	BRL	0.00375		mg/L	243390	1	06/02/2017 02:59	JR
Nickel	BRL	0.0250		mg/L	243390	1	06/02/2017 02:59	JR
Selenium	BRL	0.0100		mg/L	243390	1	06/02/2017 02:59	JR
Silver	BRL	0.00250		mg/L	243390	1	06/02/2017 02:59	JR
Thallium	0.000737	0.000500		mg/L	243390	1	06/02/2017 02:59	JR
Vanadium	BRL	0.00500		mg/L	243390	1	06/02/2017 02:59	JR
Zinc	BRL	0.0100		mg/L	243390	1	06/02/2017 02:59	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
BRL	Below reporting limit	S Spike Recovery outside limits due to matrix
H	Holding times for preparation or analysis exceeded	Narr See case narrative
N	Analyte not NELAC certified	NC Not confirmed
B	Analyte detected in the associated method blank	< Less than Result value
>	Greater than Result value	J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	MW-4R
Project Name:	Loudon County (Matiock Bend) Phase II/IV LF	Collection Date:	5/25/2017 1:05:00 PM
Lab ID:	1705Q25-002	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011 (SW8011)								
1,2-Dibromo-3-chloropropane	BRL	0.203		ug/L	243325	1	06/01/2017 02:28	AW
1,2-Dibromoethane	BRL	0.051		ug/L	243325	1	06/01/2017 02:28	AW
Surr: 4-Bromofluorobenzene	92.9	69.4-134		%REC	243325	1	06/01/2017 02:28	AW
Inorganic Anions by IC E300.0								
Fluoride	BRL	4.00		mg/L	R344522	1	06/01/2017 19:02	JM
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 05:25	AR
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 05:25	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 05:25	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 05:25	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 05:25	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 05:25	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santeck Environmental Inc.	Client Sample ID: MW-4R
Project Name: Loudon County (Matlock Bend) Phase II/IV LF	Collection Date: 5/25/2017 1:05:00 PM
Lab ID: 1705Q25-002	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
Methylene echloride	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 05:25	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 05:25	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 05:25	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 05:25	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 05:25	AR
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 05:25	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 05:25	AR
Surr: 4-Bromofluorobenzene	87	66.1-129	%REC		243483	1	06/01/2017 05:25	AR
Surr: Dibromofluoromethane	94.5	83.6-123	%REC		243483	1	06/01/2017 05:25	AR
Surr: Toluene-d8	98.4	81.8-118	%REC		243483	1	06/01/2017 05:25	AR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

- E Estimated (value above quantitation range)
- S Spike Recovery outside limits due to matrix
- Narr See case narrative
- NC Not confirmed
- < Less than Result value
- J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.	Client Sample ID: MW-4R
Project Name: Loudon County (Matlock Bend) Phase II/IV LF	Collection Date: 5/26/2017 7:40:00 AM
Lab ID: 1705Q25-003	Matrix: Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Mercury, Total	SW7470A	(SW7470A)						
Mercury	BRL	0.00200		mg/L	243660	1	06/07/2017 09:53	AS
APPENDIX I METALS	SW6020B	(SW3005A)						
Antimony	BRL	0.00150		mg/L	243390	1	06/02/2017 04:19	JR
Arsenic	BRL	0.00250		mg/L	243390	1	06/05/2017 19:10	JR
Barium	BRL	0.500		mg/L	243390	1	06/02/2017 04:19	JR
Beryllium	BRL	0.00100		mg/L	243390	1	06/02/2017 04:19	JR
Cadmium	BRL	0.00125		mg/L	243390	1	06/02/2017 04:19	JR
Chromium	BRL	0.0250		mg/L	243390	1	06/02/2017 04:19	JR
Cobalt	0.0115	0.00500		mg/L	243390	1	06/05/2017 19:10	JR
Copper	0.00503	0.00500		mg/L	243390	1	06/05/2017 19:10	JR
Lead	BRL	0.00375		mg/L	243390	1	06/02/2017 04:19	JR
Nickel	BRL	0.0250		mg/L	243390	1	06/05/2017 19:10	JR
Selenium	BRL	0.0100		mg/L	243390	1	06/02/2017 04:19	JR
Silver	BRL	0.00250		mg/L	243390	1	06/02/2017 04:19	JR
Thallium	BRL	0.000500		mg/L	243390	1	06/02/2017 04:19	JR
Vanadium	BRL	0.00500		mg/L	243390	1	06/02/2017 04:19	JR
Zinc	0.0309	0.0100		mg/L	243390	1	06/08/2017 17:29	JR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

- E Estimated (value above quantitation range)
- S Spike Recovery outside limits due to matrix
- Narr See case narrative
- NC Not confirmed
- < Less than Result value
- J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	MW-05
Project Name:	Loudon County (Matlock Bend) Phase II/IV LF	Collection Date:	5/25/2017 2:10:00 PM
Lab ID:	1705Q25-004	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011 (SW8011)								
1,2-Dibromo-3-chloropropane	BRL	0.201	S	ug/L	243325	1	05/31/2017 16:30	AW
1,2-Dibromoethane	BRL	0.050	S	ug/L	243325	1	05/31/2017 16:30	AW
Surr: 4-Bromofluorobenzene	101	69.4-134	%REC		243325	1	05/31/2017 16:30	AW
Mercury, Total SW7470A					(SW7470A)			
Mercury	BRL	0.00200		mg/L	243660	1	06/07/2017 09:56	AS
Inorganic Anions by IC E300.0								
Fluoride	BRL	4.00		mg/L	R344522	1	06/01/2017 19:17	JM
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 05:52	AR
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 05:52	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 05:52	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 05:52	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
Bromo(chloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 05:52	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

D Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	MW-05
Project Name:	Loudon County (Matlock Bend) Phase II/IV LF	Collection Date:	5/25/2017 2:10:00 PM
Lab ID:	1705Q25-004	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
----------	--------	-----------------	------	-------	---------	-----------------	---------------	---------

APPENDIX I VOLATILE ORGANICS SW8260B		(SW5030B)						
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 05:52	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 05:52	AR
Tetrachloroethylene	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 05:52	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 05:52	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 05:52	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 05:52	AR
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 05:52	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 05:52	AR
Surr: 4-Bromofluorobenzene	88.4	66.1-129	%REC		243483	1	06/01/2017 05:52	AR
Surr: Dibromofluoromethane	95.8	83.6-123	%REC		243483	1	06/01/2017 05:52	AR
Surr: Toluene-d8	97.5	81.8-118	%REC		243483	1	06/01/2017 05:52	AR

APPENDIX I METALS SW6020B		(SW3005A)						
Antimony	BRL	0.00150		mg/L	243390	1	06/02/2017 04:26	JR
Arsenic	BRL	0.00250		mg/L	243390	1	06/05/2017 19:16	JR
Barium	BRL	0.500		mg/L	243390	1	06/02/2017 04:26	JR
Beryllium	BRL	0.00100		mg/L	243390	1	06/02/2017 04:26	JR
Cadmium	BRL	0.00125		mg/L	243390	1	06/02/2017 04:26	JR
Chromium	BRL	0.0250		mg/L	243390	1	06/02/2017 04:26	JR
Cobalt	BRL	0.00500		mg/L	243390	1	06/05/2017 19:16	JR
Copper	BRL	0.00500		mg/L	243390	1	06/05/2017 19:16	JR
Lead	BRL	0.00375		mg/L	243390	1	06/02/2017 04:26	JR
Nickel	BRL	0.0250		mg/L	243390	1	06/05/2017 19:16	JR
Selenium	BRL	0.0100		mg/L	243390	1	06/02/2017 04:26	JR
Silver	BRL	0.00250		mg/L	243390	1	06/02/2017 04:26	JR
Thallium	BRL	0.000500		mg/L	243390	1	06/02/2017 04:26	JR
Vanadium	BRL	0.00500		mg/L	243390	1	06/02/2017 04:26	JR
Zinc	0.0104	0.0100		mg/L	243390	1	06/08/2017 17:35	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
	BRL Below reporting limit	S Spike Recovery outside limits due to matrix
	H Holding times for preparation or analysis exceeded	Narr See case narrative
	N Analyte not NELAC certified	NC Not confirmed
	B Analyte detected in the associated method blank	< Less than Result value
	> Greater than Result value	J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	EQUIPMENT BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase I	Collection Date:	5/25/2017 2:25:00 PM
Lab ID:	1705Q20-009	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	1.43	1.00		mg/L	R344664	1	05/31/2017 02:03	JM
Total Metals by ICP/MS SW6020B								
Calcium	BRL	0.100		mg/L	243302	1	06/08/2017 16:45	JR
Iron	BRL	0.100		mg/L	243302	1	06/08/2017 16:45	JR
Magnesium	BRL	0.100		mg/L	243302	1	06/08/2017 16:45	JR
Potassium	BRL	0.500		mg/L	243302	1	06/08/2017 16:45	JR
Sodium	BRL	0.500		mg/L	243302	1	06/08/2017 16:45	JR
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	14	1		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1								
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 13:58	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.201		ug/L	243324	1	05/31/2017 19:20	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 19:20	AW
Surrogate: 4-Bromofluorobenzene	107	69.4-134	%REC	243324	1	05/31/2017 19:20	AW	
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243457	1	06/07/2017 10:00	AS
Inorganic Anions by IC E300.0								
Chloride	1.28	1.00		mg/L	R344266	1	05/26/2017 20:53	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 20:53	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 20:53	JM
Sulfate	BRL	1.00		mg/L	R344266	1	05/26/2017 20:53	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	BRL	0.0100		mg/L	243633	1	06/05/2017 23:39	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 04:31	AR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	EQUIPMENT BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 2:25:00 PM
Lab ID:	1705Q20-009	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 04:31	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 04:31	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 04:31	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 04:31	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 04:31	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 04:31	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 04:31	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 04:31	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:31	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 04:31	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	EQUIPMENT BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 2:25:00 PM
Lab ID:	1705Q20-009	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 04:31	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 04:31	AR
Surr: 4-Bromofluorobenzene	88.1	66.1-129	%REC		243483	1	06/01/2017 04:31	AR
Surr: Dibromofluoromethane	93.4	83.6-123	%REC		243483	1	06/01/2017 04:31	AR
Surr: Toluene-d8	97.3	81.8-118	%REC		243483	1	06/01/2017 04:31	AR
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 01:13	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 20:18	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 01:13	JR
Beryllium	BRL	0.00100		mg/L	243302	1	06/02/2017 01:13	JR
Cadmium	BRL	0.00125		mg/L	243302	1	06/02/2017 01:13	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 01:13	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 01:13	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 02:00	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 01:13	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 01:13	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 01:13	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 01:13	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 01:13	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 01:13	JR
Zinc	BRL	0.0100		mg/L	243302	1	06/02/2017 01:13	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
BRL	Below reporting limit	S Spike Recovery outside limits due to matrix
H	Holding times for preparation or analysis exceeded	Narr See case narrative
N	Analyte not NELAC certified	NC Not confirmed
B	Analyte detected in the associated method blank	< Less than Result value
>	Greater than Result value	J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	TRIP BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 9:00:00 AM
Lab ID:	1705Q20-010	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	BRL	1.00		mg/L	R344664	1	05/31/2017 02:21	JM
Total Metals by ICP/MS SW6020B								
Calcium	BRL	0.100		mg/L	243302	1	06/08/2017 16:51	JR
Iron	BRL	0.100		mg/L	243302	1	06/08/2017 16:51	JR
Magnesium	BRL	0.100		mg/L	243302	1	06/08/2017 16:51	JR
Potassium	BRL	0.500		mg/L	243302	1	06/08/2017 16:51	JR
Sodium	BRL	0.500		mg/L	243302	1	06/08/2017 16:51	JR
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	5	1	H	mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1								
Nitrogen, Ammonia (As N)	BRL	0.200		mg/L	243542	1	06/02/2017 14:03	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.200		ug/L	243324	1	05/31/2017 19:48	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243324	1	05/31/2017 19:48	AW
Surr: 4-Bromofluorobenzene	103	69.4-134	%REC	243324	1	05/31/2017 19:48	AW	
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243457	1	06/07/2017 10:03	AS
Inorganic Anions by IC E300.0								
Chloride	BRL	1.00		mg/L	R344266	1	05/26/2017 21:08	JM
Fluoride	BRL	4.00		mg/L	R344266	1	05/26/2017 21:08	JM
Nitrogen, Nitrate (As N)	BRL	10.0		mg/L	R344266	1	05/26/2017 21:08	JM
Sulfate	BRL	1.00		mg/L	R344266	1	05/26/2017 21:08	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	BRL	0.0100		mg/L	243633	1	06/06/2017 19:23	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	BRL	10.0		mg/L	R344553	1	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243483	1	06/01/2017 04:57	AR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	TRIP BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 9:00:00 AM
Lab ID:	1705Q20-010	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B (SW5030B)								
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
1,1-Dichloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243483	1	06/01/2017 04:57	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243483	1	06/01/2017 04:57	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243483	1	06/01/2017 04:57	AR
2-Butanone	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
2-Hexanone	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Acetone	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Acrylonitrile	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Benzene	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
Bromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Bromodichloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Bromoform	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Bromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Carbon disulfide	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Carbon tetrachloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
Chlorobenzene	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Chloroethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Chloroform	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Chloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243483	1	06/01/2017 04:57	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Dibromochloromethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Dibromomethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Ethylbenzene	BRL	700		ug/L	243483	1	06/01/2017 04:57	AR
Iodomethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Methylene chloride	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
Styrene	BRL	100		ug/L	243483	1	06/01/2017 04:57	AR
Tetrachloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
Toluene	BRL	1000		ug/L	243483	1	06/01/2017 04:57	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243483	1	06/01/2017 04:57	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Trichloroethene	BRL	5.0		ug/L	243483	1	06/01/2017 04:57	AR
Trichlorofluoromethane	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR
Vinyl acetate	BRL	10		ug/L	243483	1	06/01/2017 04:57	AR

Qualifiers:

- * Value exceeds maximum contaminant level
- BRL Below reporting limit
- H Holding times for preparation or analysis exceeded
- N Analyte not NELAC certified
- B Analyte detected in the associated method blank
- > Greater than Result value

- E Estimated (value above quantitation range)
- S Spike Recovery outside limits due to matrix
- Narr See case narrative
- NC Not confirmed
- < Less than Result value
- J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	TRIP BLANK
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1	Collection Date:	5/25/2017 9:00:00 AM
Lab ID:	1705Q20-010	Matrix:	Aqueous

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
Vinyl chloride	BRL	2.0		ug/L	243483	1	06/01/2017 04:57	AR
Xylenes, Total	BRL	10000		ug/L	243483	1	06/01/2017 04:57	AR
Surr: 4-Bromofluorobenzene	88	66.1-129	%REC		243483	1	06/01/2017 04:57	AR
Surr: Dibromofluoromethane	92.4	83.6-123	%REC		243483	1	06/01/2017 04:57	AR
Surr: Toluene-d8	97.4	81.8-118	%REC		243483	1	06/01/2017 04:57	AR
APPENDIX I METALS SW6020B								
Antimony	BRL	0.00150		mg/L	243302	1	06/02/2017 01:38	JR
Arsenic	BRL	0.00250		mg/L	243302	1	06/05/2017 20:24	JR
Barium	BRL	0.500		mg/L	243302	1	06/02/2017 01:38	JR
Beryllium	BRL	0.00100		mg/L	243302	1	06/02/2017 01:38	JR
Cadmium	BRL	0.00125		mg/L	243302	1	06/02/2017 01:38	JR
Chromium	BRL	0.0250		mg/L	243302	1	06/02/2017 01:38	JR
Cobalt	BRL	0.00500		mg/L	243302	1	06/02/2017 01:38	JR
Copper	BRL	0.00500		mg/L	243302	1	06/02/2017 02:11	JR
Lead	BRL	0.00375		mg/L	243302	1	06/02/2017 01:38	JR
Nickel	BRL	0.0250		mg/L	243302	1	06/02/2017 01:38	JR
Selenium	BRL	0.0100		mg/L	243302	1	06/02/2017 01:38	JR
Silver	BRL	0.00250		mg/L	243302	1	06/02/2017 01:38	JR
Thallium	BRL	0.000500		mg/L	243302	1	06/02/2017 01:38	JR
Vanadium	BRL	0.00500		mg/L	243302	1	06/02/2017 01:38	JR
Zinc	BRL	0.0100		mg/L	243302	1	06/02/2017 01:38	JR

Qualifiers: * Value exceeds maximum contaminant level
 BRL Below reporting limit
 H Holding times for preparation or analysis exceeded
 N Analyte not NELAC certified
 B Analyte detected in the associated method blank
 > Greater than Result value

E Estimated (value above quantitation range)
 S Spike Recovery outside limits due to matrix
 Narr See case narrative
 NC Not confirmed
 < Less than Result value
 J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.						Dates Report
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1						
Lab Order:	1705Q20						

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q20-001A	MW-01	5/25/2017 11:26:00AM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00PM	06/01/2017	
1705Q20-001B	MW-01	5/25/2017 11:26:00AM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00PM	05/31/2017	
1705Q20-001C	MW-01	5/25/2017 11:26:00AM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017 6:03:00PM	06/05/2017	
1705Q20-001D	MW-01	5/25/2017 11:26:00AM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-001E	MW-01	5/25/2017 11:26:00AM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017 11:40:00AM	06/01/2017	
1705Q20-001F	MW-01	5/25/2017 11:26:00AM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q20-001G	MW-01	5/25/2017 11:26:00AM	Groundwater	Cyanide	6/1/2017 9:00:00AM	06/01/2017	
1705Q20-001H	MW-01	5/25/2017 11:26:00AM	Groundwater	Nitrogen, Ammonia (as N)	6/2/2017 11:45:00AM	06/02/2017	
1705Q20-001H	MW-01	5/25/2017 11:26:00AM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-002A	MW-01	5/26/2017 7:40:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM	06/02/2017	
1705Q20-002A	MW-01	5/26/2017 7:40:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM	06/05/2017	
1705Q20-002A	MW-01	5/26/2017 7:40:00AM	Groundwater	Total Metals by ICP/MS	5/30/2017 5:37:00PM	06/08/2017	
1705Q20-002A	MW-01	5/26/2017 7:40:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00PM	06/06/2017	
1705Q20-003A	MW-1A	5/25/2017 10:32:00AM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00PM	06/01/2017	
1705Q20-003B	MW-1A	5/25/2017 10:32:00AM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00PM	05/31/2017	
1705Q20-003C	MW-1A	5/25/2017 10:32:00AM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017 6:03:00PM	06/05/2017	
1705Q20-003D	MW-1A	5/25/2017 10:32:00AM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-003E	MW-1A	5/25/2017 10:32:00AM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017 11:40:00AM	06/01/2017	
1705Q20-003F	MW-1A	5/25/2017 10:32:00AM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q20-003G	MW-1A	5/25/2017 10:32:00AM	Groundwater	Cyanide	6/1/2017 9:00:00AM	06/01/2017	
1705Q20-003H	MW-1A	5/25/2017 10:32:00AM	Groundwater	Nitrogen, Ammonia (as N)	6/2/2017 11:45:00AM	06/02/2017	
1705Q20-003H	MW-1A	5/25/2017 10:32:00AM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-004A	MW-1A	5/26/2017 7:48:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM	06/02/2017	
1705Q20-004A	MW-1A	5/26/2017 7:48:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM	06/05/2017	
1705Q20-004A	MW-1A	5/26/2017 7:48:00AM	Groundwater	Total Metals by ICP/MS	5/30/2017 5:37:00PM	06/08/2017	
1705Q20-004A	MW-1A	5/26/2017 7:48:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00PM	06/06/2017	
1705Q20-005A	MW-02	5/25/2017 11:59:00AM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00PM	06/01/2017	
1705Q20-005B	MW-02	5/25/2017 11:59:00AM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00PM	05/31/2017	
1705Q20-005C	MW-02	5/25/2017 11:59:00AM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017 6:03:00PM	06/05/2017	

Client:	Santek Environmental Inc.						Dates Report
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1						
Lab Order:	1705Q20						

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q20-005D	MW-02	5/25/2017 11:59:00AM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-005E	MW-02	5/25/2017 11:59:00AM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017 11:40:00AM		06/01/2017
1705Q20-005F	MW-02	5/25/2017 11:59:00AM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q20-005G	MW-02	5/25/2017 11:59:00AM	Groundwater	Cyanide	6/1/2017 9:00:00AM		06/01/2017
1705Q20-005H	MW-02	5/25/2017 11:59:00AM	Groundwater	Nitrogen, Ammonia (as N)	6/2/2017 11:45:00AM		06/02/2017
1705Q20-005H	MW-02	5/25/2017 11:59:00AM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-005I	MW-02	5/25/2017 11:59:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM		06/02/2017
1705Q20-005I	MW-02	5/25/2017 11:59:00AM	Groundwater	APPENDIX I METALS	5/30/2017 5:37:00PM		06/05/2017
1705Q20-005I	MW-02	5/25/2017 11:59:00AM	Groundwater	Total Metals by ICP/MS	5/30/2017 5:37:00PM		06/08/2017
1705Q20-005I	MW-02	5/25/2017 11:59:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00PM		06/06/2017
1705Q20-006A	MW-03	5/25/2017 10:59:00AM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00PM		06/01/2017
1705Q20-006B	MW-03	5/25/2017 10:59:00AM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00PM		05/31/2017
1705Q20-006C	MW-03	5/25/2017 10:59:00AM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017 6:03:00PM		06/05/2017
1705Q20-006D	MW-03	5/25/2017 10:59:00AM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-006E	MW-03	5/25/2017 10:59:00AM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017 11:40:00AM		06/01/2017
1705Q20-006F	MW-03	5/25/2017 10:59:00AM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q20-006G	MW-03	5/25/2017 10:59:00AM	Groundwater	Cyanide	6/1/2017 9:00:00AM		06/01/2017
1705Q20-006H	MW-03	5/25/2017 10:59:00AM	Groundwater	Nitrogen, Ammonia (as N)	6/2/2017 11:45:00AM		06/02/2017
1705Q20-006H	MW-03	5/25/2017 10:59:00AM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-006I	MW-03	5/25/2017 10:59:00AM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00AM		06/02/2017
1705Q20-006I	MW-03	5/25/2017 10:59:00AM	Groundwater	Total Metals by ICP/MS	5/31/2017 10:54:00AM		06/08/2017
1705Q20-006I	MW-03	5/25/2017 10:59:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00PM		06/06/2017
1705Q20-007A	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00PM		06/01/2017
1705Q20-007B	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00PM		05/31/2017
1705Q20-007C	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017 6:03:00PM		06/05/2017
1705Q20-007D	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-007E	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017 11:40:00AM		06/01/2017
1705Q20-007F	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q20-007F	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Inorganic Anions by IC			05/30/2017

Client:	Santek Environmental Inc.
Project Name:	Loudon County (Matlock Bend) Landfill Phase 1
Lab Order:	1705Q20

Dates Report

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q20-007G	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Cyanide	6/1/2017	9:00:00AM	06/01/2017
1705Q20-007H	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Nitrogen, Ammonia (as N)	6/2/2017	11:45:00AM	06/02/2017
1705Q20-007H	DUPLICATE	5/25/2017 5:00:00PM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-008A	DUPLICATE	5/26/2017 5:00:00PM	Groundwater	APPENDIX I METALS	5/30/2017	5:37:00PM	06/02/2017
1705Q20-008A	DUPLICATE	5/26/2017 5:00:00PM	Groundwater	APPENDIX I METALS	5/30/2017	5:37:00PM	06/05/2017
1705Q20-008A	DUPLICATE	5/26/2017 5:00:00PM	Groundwater	Total Metals by ICP/MS	5/30/2017	5:37:00PM	06/08/2017
1705Q20-008A	DUPLICATE	5/26/2017 5:00:00PM	Groundwater	TOTAL MERCURY	6/6/2017	12:43:00PM	06/06/2017
1705Q20-009A	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	APPENDIX I VOLATILE ORGANICS	5/31/2017	12:44:00PM	06/01/2017
1705Q20-009B	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	MICRO-EXTRACTABLE VOCs	5/30/2017	3:30:00PM	05/31/2017
1705Q20-009C	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Dissolved Metals by ICP/MS	6/5/2017	6:03:00PM	06/05/2017
1705Q20-009D	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-009E	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Residue, Dissolved (TDS) by SM2540C	6/1/2017	11:40:00AM	06/01/2017
1705Q20-009F	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Inorganic Anions by IC			05/26/2017
1705Q20-009G	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Cyanide	6/1/2017	9:00:00AM	06/01/2017
1705Q20-009H	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Nitrogen, Ammonia (as N)	6/2/2017	11:45:00AM	06/02/2017
1705Q20-009H	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Total Organic Carbon by SM5310B			05/31/2017
1705Q20-009I	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	APPENDIX I METALS	5/30/2017	5:37:00PM	06/02/2017
1705Q20-009I	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Total Metals by ICP/MS	5/30/2017	5:37:00PM	06/08/2017
1705Q20-009I	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	TOTAL MERCURY	6/1/2017	1:34:00PM	06/07/2017
1705Q20-010A	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I VOLATILE ORGANICS	5/31/2017	12:44:00PM	06/01/2017
1705Q20-010B	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	MICRO-EXTRACTABLE VOCs	5/30/2017	3:30:00PM	05/31/2017
1705Q20-010C	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Dissolved Metals by ICP/MS	6/5/2017	6:03:00PM	06/06/2017
1705Q20-010D	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Chemical Oxygen Demand (COD)			06/02/2017
1705Q20-010E	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Residue, Dissolved (TDS) by SM2540C	6/1/2017	11:40:00AM	06/01/2017
1705Q20-010F	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Inorganic Anions by IC			05/26/2017
1705Q20-010G	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Cyanide	6/1/2017	9:00:00AM	06/01/2017
1705Q20-010H	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Nitrogen, Ammonia (as N)	6/2/2017	11:45:00AM	06/02/2017
1705Q20-010H	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Total Organic Carbon by SM5310B			05/31/2017

Client: Santek Environmental Inc.
Project Name: Loudon County (Matlock Bend) Landfill Phase 1
Lab Order: 1705Q20

Dates Report

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q20-0101	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I METALS	5/30/2017	5:37:00PM	06/02/2017
1705Q20-0101	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I METALS	5/30/2017	5:37:00PM	06/05/2017
1705Q20-0101	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Total Metals by ICP/MS	5/30/2017	5:37:00PM	06/08/2017
1705Q20-0101	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	TOTAL MERCURY	6/1/2017	1:34:00PM	06/07/2017

pH Adjustment Sheet

AES Sample ID number	Test Requested	pH as Received	Required pH	Preservative Required	Lot # of Preservative	Amount Added mL or Pellets*	Final pH	Tech's Initials	Date	Time
1705QZ0-004A	Metals	4	1	HNO3	747-50	0.5 mL Pellets	1	AJ	5/26	7:05
-001H	TOC, NH3	6	1	H2SO4	705-47	1.0 mL Pellets	1	AJ	✓	✓
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					
					mL Pellets					

* Number of Pellets when adding NaOH

Client:	Santek Environmental Inc.	Dates Report
Project Name:	Loudon County (Matlock Bend) Phase II/IV LF	
Lab Order:	1705Q25	

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q25-001A	MW-03	5/25/2017 10:59:00AM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00 PM	06/01/2017	
1705Q25-001B	MW-03	5/25/2017 10:59:00AM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00 PM	05/31/2017	
1705Q25-001C	MW-03	5/25/2017 10:59:00AM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/02/2017	
1705Q25-001C	MW-03	5/25/2017 10:59:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00 PM	06/06/2017	
1705Q25-001D	MW-03	5/25/2017 10:59:00AM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q25-002A	MW-4R	5/25/2017 1:05:00PM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00 PM	06/01/2017	
1705Q25-002B	MW-4R	5/25/2017 1:05:00PM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00 PM	06/01/2017	
1705Q25-002C	MW-4R	5/25/2017 1:05:00PM	Groundwater	Inorganic Anions by IC			06/01/2017
1705Q25-003A	MW-4R	5/26/2017 7:40:00AM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/02/2017	
1705Q25-003A	MW-4R	5/26/2017 7:40:00AM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/05/2017	
1705Q25-003A	MW-4R	5/26/2017 7:40:00AM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/08/2017	
1705Q25-003A	MW-4R	5/26/2017 7:40:00AM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00 PM	06/07/2017	
1705Q25-004A	MW-05	5/25/2017 2:10:00PM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00 PM	06/01/2017	
1705Q25-004B	MW-05	5/25/2017 2:10:00PM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00 PM	05/31/2017	
1705Q25-004C	MW-05	5/25/2017 2:10:00PM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/02/2017	
1705Q25-004C	MW-05	5/25/2017 2:10:00PM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/05/2017	
1705Q25-004C	MW-05	5/25/2017 2:10:00PM	Groundwater	APPENDIX I METALS	5/31/2017 10:54:00 AM	06/08/2017	
1705Q25-004C	MW-05	5/25/2017 2:10:00PM	Groundwater	TOTAL MERCURY	6/6/2017 12:43:00 PM	06/07/2017	
1705Q25-004D	MW-05	5/25/2017 2:10:00PM	Groundwater	Inorganic Anions by IC			06/01/2017
1705Q25-005A	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00 PM	06/01/2017	
1705Q25-005B	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00 PM	05/31/2017	
1705Q25-005C	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	APPENDIX I METALS	5/30/2017 5:37:00 PM	06/02/2017	
1705Q25-005C	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	APPENDIX I METALS	5/30/2017 5:37:00 PM	06/05/2017	
1705Q25-005C	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	TOTAL MERCURY	6/1/2017 1:34:00 PM	06/07/2017	
1705Q25-005D	EQUIPMENT BLANK	5/25/2017 2:25:00PM	Aqueous	Inorganic Anions by IC			05/26/2017
1705Q25-006A	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I VOLATILE ORGANICS	5/31/2017 12:44:00 PM	06/01/2017	
1705Q25-006B	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	MICRO-EXTRACTABLE VOCs	5/30/2017 3:30:00 PM	05/31/2017	
1705Q25-006C	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I METALS	5/30/2017 5:37:00 PM	06/02/2017	
1705Q25-006C	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	APPENDIX I METALS	5/30/2017 5:37:00 PM	06/05/2017	

Client: Santek Environmental Inc.
Project Name: Loudon County (Matlock Bend) Phase II/IV LF
Lab Order: 1705Q25

Dates Report

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q25-006C	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	TOTAL MERCURY		6/1/2017 1:34:00 PM	06/07/2017
1705Q25-006D	TRIP BLANK	5/25/2017 9:00:00AM	Aqueous	Inorganic Anions by IC			05/26/2017

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID:	MB-243302	Client ID:		TestCode:	APPENDIX I METALS	SW6020B	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344540
Sample Type:	MBLK	TestCode:	APPENDIX I METALS	SW6020B			BatchID:	243302	Analysis Date:	06/02/2017	Seq No:	7559367
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual	
Copper	BRL	0.0200										
Sample ID:	MB-243302	Client ID:		TestCode:	APPENDIX I METALS	SW6020B	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344566
Sample Type:	MBLK	TestCode:	APPENDIX I METALS	SW6020B			BatchID:	243302	Analysis Date:	06/01/2017	Seq No:	7559781
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual	
Antimony	BRL	0.00600										
Arsenic	BRL	0.0100										
Barium	BRL	0.0200										
Beryllium	BRL	0.00400										
Cadmium	BRL	0.00500										
Chromium	BRL	0.0200										
Cobalt	BRL	0.0500										
Lead	BRL	0.0100										
Nickel	BRL	0.0400										
Selenium	BRL	0.0500										
Silver	BRL	0.00500										
Thallium	BRL	0.00200										
Vanadium	BRL	0.0500										
Zinc	BRL	0.0200										
Sample ID:	MB-243302	Client ID:		TestCode:	Total Metals by ICP/MS	SW6020B	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344584
Sample Type:	MBLK	TestCode:	Total Metals by ICP/MS	SW6020B			BatchID:	243302	Analysis Date:	06/01/2017	Seq No:	7560426
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual	
Iron	BRL	0.100										

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: MB-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 345019					
Sample Type: MBLK	TestCode: Total Metals by ICP/MS	SW6020B	BatchID: 243302	Analysis Date:	06/08/2017	Seq No: 7571568					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Calcium	BRL	0.100									
Iron	BRL	0.100									
Magnesium	BRL	0.100									
Potassium	BRL	0.100									
Sodium	BRL	0.500									
Sample ID: LCS-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344540					
Sample Type: LCS	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/02/2017	Seq No: 7559368					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Copper	0.09284	0.0200	0.1000	0.0002030	92.6	80	120				
Sample ID: LCS-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344566					
Sample Type: LCS	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7559782					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Antimony	0.1049	0.00600	0.1000		105	80	120				
Arsenic	0.09333	0.0100	0.1000		93.3	80	120				
Barium	0.1055	0.0200	0.1000	0.0005320	105	80	120				
Beryllium	0.09692	0.00400	0.1000		96.9	80	120				
Cadmium	0.09719	0.00500	0.1000		97.2	80	120				
Chromium	0.09847	0.0200	0.1000	0.0007390	97.7	80	120				
Cobalt	0.09375	0.0500	0.1000		93.8	80	120				
Lead	0.1015	0.0100	0.1000		102	80	120				
Nickel	0.09223	0.0400	0.1000		92.2	80	120				
Selenium	0.09404	0.0500	0.1000		94.0	80	120				
Silver	0.009975	0.00500	0.0100	0.00003400	99.4	80	120				
Thallium	0.1010	0.00200	0.1000		101	80	120				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: LCS-243302	Client ID:				Units: mg/L	Prep Date:	05/30/2017	Run No: 344566
SampleType: LCS	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7559782
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Vanadium	0.09685	0.0500	0.1000		96.8	80	120	
Zinc	0.09512	0.0200	0.1000	0.0006540	94.5	80	120	
Sample ID: LCS-243302	Client ID:				Units: mg/L	Prep Date:	05/30/2017	Run No: 344584
SampleType: LCS	TestCode: Total Metals by ICP/MS	SW6020B			BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7560427
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Iron	0.9464	0.100	1.000		94.6	80	120	
Sample ID: LCS-243302	Client ID:				Units: mg/L	Prep Date:	05/30/2017	Run No: 345019
SampleType: LCS	TestCode: Total Metals by ICP/MS	SW6020B			BatchID: 243302	Analysis Date:	06/08/2017	Seq No: 7571569
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Calcium	0.9356	0.100	1.000		93.6	80	120	
Iron	0.9790	0.100	1.000		97.9	80	120	
Magnesium	0.9080	0.100	1.000		90.8	80	120	
Potassium	0.9529	0.100	1.000	0.01452	93.8	80	120	
Sodium	0.8489	0.500	1.000	0.01791	83.1	80	120	
Sample ID: 1705P77-024BMS	Client ID:				Units: mg/L	Prep Date:	05/30/2017	Run No: 344540
SampleType: MS	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date:	06/02/2017	Seq No: 7559370
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Copper	0.09849	0.0200	0.1000	0.004447	94.0	75	125	
Sample ID: 1705P77-024BMS	Client ID:				Units: mg/L	Prep Date:	05/30/2017	Run No: 344566
SampleType: MS	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7559784
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase I
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: 1705P77-024BMS	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344566
SampleType: MS	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7559784
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual						

Antimony	0.09429	0.00600	0.1000	0.0005890	93.7	75	125
Arsenic	0.08759	0.0100	0.1000	0.002215	85.4	75	125
Barium	0.3091	0.0200	0.1000	0.2111	98.0	75	125
Beryllium	0.09855	0.00400	0.1000	0.0004550	98.1	75	125
Cadmium	0.09821	0.00500	0.1000	0.001230	97.0	75	125
Chromium	0.09345	0.0200	0.1000	0.003847	89.6	75	125
Cobalt	0.09230	0.0500	0.1000	0.004258	88.0	75	125
Lead	0.1046	0.0100	0.1000	0.002562	102	75	125
Nickel	0.08925	0.0400	0.1000	0.004488	84.8	75	125
Selenium	0.08560	0.0500	0.1000	0.0004390	85.2	75	125
Silver	0.009820	0.00500	0.0100	0.0001000	97.2	75	125
Thallium	0.1018	0.00200	0.1000	0.0003950	101	75	125
Vanadium	0.09517	0.0500	0.1000	0.006062	89.1	75	125
Zinc	0.1366	0.0200	0.1000	0.05003	86.6	75	125

Sample ID: 1705P77-024BMS	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344584
SampleType: MS	TestCode: Total Metals by ICP/MS	SW6020B	BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7560429
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual						

Iron	7.296	0.100	1.000	6.514	78.2	75	125
------	-------	-------	-------	-------	------	----	-----

Sample ID: 1705P77-024BMS	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 345019
SampleType: MS	TestCode: Total Metals by ICP/MS	SW6020B	BatchID: 243302	Analysis Date:	06/08/2017	Seq No: 7571571
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual						

Calcium	11.95	0.100	1.000	11.31	64.0	75	125	S
Iron	11.54	0.100	1.000	10.68	86.0	75	125	
Magnesium	7.619	0.100	1.000	6.937	68.2	75	125	S

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: 1705P77-024BMS		Client ID: SampleType: MS TestCode: Total Metals by ICP/MS		Units: mg/L		Prep Date: 05/30/2017		Run No: 345019			
				BatchID: 243302		Analysis Date: 06/08/2017		Seq No: 7571571			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Potassium	3.952	0.100	1.000	3.065	88.7	75	125				
Sodium	24.97	0.500	1.000	25.23	-26.0	75	125				S

Sample ID: 1705P77-024BMSD		Client ID: SampleType: MSD TestCode: APPENDIX I METALS		Units: mg/L		Prep Date: 05/30/2017		Run No: 344540			
				BatchID: 243302		Analysis Date: 06/02/2017		Seq No: 7559373			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Copper	0.1049	0.0200	0.1000	0.004447	100	75	125	0.09849	6.28	20	

Sample ID: 1705P77-024BMSD		Client ID: SampleType: MSD TestCode: APPENDIX I METALS		Units: mg/L		Prep Date: 05/30/2017		Run No: 344566			
				BatchID: 243302		Analysis Date: 06/01/2017		Seq No: 7559785			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.09219	0.00600	0.1000	0.0005890	91.6	75	125	0.09429	2.25	20	
Arsenic	0.08473	0.0100	0.1000	0.002215	82.5	75	125	0.08759	3.32	20	
Barium	0.3017	0.0200	0.1000	0.2111	90.6	75	125	0.3091	2.42	20	
Beryllium	0.09474	0.00400	0.1000	0.0004550	94.3	75	125	0.09855	3.94	20	
Cadmium	0.09841	0.00500	0.1000	0.001230	97.2	75	125	0.09821	0.203	20	
Chromium	0.09519	0.0200	0.1000	0.003847	91.3	75	125	0.09345	1.84	20	
Cobalt	0.09275	0.0500	0.1000	0.004258	88.5	75	125	0.09230	0.486	20	
Lead	0.1054	0.0100	0.1000	0.002562	103	75	125	0.1046	0.762	20	
Nickel	0.08886	0.0400	0.1000	0.004488	84.4	75	125	0.08925	0.438	20	
Selenium	0.08169	0.0500	0.1000	0.0004390	81.3	75	125	0.08560	4.67	20	
Silver	0.009999	0.00500	0.0100	0.0001000	99.0	75	125	0.009820	1.81	20	
Thallium	0.1030	0.00200	0.1000	0.0003950	103	75	125	0.1018	1.17	20	
Vanadium	0.09652	0.0500	0.1000	0.006062	90.5	75	125	0.09517	1.41	20	
Zinc	0.1380	0.0200	0.1000	0.05003	88.0	75	125	0.1366	1.02	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: 1705P77-024BMSD	Client ID:					Units: mg/L	Prep Date: 05/30/2017	Run No: 344584
SampleType: MSD	TestCode: Total Metals by ICP/MS	SW6020B				BatchID: 243302	Analysis Date: 06/01/2017	Seq No: 7560430
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Iron	7.547	0.100	1.000	6.514	103	75	125	7.296
Sample ID: 1705P77-024BMSD	Client ID:					Units: mg/L	Prep Date: 05/30/2017	Run No: 345019
SampleType: MSD	TestCode: Total Metals by ICP/MS	SW6020B				BatchID: 243302	Analysis Date: 06/08/2017	Seq No: 7571572
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Calcium	12.05	0.100	1.000	11.31	74.0	75	125	11.95
Iron	11.54	0.100	1.000	10.68	86.0	75	125	11.54
Magnesium	7.838	0.100	1.000	6.937	90.1	75	125	7.619
Potassium	3.980	0.100	1.000	3.065	91.5	75	125	3.952
Sodium	25.94	0.500	1.000	25.23	71.0	75	125	24.97

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase I
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243324

Sample ID: MB-243324	Client ID:		Units: ug/L	Prep Date: 05/30/2017	Run No: 344377
SampleType: MBLK	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243324	Analysis Date: 05/31/2017	Seq No: 7554682
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

1,2-Dibromo-3-chloropropane	BRL	0.040				
1,2-Dibromoethane	BRL	0.020				
Surr: 4-Bromofluorobenzene	4.986	0	5.000	99.7	69.4	134

Sample ID: LCS-243324	Client ID:		Units: ug/L	Prep Date: 05/30/2017	Run No: 344377
SampleType: LCS	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243324	Analysis Date: 05/31/2017	Seq No: 7554683
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000	98.0	60	140
1,2-Dibromoethane	0.09500	0.020	0.1000	95.0	60	140
Surr: 4-Bromofluorobenzene	5.301	0	5.000	106	69.4	134

Sample ID: LCSD-243324	Client ID:		Units: ug/L	Prep Date: 05/30/2017	Run No: 344377
SampleType: LCSD	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243324	Analysis Date: 05/31/2017	Seq No: 7554685
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000	98.0	60	140	0.09800	0	20
1,2-Dibromoethane	0.09600	0.020	0.1000	96.0	60	140	0.09500	1.05	20
Surr: 4-Bromofluorobenzene	5.245	0	5.000	105	69.4	134	5.301	0	0

Sample ID: 1705Q20-001BMS	Client ID: MW-01		Units: ug/L	Prep Date: 05/30/2017	Run No: 344377
SampleType: MS	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243324	Analysis Date: 05/31/2017	Seq No: 7554690
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

1,2-Dibromo-3-chloropropane	0.09659	0.040	0.0996	97.0	51.3	144
1,2-Dibromoethane	0.09758	0.020	0.0996	98.0	57.7	132
Surr: 4-Bromofluorobenzene	4.784	0	4.979	96.1	69.4	134

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID: MB-243390	Client ID:		Units: mg/L	Prep Date: 05/31/2017	Run No: 344570
SampleType: MBLK	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243390	Analysis Date: 06/02/2017	Seq No: 7559943
Analyte Result RPT Limit SPK value SPK Ref Val %REC					
Antimony	BRL	0.00600			
Arsenic	BRL	0.0100			
Barium	BRL	0.0200			
Beryllium	BRL	0.00400			
Cadmium	BRL	0.00500			
Chromium	BRL	0.0200			
Cobalt	BRL	0.0500			
Copper	BRL	0.0200			
Lead	BRL	0.0100			
Nickel	BRL	0.0400			
Selenium	BRL	0.0500			
Silver	BRL	0.00500			
Thallium	BRL	0.00200			
Vanadium	BRL	0.0500			
Zinc	BRL	0.0200			

Sample ID: MB-243390	Client ID:		Units: mg/L	Prep Date: 05/31/2017	Run No: 345018
SampleType: MBLK	TestCode: Total Metals by ICP/MS	SW6020B	BatchID: 243390	Analysis Date: 06/08/2017	Seq No: 7571535
Analyte Result RPT Limit SPK value SPK Ref Val %REC					
Calcium	BRL	0.100			
Iron	BRL	0.100			
Magnesium	BRL	0.100			
Potassium	BRL	0.100			
Sodium	BRL	0.500			

Qualifiers: >	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	LCS-243390	Client ID:		Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570		
Sample Type:	LCS	TestCode:	APPENDIX I METALS	BatchID:	243390	Analysis Date:	06/02/2017	Seq No:	7559944		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1049	0.00600	0.1000		105	80	120				
Arsenic	0.09720	0.0100	0.1000	0.0003020	96.9	80	120				
Barium	0.1059	0.0200	0.1000	0.0001990	106	80	120				
Beryllium	0.1004	0.00400	0.1000		100	80	120				
Cadmium	0.1004	0.00500	0.1000		100	80	120				
Chromium	0.1114	0.0200	0.1000	0.004256	107	80	120				
Cobalt	0.09718	0.0500	0.1000		97.2	80	120				
Copper	0.09508	0.0200	0.1000	0.001508	93.6	80	120				
Lead	0.1015	0.0100	0.1000		102	80	120				
Nickel	0.1033	0.0400	0.1000	0.002346	101	80	120				
Selenium	0.09930	0.0500	0.1000		99.3	80	120				
Silver	0.01025	0.00500	0.0100	0.00005200	102	80	120				
Thallium	0.1003	0.00200	0.1000		100	80	120				
Vanadium	0.09813	0.0500	0.1000	0.0004270	97.7	80	120				
Zinc	0.1082	0.0200	0.1000	0.003554	105	80	120				

Sample ID:	LCS-243390	Client ID:		Units:	mg/L	Prep Date:	05/31/2017	Run No:	345018		
Sample Type:	LCS	TestCode:	Total Metals by ICP/MS	BatchID:	243390	Analysis Date:	06/08/2017	Seq No:	7571536		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	1.097	0.100	1.000	0.07192	103	80	120				
Iron	0.9963	0.100	1.000		99.6	80	120				
Magnesium	0.9162	0.100	1.000		91.6	80	120				
Potassium	0.9673	0.100	1.000		96.7	80	120				
Sodium	0.9071	0.500	1.000	0.03703	87.0	80	120				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	1705Q20-006IMS	Client ID:	MW-03			Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570
Sample Type:	MS	TestCode:	APPENDIX I METALS			BatchID:	243390	Analysis Date:	06/02/2017	Seq No:	7559947
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1029	0.00600	0.1000	0.0008790	102	75	125				
Arsenic	0.09026	0.0100	0.1000	0.0005500	89.7	75	125				
Barium	0.2064	0.0200	0.1000	0.1040	102	75	125				
Beryllium	0.09809	0.00400	0.1000		98.1	75	125				
Cadmium	0.09740	0.00500	0.1000	0.0003680	97.0	75	125				
Chromium	0.1008	0.0200	0.1000	0.001539	99.3	75	125				
Cobalt	0.1025	0.0500	0.1000	0.01097	91.5	75	125				
Copper	0.08859	0.0200	0.1000	0.002790	85.8	75	125				
Lead	0.1018	0.0100	0.1000	0.0008580	101	75	125				
Nickel	0.1040	0.0400	0.1000	0.01205	92.0	75	125				
Selenium	0.09003	0.0500	0.1000	0.0003690	89.7	75	125				
Silver	0.009767	0.00500	0.0100	0.00006400	97.0	75	125				
Thallium	0.1013	0.00200	0.1000	0.0007370	101	75	125				
Vanadium	0.09545	0.0500	0.1000		95.4	75	125				
Zinc	0.09775	0.0200	0.1000	0.004953	92.8	75	125				

Sample ID:	1705Q20-006IMS	Client ID:	MW-03			Units:	mg/L	Prep Date:	05/31/2017	Run No:	345018
Sample Type:	MS	TestCode:	Total Metals by ICP/MS			BatchID:	243390	Analysis Date:	06/08/2017	Seq No:	7571517
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	13.16	0.100	1.000	12.27	89.0	75	125				
Iron	1.112	0.100	1.000	0.1392	97.3	75	125				
Magnesium	5.212	0.100	1.000	4.293	91.9	75	125				
Potassium	5.955	0.100	1.000	5.073	88.2	75	125				
Sodium	42.74	0.500	1.000	42.28	46.0	75	125				S

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	1705Q20-006IMSD	Client ID:	MW-03			Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570
Sample Type:	MSD	Test Code:	APPENDIX I METALS			Batch ID:	243390	Analysis Date:	06/02/2017	Seq No:	7559949
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1011	0.00600	0.1000	0.0008790	100	75	125	0.1029	1.76	20	
Arsenic	0.08511	0.0100	0.1000	0.0005500	84.6	75	125	0.09026	5.87	20	
Barium	0.2115	0.0200	0.1000	0.1040	108	75	125	0.2064	2.44	20	
Beryllium	0.09513	0.00400	0.1000		95.1	75	125	0.09809	3.06	20	
Cadmium	0.09516	0.00500	0.1000	0.0003680	94.8	75	125	0.09740	2.33	20	
Chromium	0.09581	0.0200	0.1000	0.001539	94.3	75	125	0.1008	5.08	20	
Cobalt	0.09885	0.0500	0.1000	0.01097	87.9	75	125	0.1025	3.63	20	
Copper	0.08345	0.0200	0.1000	0.002790	80.7	75	125	0.08859	5.98	20	
Lead	0.1042	0.0100	0.1000	0.0008580	103	75	125	0.1018	2.33	20	
Nickel	0.09845	0.0400	0.1000	0.01205	86.4	75	125	0.1040	5.48	20	
Selenium	0.08619	0.0500	0.1000	0.0003690	85.8	75	125	0.09003	4.36	20	
Silver	0.009144	0.00500	0.0100	0.00006400	90.8	75	125	0.009767	6.59	20	
Thallium	0.1049	0.00200	0.1000	0.0007370	104	75	125	0.1013	3.49	20	
Vanadium	0.09432	0.0500	0.1000		94.3	75	125	0.09545	1.19	20	
Zinc	0.09047	0.0200	0.1000	0.004953	85.5	75	125	0.09775	7.74	20	

Sample ID:	1705Q20-006IMSD	Client ID:	MW-03			Units:	mg/L	Prep Date:	05/31/2017	Run No:	345018
Sample Type:	MSD	Test Code:	Total Metals by ICP/MS			Batch ID:	243390	Analysis Date:	06/08/2017	Seq No:	7571523
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	13.26	0.100	1.000	12.27	99.0	75	125	13.16	0.757	20	
Iron	1.094	0.100	1.000	0.1392	95.5	75	125	1.112	1.63	20	
Magnesium	5.413	0.100	1.000	4.293	112	75	125	5.212	3.78	20	
Potassium	6.059	0.100	1.000	5.073	98.6	75	125	5.955	1.73	20	
Sodium	44.83	0.500	1.000	42.28	255	75	125	42.74	4.77	20	S

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243457

Sample ID:	MB-243457	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MBLK	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557558
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Mercury		BRL	0.00020								
Sample ID:	LCS-243457	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	LCS	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557559
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Mercury		0.003802	0.00020	0.0040		95.1	80	120			
Sample ID:	1705P20-002BMS	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MS	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557561
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Mercury		0.003802	0.00020	0.0040		95.1	70	130			
Sample ID:	1705P20-002BMSD	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MSD	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557562
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Mercury		0.003868	0.00020	0.0040		96.7	70	130	0.003802	1.72	20

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spiko Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID:	MB-243483	Client ID:		Units:	ug/L	Prep Date:	05/31/2017	Run No:	344328		
Sample Type:	MBLK	TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	BatchID:	243483	Analysis Date:	05/31/2017	Seq No:	7556038		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1,1,2-Tetrachloroethane	BRL	5.0									
1,1,1-Trichloroethane	BRL	5.0									
1,1,2,2-Tetrachloroethane	BRL	5.0									
1,1,2-Trichloroethane	BRL	5.0									
1,1-Dichloroethane	BRL	5.0									
1,1-Dichloroethene	BRL	5.0									
1,2,3-Trichloropropane	BRL	5.0									
1,2-Dichlorobenzene	BRL	5.0									
1,2-Dichloroethane	BRL	5.0									
1,2-Dichloropropane	BRL	5.0									
1,4-Dichlorobenzene	BRL	5.0									
2-Butanone	BRL	50									
2-Hexanone	BRL	10									
4-Methyl-2-pentanone	BRL	10									
Acetone	BRL	50									
Acrylonitrile	BRL	5.0									
Benzene	BRL	5.0									
Bromochloromethane	BRL	5.0									
Bromodichloromethane	BRL	5.0									
Bromoform	BRL	5.0									
Bromomethane	BRL	5.0									
Carbon disulfide	BRL	5.0									
Carbon tetrachloride	BRL	5.0									
Chlorobenzene	BRL	5.0									
Chloroethane	BRL	10									
Chloroform	BRL	5.0									
Chloromethane	BRL	10									

Qualifiers: > Greater than Result value

BRL Below reporting limit

J Estimated value detected below Reporting Limit

Rpt Lim Reporting Limit

< Less than Result value

E Estimated (value above quantitation range)

N Analyte not NELAC certified

S Spike Recovery outside limits due to matrix

B Analyte detected in the associated method blank

H Holding times for preparation or analysis exceeded

R RPD outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase I
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID: MB-243483	Client ID:		Units: ug/L	Prep Date: 05/31/2017	Run No: 344328
SampleType: MBLK	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B		BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7556038
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

cis-1,2-Dichloroethene	BRL	5.0									
cis-1,3-Dichloropropene	BRL	5.0									
Dibromochloromethane	BRL	5.0									
Dibromomethane	BRL	5.0									
Ethylbenzene	BRL	5.0									
Iodomethane	BRL	10									
Methylene chloride	BRL	5.0									
Styrene	BRL	5.0									
Tetrachloroethene	BRL	5.0									
Toluene	BRL	5.0									
trans-1,2-Dichloroethene	BRL	5.0									
trans-1,3-Dichloropropene	BRL	5.0									
trans-1,4-Dichloro-2-butene	BRL	10									
Trichloroethene	BRL	5.0									
Trichlorofluoromethane	BRL	5.0									
Vinyl acetate	BRL	10									
Vinyl chloride	BRL	2.0									
Xylenes, Total	BRL	10									
Surr: 4-Bromofluorobenzene	46.71	0	50.00		93.4	66.1	129				
Surr: Dibromofluoromethane	46.93	0	50.00		93.9	83.6	123				
Surr: Toluene-d8	48.85	0	50.00		97.7	81.8	118				

Sample ID: LCS-243483	Client ID:		Units: ug/L	Prep Date: 05/31/2017	Run No: 344328						
SampleType: LCS	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B		BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7556037						
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
1,1-Dichloroethene	18.15	5.0	20.00		90.8	68	139				
Benzene	18.91	5.0	20.00		94.6	74	125				

Qualifiers: >	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase I
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID: LCS-243483	Client ID:					Units: ug/L	Prep Date: 05/31/2017	Run No: 344328			
SampleType: LCS	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B					BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7556037			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

Chlorobenzene	19.22	5.0	20.00		96.1	75.7	123				
Toluene	18.87	5.0	20.00		94.4	75.9	126				
Trichloroethene	19.44	5.0	20.00		97.2	70.6	129				
Sur: 4-Bromofluorobenzene	48.08	0	50.00		96.2	66.1	129				
Sur: Dibromofluoromethane	49.39	0	50.00		98.8	83.6	123				
Sur: Toluene-d8	49.22	0	50.00		98.4	81.8	118				

Sample ID: 1705Q21-001AMS	Client ID:					Units: ug/L	Prep Date: 05/31/2017	Run No: 344413			
SampleType: MS	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B					BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7555545			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

1,1-Dichloroethene	54.45	5.0	50.00		109	64.3	149				
Benzene	53.03	5.0	50.00		106	71.6	132				
Chlorobenzene	54.14	5.0	50.00		108	73.1	126				
Toluene	53.26	5.0	50.00		107	72.5	135				
Trichloroethene	52.13	5.0	50.00		104	70.2	132				
Sur: 4-Bromofluorobenzene	46.26	0	50.00		92.5	66.1	129				
Sur: Dibromofluoromethane	46.19	0	50.00		92.4	83.6	123				
Sur: Toluene-d8	48.57	0	50.00		97.1	81.8	118				

Sample ID: 1705Q21-001AMSD	Client ID:					Units: ug/L	Prep Date: 05/31/2017	Run No: 344413			
SampleType: MSD	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B					BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7555546			
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

1,1-Dichloroethene	49.16	5.0	50.00		98.3	64.3	149	54.45	10.2	30.8	
Benzene	51.53	5.0	50.00		103	71.6	132	53.03	2.87	20.7	
Chlorobenzene	52.72	5.0	50.00		105	73.1	126	54.14	2.66	26.6	
Toluene	51.57	5.0	50.00		103	72.5	135	53.26	3.22	23.2	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID: 1705Q21-001AMSD	Client ID:				Units: ug/L	Prep Date:	05/31/2017	Run No: 344413
SampleType: MSD	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243483	Analysis Date:	05/31/2017	Seq No: 7555546
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val
Trichloroethene	49.43	5.0	50.00		98.9	70.2	132	52.13
Surrogate: 4-Bromofluorobenzene	46.48	0	50.00		93.0	66.1	129	46.26
Surrogate: Dibromofluoromethane	46.38	0	50.00		92.8	83.6	123	46.19
Surrogate: Toluene-d8	48.46	0	50.00		96.9	81.8	118	48.57

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243493

Sample ID: MB-243493	Client ID:	Units: mg/L	Prep Date: 06/01/2017	Run No: 344564							
SampleType: MBLK	TestCode: Residue, Dissolved (TDS) by SM2540C	BatchID: 243493	Analysis Date: 06/01/2017	Seq No: 7559706							
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

Residue, Dissolved (TDS)	BRL	10	Sample ID: 1705Q20-001EDUP	Client ID: MW-01	Units: mg/L	Prep Date: 06/01/2017	Run No: 344564				
SampleType: DUP	TestCode: Residue, Dissolved (TDS) by SM2540C				BatchID: 243493	Analysis Date: 06/01/2017	Seq No: 7559721				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Residue, Dissolved (TDS)	280.0	10				270.0		3.64		5	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243542

Sample ID:	MB-243542	Client ID:				Units:	mg/L	Prep Date:	06/02/2017	Run No:	344559
SampleType:	MBLK	TestCode:	Nitrogen, Ammonia (as N)	E350.1		BatchID:	243542	Analysis Date:	06/02/2017	Seq No:	7559900
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	BRL	0.200									
Sample ID:	LCS-243542	Client ID:				Units:	mg/L	Prep Date:	06/02/2017	Run No:	344559
SampleType:	LCS	TestCode:	Nitrogen, Ammonia (as N)	E350.1		BatchID:	243542	Analysis Date:	06/02/2017	Seq No:	7559901
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.210	0.200	5.000		104	90	110				
Sample ID:	1705Q20-005HMS	Client ID:	MW-02				Units:	mg/L	Prep Date:	06/02/2017	Run No:
SampleType:	MS	TestCode:	Nitrogen, Ammonia (as N)	E350.1		BatchID:	243542	Analysis Date:	06/02/2017	Seq No:	7559907
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.070	0.200	5.000		101	90	110				
Sample ID:	1706118-001AMS	Client ID:				Units:	mg/L	Prep Date:	06/02/2017	Run No:	344559
SampleType:	MS	TestCode:	Nitrogen, Ammonia (as N)	E350.1		BatchID:	243542	Analysis Date:	06/02/2017	Seq No:	7560098
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.510	0.200	5.000	0.8210	93.8	90	110				
Sample ID:	1705Q20-005HMSD	Client ID:	MW-02				Units:	mg/L	Prep Date:	06/02/2017	Run No:
SampleType:	MSD	TestCode:	Nitrogen, Ammonia (as N)	E350.1		BatchID:	243542	Analysis Date:	06/02/2017	Seq No:	7559908
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.070	0.200	5.000		101	90	110	5.070	0	30	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243607

Sample ID:	MB-243607	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640
SampleType:	MBLK	TestCode:	Cyanide	SW9014		BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561664
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Cyanide, Total		BRL	0.010								
Sample ID:	LCS-243607	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640
SampleType:	LCS	TestCode:	Cyanide	SW9014		BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561665
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Cyanide, Total		0.2390	0.010	0.2500		95.6	85	115			
Sample ID:	1705Q20-001GMS	Client ID:	MW-01			Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640
SampleType:	MS	TestCode:	Cyanide	SW9014		BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561683
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Cyanide, Total		0.2730	0.010	0.2500		109	70	130			
Sample ID:	1705Q20-001GMSD	Client ID:	MW-01			Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640
SampleType:	MSD	TestCode:	Cyanide	SW9014		BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561693
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit Qual
Cyanide, Total		0.2830	0.010	0.2500		113	70	130	0.2730	3.60	20

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243633

Sample ID:	MB-243633	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771	
Sample Type:	MBLK	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566789	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese		BRL	0.00500									
Sample ID:	LCS-243633	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771	
Sample Type:	LCS	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566792	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese		0.08865	0.00500	0.1000		88.7	80	120				
Sample ID:	1705Q15-002DMS	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771	
Sample Type:	MS	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566794	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese		0.1287	0.00500	0.1000	0.04800	80.7	75	125				
Sample ID:	1705Q15-002DMSD	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771	
Sample Type:	MSD	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566795	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese		0.1292	0.00500	0.1000	0.04800	81.2	75	125	0.1287	0.385	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santeck Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: 243660

Sample ID:	MB-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
SampleType:	MBLK	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566603
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	BRL	0.00020									
Sample ID:	LCS-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
SampleType:	LCS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566606
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.004880	0.00020	0.0050		97.6	80	120				
Sample ID:	1705Q20-002AMS	Client ID:	MW-01			Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
SampleType:	MS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566608
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005527	0.00020	0.0050	0.0001346	108	70	130				
Sample ID:	1705Q20-002AMSD	Client ID:	MW-01			Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
SampleType:	MSD	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566609
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005814	0.00020	0.0050	0.0001346	114	70	130	0.005527	5.06	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: R344266

Sample ID: MB-R344266	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MBLK	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7551989
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride	BRL	1.00
Fluoride	BRL	0.200
Nitrogen, Nitrate (As N)	BRL	0.250
Sulfate	BRL	1.00

Sample ID: LCS-R344266	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: LCS	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7551988
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride	10.27	1.00	10.00	0.1782	101	90	110
Fluoride	4.778	0.200	5.000		95.6	90	110
Nitrogen, Nitrate (As N)	4.731	0.250	5.000		94.6	90	110
Sulfate	25.54	1.00	25.00	0.3314	101	90	110

Sample ID: 1705Q20-010FMS	Client ID: TRIP BLANK		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MS	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552004
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride	10.75	1.00	10.00	0.3582	104	90	110
Fluoride	4.747	0.200	5.000		94.9	90	110
Nitrogen, Nitrate (As N)	4.638	0.250	5.000		92.8	90	110
Sulfate	25.27	1.00	25.00		101	90	110

Sample ID: 1705Q20-010FMSD	Client ID: TRIP BLANK		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MSD	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552008
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride	10.41	1.00	10.00	0.3582	101	90	110	10.75	3.17	20
----------	-------	------	-------	--------	-----	----	-----	-------	------	----

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase I
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: R344266

Sample ID: 1705Q20-010FMSD	Client ID: TRIP BLANK	Units: mg/L	Prep Date:	Run No: 344266							
SampleType: MSD	TestCode: Inorganic Anions by IC E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552008							
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	4.831	0.200	5.000		96.6	90	110	4.747	1.75	20	
Nitrogen, Nitrate (As N)	4.698	0.250	5.000		94.0	90	110	4.638	1.28	20	
Sulfate	25.45	1.00	25.00		102	90	110	25.27	0.699	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
J		Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
Rpt Lim		Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: R344553

Sample ID:	MB-R344553	Client ID:	TestCode: Chemical Oxygen Demand (COD) E410.4			Units:	mg/L	Prep Date:	Run No:	344553	
SampleType:	MBLK	BatchID:				BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559642
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	BRL	10.0									
Sample ID:	LCS-R344553	Client ID:	TestCode: Chemical Oxygen Demand (COD) E410.4			Units:	mg/L	Prep Date:	Run No:	344553	
SampleType:	LCS	BatchID:				BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559643
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	538.3	10.0	500.0		108	90	110				
Sample ID:	1705Q15-002FMS	Client ID:	TestCode: Chemical Oxygen Demand (COD) E410.4			Units:	mg/L	Prep Date:	Run No:	344553	
SampleType:	MS	BatchID:				BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559664
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	387.2	12.5	375.0		103	90	110				
Sample ID:	1705R04-001CMS	Client ID:	TestCode: Chemical Oxygen Demand (COD) E410.4			Units:	mg/L	Prep Date:	Run No:	344553	
SampleType:	MS	BatchID:				BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559666
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	647.1	12.5	375.0	257.2	104	90	110				
Sample ID:	1705Q15-002FMSD	Client ID:	TestCode: Chemical Oxygen Demand (COD) E410.4			Units:	mg/L	Prep Date:	Run No:	344553	
SampleType:	MSD	BatchID:				BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559665
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	395.8	12.5	375.0		106	90	110	387.2	2.17	30	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill Phase 1
 Workorder: 1705Q20

ANALYTICAL QC SUMMARY REPORT

BatchID: R344664

Sample ID:	MB-R344664	Client ID:				Units:	mg/L	Prep Date:	Run No: 344664		
SampleType:	MBLK	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344664	Analysis Date:	05/30/2017	Seq No: 7562309	
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	BRL	1.00									
Sample ID:	LCS-R344664	Client ID:				Units:	mg/L	Prep Date:	Run No: 344664		
SampleType:	LCS	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344664	Analysis Date:	05/30/2017	Seq No: 7562308	
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	24.50	1.00	25.00	0.2483	97.0	90	110				
Sample ID:	1705Q20-001HMS	Client ID:	MW-01			Units:	mg/L	Prep Date:	Run No: 344664		
SampleType:	MS	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344664	Analysis Date:	05/31/2017	Seq No: 7562351	
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	476.2	20.0	500.0		95.2	80	120				
Sample ID:	1705Q20-001HMSD	Client ID:	MW-01			Units:	mg/L	Prep Date:	Run No: 344664		
SampleType:	MSD	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344664	Analysis Date:	05/31/2017	Seq No: 7562352	
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	476.0	20.0	500.0		95.2	80	120	476.2	0.042	20	

Qualifiers: > Greater than Result value

< Less than Result value

B Analyte detected in the associated method blank

BRL Below reporting limit

E Estimated (value above quantitation range)

H Holding times for preparation or analysis exceeded

J Estimated value detected below Reporting Limit

N Analyte not NELAC certified

R RPD outside limits due to matrix

Rpt Lim Reporting Limit

S Spike Recovery outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: MB-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344540					
SampleType: MBLK	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/02/2017	Seq No: 7559367					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Copper	BRL	0.0200									
Sample ID: MB-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344566					
SampleType: MBLK	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/01/2017	Seq No: 7559781					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Antimony	BRL	0.00600									
Arsenic	BRL	0.0100									
Barium	BRL	0.0200									
Beryllium	BRL	0.00400									
Cadmium	BRL	0.00500									
Chromium	BRL	0.0200									
Cobalt	BRL	0.0500									
Lead	BRL	0.0100									
Nickel	BRL	0.0400									
Selenium	BRL	0.0500									
Silver	BRL	0.00500									
Thallium	BRL	0.00200									
Vanadium	BRL	0.0500									
Zinc	BRL	0.0200									
Sample ID: LCS-243302	Client ID:		Units: mg/L	Prep Date:	05/30/2017	Run No: 344540					
SampleType: LCS	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243302	Analysis Date:	06/02/2017	Seq No: 7559368					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Copper	0.09284	0.0200	0.1000	0.0002030	92.6	80	120				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID:	LCS-243302	Client ID:		Units:	mg/L	Prep Date:	05/30/2017	Run No:	344566		
SampleType:	LCS	TestCode:	APPENDIX I METALS	BatchID:	243302	Analysis Date:	06/01/2017	Seq No:	7559782		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1049	0.00600	0.1000		105	80	120				
Arsenic	0.09333	0.0100	0.1000		93.3	80	120				
Barium	0.1055	0.0200	0.1000	0.0005320	105	80	120				
Beryllium	0.09692	0.00400	0.1000		96.9	80	120				
Cadmium	0.09719	0.00500	0.1000		97.2	80	120				
Chromium	0.09847	0.0200	0.1000	0.0007390	97.7	80	120				
Cobalt	0.09375	0.0500	0.1000		93.8	80	120				
Lead	0.1015	0.0100	0.1000		102	80	120				
Nickel	0.09223	0.0400	0.1000		92.2	80	120				
Selenium	0.09404	0.0500	0.1000		94.0	80	120				
Silver	0.009975	0.00500	0.1000	0.00003400	99.4	80	120				
Thallium	0.1010	0.00200	0.1000		101	80	120				
Vanadium	0.09685	0.0500	0.1000		96.8	80	120				
Zinc	0.09512	0.0200	0.1000	0.0006540	94.5	80	120				

Sample ID:	1705P77-024BMS	Client ID:	GWC-23	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344540		
SampleType:	MS	TestCode:	APPENDIX I METALS	BatchID:	243302	Analysis Date:	06/02/2017	Seq No:	7559370		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Copper	0.09849	0.0200	0.1000	0.004447	94.0	75	125				

Sample ID:	1705P77-024BMS	Client ID:	GWC-23	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344566		
SampleType:	MS	TestCode:	APPENDIX I METALS	BatchID:	243302	Analysis Date:	06/01/2017	Seq No:	7559784		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.09429	0.00600	0.1000	0.0005890	93.7	75	125				
Arsenic	0.08759	0.0100	0.1000	0.002215	85.4	75	125				
Barium	0.3091	0.0200	0.1000	0.2111	98.0	75	125				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID: 1705P77-024BMS	Client ID: GWC-23				Units: mg/L	Prep Date: 05/30/2017	Run No: 344566				
SampleType: MS	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date: 06/01/2017	Seq No: 7559784				
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Beryllium	0.09855	0.00400	0.1000	0.0004550	98.1	75	125				
Cadmium	0.09821	0.00500	0.1000	0.001230	97.0	75	125				
Chromium	0.09345	0.0200	0.1000	0.003847	89.6	75	125				
Cobalt	0.09230	0.0500	0.1000	0.004258	88.0	75	125				
Lead	0.1046	0.0100	0.1000	0.002562	102	75	125				
Nickel	0.08925	0.0400	0.1000	0.004488	84.8	75	125				
Selenium	0.08560	0.0500	0.1000	0.0004390	85.2	75	125				
Silver	0.009820	0.00500	0.0100	0.0001000	97.2	75	125				
Thallium	0.1018	0.00200	0.1000	0.0003950	101	75	125				
Vanadium	0.09517	0.0500	0.1000	0.006062	89.1	75	125				
Zinc	0.1366	0.0200	0.1000	0.05003	86.6	75	125				
Sample ID: 1705P77-024BMSD	Client ID: GWC-23				Units: mg/L	Prep Date: 05/30/2017	Run No: 344540				
SampleType: MSD	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date: 06/02/2017	Seq No: 7559373				
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Copper	0.1049	0.0200	0.1000	0.004447	100	75	125	0.09849	6.28	20	
Sample ID: 1705P77-024BMSD	Client ID: GWC-23				Units: mg/L	Prep Date: 05/30/2017	Run No: 344566				
SampleType: MSD	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243302	Analysis Date: 06/01/2017	Seq No: 7559785				
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Antimony	0.09219	0.00600	0.1000	0.0005890	91.6	75	125	0.09429	2.25	20	
Arsenic	0.08473	0.0100	0.1000	0.002215	82.5	75	125	0.08759	3.32	20	
Barium	0.3017	0.0200	0.1000	0.2111	90.6	75	125	0.3091	2.42	20	
Beryllium	0.09474	0.00400	0.1000	0.0004550	94.3	75	125	0.09855	3.94	20	
Cadmium	0.09841	0.00500	0.1000	0.001230	97.2	75	125	0.09821	0.203	20	
Chromium	0.09519	0.0200	0.1000	0.003847	91.3	75	125	0.09345	1.84	20	

Qualifiers: > Greater than Result value

< Less than Result value

B Analyte detected in the associated method blank

BRL Below reporting limit

E Estimated (value above quantitation range)

H Holding times for preparation or analysis exceeded

J Estimated value detected below Reporting Limit

N Analyte not NELAC certified

R RPD outside limits due to matrix

Rpt Lim Reporting Limit

S Spike Recovery outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243302

Sample ID:	1705P77-024BMSD	Client ID:	GWC-23	Units:	mg/L	Prep Date:	05/30/2017	Run No:	344566		
SampleType:	MSD	TestCode:	APPENDIX I METALS	SPK Ref Val		BatchID:	243302	Analysis Date:	06/01/2017	Seq No:	7559785
Analyte	Result	RPT Limit	SPK value	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual	
Cobalt	0.09275	0.0500	0.1000	0.004258	88.5	75	125	0.09230	0.486	20	
Lead	0.1054	0.0100	0.1000	0.002562	103	75	125	0.1046	0.762	20	
Nickel	0.08886	0.0400	0.1000	0.004488	84.4	75	125	0.08925	0.438	20	
Selenium	0.08169	0.0500	0.1000	0.0004390	81.3	75	125	0.08560	4.67	20	
Silver	0.009999	0.00500	0.0100	0.0001000	99.0	75	125	0.009820	1.81	20	
Thallium	0.1030	0.00200	0.1000	0.0003950	103	75	125	0.1018	1.17	20	
Vanadium	0.09652	0.0500	0.1000	0.006062	90.5	75	125	0.09517	1.41	20	
Zinc	0.1380	0.0200	0.1000	0.05003	88.0	75	125	0.1366	1.02	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243325

Sample ID: MB-243325	Client ID:		Units: ug/L	Prep Date:	05/30/2017	Run No: 344377					
SampleType: MBLK	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243325	Analysis Date:	05/31/2017	Seq No: 7554693					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
1,2-Dibromo-3-chloropropane	BRL	0.040									
1,2-Dibromoethane	BRL	0.020									
Surr: 4-Bromofluorobenzene	5.044	0	5.000		101	69.4	134				
Sample ID: LCS-243325	Client ID:		Units: ug/L	Prep Date:	05/30/2017	Run No: 344377					
SampleType: LCS	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243325	Analysis Date:	05/31/2017	Seq No: 7554694					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000		98.0	60	140				
1,2-Dibromoethane	0.09400	0.020	0.1000		94.0	60	140				
Surr: 4-Bromofluorobenzene	5.266	0	5.000		105	69.4	134				
Sample ID: LCSD-243325	Client ID:		Units: ug/L	Prep Date:	05/30/2017	Run No: 344377					
SampleType: LCSD	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243325	Analysis Date:	05/31/2017	Seq No: 7554695					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000		98.0	60	140	0.09800	0	20	
1,2-Dibromoethane	0.09600	0.020	0.1000		96.0	60	140	0.09400	2.11	20	
Surr: 4-Bromofluorobenzene	5.262	0	5.000		105	69.4	134	5.266	0	0	
Sample ID: 1705Q25-004BMS	Client ID: MW-05		Units: ug/L	Prep Date:	05/30/2017	Run No: 344377					
SampleType: MS	TestCode: MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011		BatchID: 243325	Analysis Date:	05/31/2017	Seq No: 7554698					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
1,2-Dibromo-3-chloropropane	BRL	0.200	0.0999		102	51.3	144				
1,2-Dibromoethane	0.1019	0.050	0.0999		102	57.7	132				*
Surr: 4-Bromofluorobenzene	5.082	0.050	4.993		102	69.4	134				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID: MB-243390	Client ID:		Units: mg/L	Prep Date:	05/31/2017	Run No: 344570					
SampleType: MBLK	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243390	Analysis Date:	06/02/2017	Seq No: 7559943					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Antimony	BRL	0.00600									
Arsenic	BRL	0.0100									
Barium	BRL	0.0200									
Beryllium	BRL	0.00400									
Cadmium	BRL	0.00500									
Chromium	BRL	0.0200									
Cobalt	BRL	0.0500									
Copper	BRL	0.0200									
Lead	BRL	0.0100									
Nickel	BRL	0.0400									
Selenium	BRL	0.0500									
Silver	BRL	0.00500									
Thallium	BRL	0.00200									
Vanadium	BRL	0.0500									
Zinc	BRL	0.0200									

Sample ID: LCS-243390	Client ID:		Units: mg/L	Prep Date:	05/31/2017	Run No: 344570					
SampleType: LCS	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243390	Analysis Date:	06/02/2017	Seq No: 7559944					
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual											
Antimony	0.1049	0.00600	0.1000		105	80	120				
Arsenic	0.09720	0.0100	0.1000	0.0003020	96.9	80	120				
Barium	0.1059	0.0200	0.1000	0.0001990	106	80	120				
Beryllium	0.1004	0.00400	0.1000		100	80	120				
Cadmium	0.1004	0.00500	0.1000		100	80	120				
Chromium	0.1114	0.0200	0.1000	0.004256	107	80	120				
Cobalt	0.09718	0.0500	0.1000		97.2	80	120				
Copper	0.09508	0.0200	0.1000	0.001508	93.6	80	120				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID: LCS-243390	Client ID:	Units: mg/L	Prep Date: 05/31/2017	Run No: 344570							
SampleType: LCS	TestCode: APPENDIX I METALS	BatchID: 243390	Analysis Date: 06/02/2017	Seq No: 7559944							
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Lead	0.1015	0.0100	0.1000		102	80	120				
Nickel	0.1033	0.0400	0.1000	0.002346	101	80	120				
Selenium	0.09930	0.0500	0.1000		99.3	80	120				
Silver	0.01025	0.00500	0.0100	0.00005200	102	80	120				
Thallium	0.1003	0.00200	0.1000		100	80	120				
Vanadium	0.09813	0.0500	0.1000	0.0004270	97.7	80	120				
Zinc	0.1082	0.0200	0.1000	0.003554	105	80	120				

Sample ID: 1705Q20-006IMS	Client ID:	Units: mg/L	Prep Date: 05/31/2017	Run No: 344570							
SampleType: MS	TestCode: APPENDIX I METALS	BatchID: 243390	Analysis Date: 06/02/2017	Seq No: 7559947							
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1029	0.00600	0.1000	0.0008790	102	75	125				
Arsenic	0.09026	0.0100	0.1000	0.0005500	89.7	75	125				
Barium	0.2064	0.0200	0.1000	0.1040	102	75	125				
Beryllium	0.09809	0.00400	0.1000		98.1	75	125				
Cadmium	0.09740	0.00500	0.1000	0.0003680	97.0	75	125				
Chromium	0.1008	0.0200	0.1000	0.001539	99.3	75	125				
Cobalt	0.1025	0.0500	0.1000	0.01097	91.5	75	125				
Copper	0.08859	0.0200	0.1000	0.002790	85.8	75	125				
Lead	0.1018	0.0100	0.1000	0.0008580	101	75	125				
Nickel	0.1040	0.0400	0.1000	0.01205	92.0	75	125				
Selenium	0.09003	0.0500	0.1000	0.0003690	89.7	75	125				
Silver	0.009767	0.00500	0.0100	0.00006400	97.0	75	125				
Thallium	0.1013	0.00200	0.1000	0.0007370	101	75	125				
Vanadium	0.09545	0.0500	0.1000		95.4	75	125				
Zinc	0.09775	0.0200	0.1000	0.004953	92.8	75	125				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	1705Q20-006IMSD	Client ID:		TestCode:	APPENDIX I METALS	SW6020B	Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570
Sample Type:	MSD	BatchID:	243390	Analysis Date:	06/02/2017	Seq No:	7559949					
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual	
Antimony	0.1011	0.00600	0.1000	0.0008790	100	75	125	0.1029	1.76	20		
Arsenic	0.08511	0.0100	0.1000	0.0005500	84.6	75	125	0.09026	5.87	20		
Barium	0.2115	0.0200	0.1000	0.1040	108	75	125	0.2064	2.44	20		
Beryllium	0.09513	0.00400	0.1000		95.1	75	125	0.09809	3.06	20		
Cadmium	0.09516	0.00500	0.1000	0.0003680	94.8	75	125	0.09740	2.33	20		
Chromium	0.09581	0.0200	0.1000	0.001539	94.3	75	125	0.1008	5.08	20		
Cobalt	0.09885	0.0500	0.1000	0.01097	87.9	75	125	0.1025	3.63	20		
Copper	0.08345	0.0200	0.1000	0.002790	80.7	75	125	0.08859	5.98	20		
Lead	0.1042	0.0100	0.1000	0.0008580	103	75	125	0.1018	2.33	20		
Nickel	0.09845	0.0400	0.1000	0.01205	86.4	75	125	0.1040	5.48	20		
Selenium	0.08619	0.0500	0.1000	0.0003690	85.8	75	125	0.09003	4.36	20		
Silver	0.009144	0.00500	0.0100	0.00006400	90.8	75	125	0.009767	6.59	20		
Thallium	0.1049	0.00200	0.1000	0.0007370	104	75	125	0.1013	3.49	20		
Vanadium	0.09432	0.0500	0.1000		94.3	75	125	0.09545	1.19	20		
Zinc	0.09047	0.0200	0.1000	0.004953	85.5	75	125	0.09775	7.74	20		

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank	
	BRL	Below reporting limit		E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit		N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit		S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243457

Sample ID:	MB-243457	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MBLK	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557558
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	BRL	0.00020									
Sample ID:	LCS-243457	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	LCS	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557559
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.003802	0.00020	0.0040		95.1	80	120				
Sample ID:	1705P20-002BMS	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MS	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557561
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.003802	0.00020	0.0040		95.1	70	130				
Sample ID:	1705P20-002BMSD	Client ID:				Units:	mg/L	Prep Date:	06/01/2017	Run No:	344485
SampleType:	MSD	TestCode:	Mercury, Total	SW7470A		BatchID:	243457	Analysis Date:	06/01/2017	Seq No:	7557562
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.003868	0.00020	0.0040		96.7	70	130	0.003802	1.72	20	

Qualifiers: > Greater than Result value
 BRL Below reporting limit
 J Estimated value detected below Reporting Limit
 Rpt Lim Reporting Limit

< Less than Result value
 E Estimated (value above quantitation range)
 N Analyte not NELAC certified
 S Spike Recovery outside limits due to matrix

B Analyte detected in the associated method blank
 H Holding times for preparation or analysis exceeded
 R RPD outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID:	MB-243483	Client ID:		TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	Units:	ug/L	Prep Date:	05/31/2017	Run No:	344328	
Sample Type:	MBLK					BatchID:	243483	Analysis Date:	05/31/2017	Seq No:	7556038	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1,1,2-Tetrachloroethane		BRL	5.0									
1,1,1-Trichloroethane		BRL	5.0									
1,1,2,2-Tetrachloroethane		BRL	5.0									
1,1,2-Trichloroethane		BRL	5.0									
1,1-Dichloroethane		BRL	5.0									
1,1-Dichloroethene		BRL	5.0									
1,2,3-Trichloropropane		BRL	5.0									
1,2-Dichlorobenzene		BRL	5.0									
1,2-Dichloroethane		BRL	5.0									
1,2-Dichloropropane		BRL	5.0									
1,4-Dichlorobenzene		BRL	5.0									
2-Butanone		BRL	50									
2-Hexanone		BRL	10									
4-Methyl-2-pentanone		BRL	10									
Acetone		BRL	50									
Acrylonitrile		BRL	5.0									
Benzene		BRL	5.0									
Bromoform		BRL	5.0									
Bromochloromethane		BRL	5.0									
Bromodichloromethane		BRL	5.0									
Bromoform		BRL	5.0									
Bromomethane		BRL	5.0									
Carbon disulfide		BRL	5.0									
Carbon tetrachloride		BRL	5.0									
Chlorobenzene		BRL	5.0									
Chloroethane		BRL	10									
Chloroform		BRL	5.0									
Chloromethane		BRL	10									

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank	
	BRL	Below reporting limit		E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit		N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit		S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID:	MB-243483	Client ID:		TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	Units:	ug/L	Prep Date:	05/31/2017	Run No:	344328
SampleType:	MBLK		<th></th> <th></th> <th>BatchID:</th> <td>243483</td> <th>Analysis Date:</th> <td>05/31/2017</td> <th>Seq No:</th> <td>7556038</td>			BatchID:	243483	Analysis Date:	05/31/2017	Seq No:	7556038
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
cis-1,2-Dichloroethene	BRL	5.0									
cis-1,3-Dichloropropene	BRL	5.0									
Dibromochloromethane	BRL	5.0									
Dibromomethane	BRL	5.0									
Ethylbenzene	BRL	5.0									
Iodomethane	BRL	10									
Methylene chloride	BRL	5.0									
Styrene	BRL	5.0									
Tetrachloroethene	BRL	5.0									
Toluene	BRL	5.0									
trans-1,2-Dichloroethene	BRL	5.0									
trans-1,3-Dichloropropene	BRL	5.0									
trans-1,4-Dichloro-2-butene	BRL	10									
Trichloroethene	BRL	5.0									
Trichlorofluoromethane	BRL	5.0									
Vinyl acetate	BRL	10									
Vinyl chloride	BRL	2.0									
Xylenes, Total	BRL	10									
Sur: 4-Bromofluorobenzene	46.71	0	50.00		93.4	66.1	129				
Sur: Dibromofluoromethane	46.93	0	50.00		93.9	83.6	123				
Sur: Toluene-d8	48.85	0	50.00		97.7	81.8	118				

Sample ID:	LCS-243483	Client ID:		TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	Units:	ug/L	Prep Date:	05/31/2017	Run No:	344328
SampleType:	LCS		<th></th> <th></th> <th>BatchID:</th> <td>243483</td> <th>Analysis Date:</th> <td>05/31/2017</td> <th>Seq No:</th> <td>7556037</td>			BatchID:	243483	Analysis Date:	05/31/2017	Seq No:	7556037
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1-Dichloroethene	18.15	5.0	20.00		90.8	68	139				
Benzene	18.91	5.0	20.00		94.6	74	125				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank	
	BRL	Below reporting limit		E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit		N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit		S	Spike Recovery outside limits due to matrix		

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID: LCS-243483	Client ID:				Units: ug/L	Prep Date: 05/31/2017	Run No: 344328				
SampleType: LCS	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7556037				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

Chlorobenzene	19.22	5.0	20.00		96.1	75.7	123				
Toluene	18.87	5.0	20.00		94.4	75.9	126				
Trichloroethene	19.44	5.0	20.00		97.2	70.6	129				
Sur: 4-Bromofluorobenzene	48.08	0	50.00		96.2	66.1	129				
Sur: Dibromofluoromethane	49.39	0	50.00		98.8	83.6	123				
Sur: Toluene-d8	49.22	0	50.00		98.4	81.8	118				

Sample ID: 1705Q21-001AMS	Client ID:				Units: ug/L	Prep Date: 05/31/2017	Run No: 344413				
SampleType: MS	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7555545				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

1,1-Dichloroethene	54.45	5.0	50.00		109	64.3	149				
Benzene	53.03	5.0	50.00		106	71.6	132				
Chlorobenzene	54.14	5.0	50.00		108	73.1	126				
Toluene	53.26	5.0	50.00		107	72.5	135				
Trichloroethene	52.13	5.0	50.00		104	70.2	132				
Sur: 4-Bromofluorobenzene	46.26	0	50.00		92.5	66.1	129				
Sur: Dibromofluoromethane	46.19	0	50.00		92.4	83.6	123				
Sur: Toluene-d8	48.57	0	50.00		97.1	81.8	118				

Sample ID: 1705Q21-001AMSD	Client ID:				Units: ug/L	Prep Date: 05/31/2017	Run No: 344413				
SampleType: MSD	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7555546				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual

1,1-Dichloroethene	49.16	5.0	50.00		98.3	64.3	149	54.45	10.2	30.8	
Benzene	51.53	5.0	50.00		103	71.6	132	53.03	2.87	20.7	
Chlorobenzene	52.72	5.0	50.00		105	73.1	126	54.14	2.66	26.6	
Toluene	51.57	5.0	50.00		103	72.5	135	53.26	3.22	23.2	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243483

Sample ID: 1705Q21-001AMSD	Client ID:				Units: ug/L	Prep Date: 05/31/2017	Run No: 344413				
SampleType: MSD	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243483	Analysis Date: 05/31/2017	Seq No: 7555546				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Trichloroethene	49.43	5.0	50.00		98.9	70.2	132	52.13	5.32	27.7	
Surr: 4-Bromofluorobenzene	46.48	0	50.00		93.0	66.1	129	46.26	0	0	
Surr: Dibromofluoromethane	46.38	0	50.00		92.8	83.6	123	46.19	0	0	
Surr: Toluene-d8	48.46	0	50.00		96.9	81.8	118	48.57	0	0	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: 243660

Sample ID:	MB-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MBLK	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566603
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	BRL	0.00020									
Sample ID:	LCS-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	LCS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566606
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.004880	0.00020	0.0050		97.6	80	120				
Sample ID:	1705Q20-002AMS	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566608
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005527	0.00020	0.0050	0.0001346	108	70	130				
Sample ID:	1705Q20-002AMSD	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MSD	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566609
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005814	0.00020	0.0050	0.0001346	114	70	130	0.005527	5.06	20	

Qualifiers: > Greater than Result value

BRL Below reporting limit

J Estimated value detected below Reporting Limit

Rpt Lim Reporting Limit

< Less than Result value

E Estimated (value above quantitation range)

N Analyte not NELAC certified

S Spike Recovery outside limits due to matrix

B Analyte detected in the associated method blank

H Holding times for preparation or analysis exceeded

R RPD outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q25

ANALYTICAL QC SUMMARY REPORT

BatchID: R344266

Sample ID:	MB-R344266	Client ID:		Units:	mg/L	Prep Date:		Run No:	344266		
SampleType:	MBLK	TestCode:	Inorganic Anions by IC E300.0	BatchID:	R344266	Analysis Date:	05/26/2017	Seq No:	7555314		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	BRL	0.200									
Sample ID:	LCS-R344266	Client ID:		Units:	mg/L	Prep Date:		Run No:	344266		
SampleType:	LCS	TestCode:	Inorganic Anions by IC E300.0	BatchID:	R344266	Analysis Date:	05/26/2017	Seq No:	7555320		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	4.778	0.200	5.000		95.6	90	110				
Sample ID:	1705Q25-006DMS	Client ID:	TRIP BLANK	Units:	mg/L	Prep Date:		Run No:	344266		
SampleType:	MS	TestCode:	Inorganic Anions by IC E300.0	BatchID:	R344266	Analysis Date:	05/26/2017	Seq No:	7555352		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	4.747	0.200	5.000		94.9	90	110				
Sample ID:	1705Q25-006DMSD	Client ID:	TRIP BLANK	Units:	mg/L	Prep Date:		Run No:	344266		
SampleType:	MSD	TestCode:	Inorganic Anions by IC E300.0	BatchID:	R344266	Analysis Date:	05/26/2017	Seq No:	7555353		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	4.831	0.200	5.000		96.6	90	110	4.747	1.75	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Phase II/IV LF
 Workorder: 1705Q2S

ANALYTICAL QC SUMMARY REPORT

BatchID: R344522

Sample ID:	MB-R344522	Client ID:				Units:	mg/L	Prep Date:	Run No: 344522			
SampleType:	MLBK	TestCode:	Inorganic Anions by IC	E300.0		BatchID:	R344522	Analysis Date:	06/01/2017	Seq No:	7558942	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride		BRL	0.200									
Sample ID:	LCS-R344522	Client ID:				Units:	mg/L	Prep Date:	Run No: 344522			
SampleType:	LCS	TestCode:	Inorganic Anions by IC	E300.0		BatchID:	R344522	Analysis Date:	06/01/2017	Seq No:	7558941	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride		4.985	0.200	5.000		99.7	90	110				
Sample ID:	1705P77-032DMS	Client ID:	SWC-2				Units:	mg/L	Prep Date:	Run No: 344522		
SampleType:	MS	TestCode:	Inorganic Anions by IC	E300.0		BatchID:	R344522	Analysis Date:	06/01/2017	Seq No:	7558951	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride		5.365	0.200	5.000	0.1253	105	90	110				
Sample ID:	1705P77-038CMS	Client ID:	SWC-9				Units:	mg/L	Prep Date:	Run No: 344522		
SampleType:	MS	TestCode:	Inorganic Anions by IC	E300.0		BatchID:	R344522	Analysis Date:	06/01/2017	Seq No:	7558963	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride		5.238	- 0.200	5.000	0.09905	103	90	110				
Sample ID:	1705P77-032DMSD	Client ID:	SWC-2				Units:	mg/L	Prep Date:	Run No: 344522		
SampleType:	MSD	TestCode:	Inorganic Anions by IC	E300.0		BatchID:	R344522	Analysis Date:	06/01/2017	Seq No:	7558952	
Analyte		Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride		5.335	0.200	5.000	0.1253	104	90	110	5.365	0.552	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

APPENDIX C

**LOUDON COUNTY
COMPLIANCE WELL
MONITORING WELL #1**

| Parameter | Non-Regulatory | | In-Regulation | | Total | | WQA-Avg | | WQD-Avg | | WQD-17 | | WQD-18 | | WQD-19 | | WQD-20 | | WQD-21 | | WQD-22 | | WQD-23 | | WQD-24 | | WQD-25 | | WQD-26 | | WQD-27 | | WQD-28 | | WQD-29 | | WQD-30 | | WQD-31 | | WQD-32 | | WQD-33 | | WQD-34 | | WQD-35 | | WQD-36 | | WQD-37 | | WQD-38 | | WQD-39 | | WQD-40 | | WQD-41 | | WQD-42 | | WQD-43 | | WQD-44 | | WQD-45 | | WQD-46 | | WQD-47 | | WQD-48 | | WQD-49 | | WQD-50 | | WQD-51 | | WQD-52 | | WQD-53 | | WQD-54 | | WQD-55 | | WQD-56 | | WQD-57 | | WQD-58 | | WQD-59 | | WQD-60 | | WQD-61 | | WQD-62 | | WQD-63 | | WQD-64 | | WQD-65 | | WQD-66 | | WQD-67 | | WQD-68 | | WQD-69 | | WQD-70 | | WQD-71 | | WQD-72 | | WQD-73 | | WQD-74 | | WQD-75 | | WQD-76 | | WQD-77 | | WQD-78 | | WQD-79 | | WQD-80 | | WQD-81 | | WQD-82 | | WQD-83 | | WQD-84 | | WQD-85 | | WQD-86 | | WQD-87 | | WQD-88 | | WQD-89 | | WQD-90 | | WQD-91 | | WQD-92 | | WQD-93 | | WQD-94 | | WQD-95 | | WQD-96 | | WQD-97 | | WQD-98 | | WQD-99 | | WQD-100 | | WQD-101 | | WQD-102 | | WQD-103 | | WQD-104 | | WQD-105 | | WQD-106 | | WQD-107 | | WQD-108 | | WQD-109 | | WQD-110 | | WQD-111 | | WQD-112 | | WQD-113 | | WQD-114 | | WQD-115 | | WQD-116 | | WQD-117 | | WQD-118 | | WQD-119 | | WQD-120 | | WQD-121 | | WQD-122 | | WQD-123 | | WQD-124 | | WQD-125 | | WQD-126 | | WQD-127 | | WQD-128 | | WQD-129 | | WQD-130 | | WQD-131 | | WQD-132 | | WQD-133 | | WQD-134 | | WQD-135 | | WQD-136 | | WQD-137 | | WQD-138 | | WQD-139 | | WQD-140 | | WQD-141 | | WQD-142 | | WQD-143 | | WQD-144 | | WQD-145 | | WQD-146 | | WQD-147 | | WQD-148 | | WQD-149 | | WQD-150 | | WQD-151 | | WQD-152 | | WQD-153 | | WQD-154 | | WQD-155 | | WQD-156 | | WQD-157 | | WQD-158 | | WQD-159 | | WQD-160 | | WQD-161 | | WQD-162 | | WQD-163 | | WQD-164 | | WQD-165 | | WQD-166 | | WQD-167 | | WQD-168 | | WQD-169 | | WQD-170 | | WQD-171 | | WQD-172 | | WQD-173 | | WQD-174 | | WQD-175 | | WQD-176 | | WQD-177 | | WQD-178 | | WQD-179 | | WQD-180 | | WQD-181 | | WQD-182 | | WQD-183 | | WQD-184 | | WQD-185 | | WQD-186 | | WQD-187 | | WQD-188 | | WQD-189 | | WQD-190 | | WQD-191 | | WQD-192 | | WQD-193 | | WQD-194 | | WQD-195 | | WQD-196 | | WQD-197 | | WQD-198 | | WQD-199 | | WQD-200 | | WQD-201 | | WQD-202 | | WQD-203 | | WQD-204 | | WQD-205 | | WQD-206 | | WQD-207 | | WQD-208 | | WQD-209 | | WQD-210 | | WQD-211 | | WQD-212 | | WQD-213 | | WQD-214 | | WQD-215 | | WQD-216 | | WQD-217 | | WQD-218 | | WQD-219 | | WQD-220 | | WQD-221 | | WQD-222 | | WQD-223 | | WQD-224 | | WQD-225 | | WQD-226 | | WQD-227 | | WQD-228 | | WQD-229 | | WQD-230 | | WQD-231 | | WQD-232 | | WQD-233 | | WQD-234 | | WQD-235 | | WQD-236 | | WQD-237 | | WQD-238 | | WQD-239 | | WQD-240 | | WQD-241 | | WQD-242 | | WQD-243 | | WQD-244 | | WQD-245 | | WQD-246 | | WQD-247 | | WQD-248 | | WQD-249 | | WQD-250 | | WQD-251 | | WQD-252 | | WQD-253 | | WQD-254 | | WQD-255 | | WQD-256 | | WQD-257 | | WQD-258 | | WQD-259 | | WQD-260 | | WQD-261 | | WQD-262 | | WQD-263 | | WQD-264 | | WQD-265 | | WQD-266 | | WQD-267 | | WQD-268 | | WQD-269 | | WQD-270 | | WQD-271 | | WQD-272 | | WQD-273 | | WQD-274 | | WQD-275 | | WQD-276 | | WQD-277 | | WQD-278 | | WQD-279 | | WQD-280 | | WQD-281 | | WQD-282 | | WQD-283 | | WQD-284 | | WQD-285 | | WQD-286 | | WQD-287 | | WQD-288 | | WQD-289 | | WQD-290 | | WQD-291 | | WQD-292 | | WQD-293 | | WQD-294 | | WQD-295 | | WQD-296 | | WQD-297 | | WQD-298 | | WQD-299 | | WQD-300 | | WQD-301 | | WQD-302 | | WQD-303 | | WQD-304 | | WQD-305 | | WQD-306 | | WQD-307 | | WQD-308 | | WQD-309 | | WQD-310 | | WQD-311 | | WQD-312 | | WQD-313 | | WQD-314 | | WQD-315 | | WQD-316 | | WQD-317 | | WQD-318 | | WQD-319 | | WQD-320 | | WQD-321 | | WQD-322 | | WQD-323 | | WQD-324 | | WQD-325 | | WQD-326 | | WQD-327 | | WQD-328 | | WQD-329 | | WQD-330 | | WQD-331 | | WQD-332 | | WQD-333 | | WQD-334 | | WQD-335 | | WQD-336 | | WQD-337 | | WQD-338 | | WQD-339 | | WQD-340 | | WQD-341 | | WQD-342 | | WQD-343 | | WQD-344 | | WQD-345 | | WQD-346 | | WQD-347 | | WQD-348 | | WQD-349 | | WQD-350 | | WQD-351 | | WQD-352 | | WQD-353 | | WQD-354 | | WQD-355 | | WQD-356 | | WQD-357 | | WQD-358 | | WQD-359 | | WQD-360 | | WQD-361 | | WQD-362 | | WQD-363 | | WQD-364 | | WQD-365 | | WQD-366 | | WQD-367 | | WQD-368 | | WQD-369 | | WQD-370 | | WQD-371 | | WQD-372 | | WQD-373 | | WQD-374 | | WQD-375 | | WQD-376 | | WQD-377 | | WQD-378 | | WQD-379 | | WQD-380 | | WQD-381 | | WQD-382 | | WQD-383 | | WQD-384 | | WQD-385 | | WQD-386 | | WQD-387 | | WQD-388 | | WQD-389 | | WQD-390 | | WQD-391 | | WQD-392 | | WQD-393 | | WQD-394 | | WQD-395 | | WQD-396 | | WQD-397 | | WQD-398 | | WQD-399 | | WQD-400 | | WQD-401 | | WQD-402 | | WQD-403 | | WQD-404 | | WQD-405 | | WQD-406 | | WQD-407 | | WQD-408 | | WQD-409 | | WQD-410 | | WQD-411 | | WQD-412 | | WQD-413 | | WQD-414 | | WQD-415 | | WQD-416 | | WQD-417 | | WQD-418 | | WQD-419 | | WQD-420 | | WQD-421 | | WQD-422 | | WQD-423 | | WQD-424 | | WQD-425 | | WQD-426 | | WQD-427 | | WQD-428 | | WQD-429 | | WQD-430 | | WQD-431 | | WQD-432 | | WQD-433 | | WQD-434 | | WQD-435 | | WQD-436 | | WQD-437 | | WQD-438 | | WQD-439 | | WQD-440 | | WQD-441 | | WQD-442 | | WQD-443 | | WQD-444 | | WQD-445 | | WQD-446 | | WQD-447 | | WQD-448 | | WQD-449 | | WQD-450 | | WQD-451 | | WQD-452 | | WQD-453 | | WQD-454 | | WQD-455 | | WQD-456 | | WQD-457 | | WQD-458 | | WQD-459 | | WQD-460 | | WQD-461 | | WQD-462 | | WQD-463 | | WQD-464 | | WQD-465 | | WQD-466 | | WQD-467 | | WQD-468 | | WQD-469 | | WQD-470 | | WQD-471 | | WQD-472 | | WQD-473 | | WQD-474 | | WQD-475 | | WQD-476 | | WQD-477 | | WQD-478 | | WQD-479 | | WQD-480 | | WQD-481 | | WQD-482 | | WQD-483 | | WQD-484 | | WQD-485 | | WQD-486 | | WQD-487 | | WQD-488 | | WQD-489 | | WQD-490 | | WQD-491 | | WQD-492 | | WQD-493 | | WQD-494 | | WQD-495 | | WQD-496 | | WQD-497 | | WQD-498 | | WQD-499 | | WQD-500 | | WQD-501 | | WQD-502 | | WQD-503 | | WQD-504 | | WQD-505 | | WQD-506 | | WQD-507 | | WQD-508 | | WQD-509 | | WQD-510 | | WQD-511 | | WQD-512 | | WQD-513 | | WQD-514 | | WQD-515 | | WQD-516 | | WQD-517 | | WQD-518 | | WQD-519 | | WQD-520 | | WQD-521 | | WQD-522 | | WQD-523 | | WQD-524 | | WQD-525 | | WQD-526 | | WQD-527 | |
<th colspan="2
| --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- | --- |

**LOUDON COUNTY
COMPLIANCE WELL
MONITORING WELL #1A**

INORGANIC	TN REGULATORY LIMITS	1-17-07	3-22-07	5-15-07	6-14-07	11-1-07	3-27-08	10-13-08	4-2-09	10-2-09	4-7-10	10-6-10	1-5-11	10-5-11	3-15-12	10-3-12	3-28-13	9-25-13	3-25-14	9-24-14	4-1-15	10-7-15	5-24-16	11-30-16	5-26-17	MW-1A AVG	MW-4R AVG.		
Antimony	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	6	1.5	5.81	5.86	
Arsenic	10	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	2.5	46.35	47.01		
Barium	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	500	1937.50	1543.27		
Beryllium	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	1	3.88	6.89	
Cadmium	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	1.25	4.84	4.98
Chromium	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	25	96.88	85.33	
Cobalt	6****	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	5.0	9.79	15.52	
Copper	800****	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	5.0	9.79	17.59	
Fluoride***	4	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.00	3.07	
Lead	115	50.0	50.0	50.0	50.0	50.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	15.0	3.75	20.36	38.07	
Mercury	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2.00	1.77	
Nickel	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	25	96.88	98.62	
Selenium	50	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10	10.00	12.17	
Silver	±100	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	2.5	48.02	39.21	
Thallium	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	0.5	1.94	3.03	
Vanadium	86****	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	5.0	9.79	21.41		
Zinc	6000****	39.0	20.0	22.9	20.0	23.2	20.0	31.4	20.0	20.0	35.2	20.0	20.0	30.5	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	40.1	10.0	23.32	196.26	

T = TREATMENT TECHNIQUE ACTION LEVEL

† = NATIONAL SECONDARY DRINKING WATER STANDARD

* PARAMETER NOT TESTED FOR

"RESAMPLE DATE

***ALL DATA IN UGL, EXCEPT FLUORIDE (MG/L)

*****EPA REGION 4 SCREENING LEVEL

**LOUDON COUNTY
COMPLIANCE WELL
MONITORING WELL #25**

*ALL DATA IN UG/L EXCEPT FLUORIDE (MG/L)

1 = TREATMENT TECHNIQUE ACTION LEVEL

† = NATIONAL SECONDARY DRINKING WATER STANDARD

EPA REGION 4 SCREENING LEVEL

APPENDIX D

GROUNDWATER DATA

Matlock Bend Landfill

May 25, 2017

Well No.	Elev. Of TOC	Depth to GW (ft below TOC)	Water Elevation	Contour Elevation	Distance	Hydraulic Conductivity	Effective Porosity (n)	Hydraulic Gradient	Average Linear Velocity		Directions
									ft/min	ft/day	
MW-01	830.87	3.82	827.05	825	25	4.70E-06	0.18	8.20E-02	2.14E-06	3.08E-03	S
MW-1A*	805.13	7.63	797.50	800	35	3.93E-06	0.18	7.14E-02	1.56E-06	2.25E-03	S
MW-02	825.20	7.33	817.87	815	40	5.90E-06	0.18	7.18E-02	2.35E-06	3.39E-03	S
MW-03	867.86	15.03	852.83	855	80	1.20E-05	0.18	2.71E-02	1.81E-06	2.60E-03	SW
MW-4R**	992.32	95.53	896.79	895	60	1.90E-05	0.18	2.98E-02	3.15E-06	4.53E-03	NW
MW-05	936.84	83.82	853.02	855	60	2.20E-05	0.18	3.30E-02	4.03E-06	5.81E-03	NW

*-The hydraulic conductivity for MW-1A is an average from monitoring wells MW-01, MW-02 and MW-03.

**-The hydraulic conductivity for MW-4R is from MW-04.

APPENDIX E


LEGEND:

	PROPERTY BOUNDARY
	WATER TABLE CONTOURS (INFERRED)
	AERIAL INDEX CONTOUR
	AERIAL CONTOUR
	ROAD
	GROUNDWATER MONITORING WELL
	GROUNDWATER FLOW DIRECTION
	PERMITTED LIMITS OF WASTE

NOTES:


- POTENIOMETRIC CONTOURS DEVELOPED FROM WATER ELEVATIONS TAKEN MAY 25, 2017.
- TOPOGRAPHIC CONTOURS SHOWN WERE PROVIDED BY SOUTHERN RESOURCES MAPPING CORP., NORTHPORT, ALABAMA, PHOTOS DATED AUGUST 25, 2015 AND SEPTEMBER 15, 2016.

G.W. WELL NO.	WATER ELEV.
MW-01	827.05
MW-1A	797.50
MW-02	817.87
MW-03	852.83
MW-4R	896.79
MW-05	853.02



DATE	DRWN	CHKD

PHASE I/II/IV 1ST SEMI- ANNUAL 2017
POTENIOMETRIC CONTOUR MAP
MATLOCK BEND LANDFILL
LOUDON COUNTY, TENNESSEE



SCALE: 1"=500
DATE: 7/20/17
DRAWN BY: RH
CHECKED BY: RH
APPROVED BY: RV
FILE: 1710-51
DOB NO 200-1710

S-1

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243443

Sample ID:	MB-243443	Client ID:				Units:	mg/L	Prep Date:	05/31/2017	Run No:	344363
Sample Type:	MBLK	TestCode:	Nitrogen, Ammonia (as N) E350.1			BatchID:	243443	Analysis Date:	05/31/2017	Seq No:	7554489
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	BRL	0.200									
Sample ID:	LCS-243443	Client ID:				Units:	mg/L	Prep Date:	05/31/2017	Run No:	344363
Sample Type:	LCS	TestCode:	Nitrogen, Ammonia (as N) E350.1			BatchID:	243443	Analysis Date:	05/31/2017	Seq No:	7554490
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.280	0.200	5.000		106	90	110				
Sample ID:	1705O89-012AMS	Client ID:				Units:	mg/L	Prep Date:	05/31/2017	Run No:	344363
Sample Type:	MS	TestCode:	Nitrogen, Ammonia (as N) E350.1			BatchID:	243443	Analysis Date:	05/31/2017	Seq No:	7554493
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	6.170	0.200	5.000	1.700	89.4	90	110				S
Sample ID:	1705P17-001CMS	Client ID:				Units:	mg/L	Prep Date:	05/31/2017	Run No:	344363
Sample Type:	MS	TestCode:	Nitrogen, Ammonia (as N) E350.1			BatchID:	243443	Analysis Date:	05/31/2017	Seq No:	7554495
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.220	0.200	5.000		104	90	110				
Sample ID:	1705P17-001CMSD	Client ID:				Units:	mg/L	Prep Date:	05/31/2017	Run No:	344363
Sample Type:	MSD	TestCode:	Nitrogen, Ammonia (as N) E350.1			BatchID:	243443	Analysis Date:	05/31/2017	Seq No:	7554496
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Nitrogen, Ammonia (As N)	5.200	0.200	5.000		104	90	110	5.220	0.384	30	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243493

Sample ID: MB-243493	Client ID:		Units: mg/L	Prep Date: 06/01/2017	Run No: 344564
SampleType: MBLK	TestCode: Residue, Dissolved (TDS) by SM2540C		BatchID: 243493	Analysis Date: 06/01/2017	Seq No: 7559706
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC

Residue, Dissolved (TDS)	BRL	10									
--------------------------	-----	----	--	--	--	--	--	--	--	--	--

Sample ID: 1705Q20-001EDUP	Client ID:		Units: mg/L	Prep Date: 06/01/2017	Run No: 344564
SampleType: DUP	TestCode: Residue, Dissolved (TDS) by SM2540C		BatchID: 243493	Analysis Date: 06/01/2017	Seq No: 7559721
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC

Residue, Dissolved (TDS)	280.0	10									
								270.0	3.64	5	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santeck Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243607

Sample ID:	MB-243607	Client ID:		Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640		
SampleType:	MLBK	TestCode:	Cyanide SW9014	BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561664		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Cyanide, Total	BRL	0.010									
Sample ID:	LCS-243607	Client ID:		Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640		
SampleType:	LCS	TestCode:	Cyanide SW9014	BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561665		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Cyanide, Total	0.2390	0.010	0.2500		95.6	85	115				
Sample ID:	1705Q20-001GMS	Client ID:		Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640		
SampleType:	MS	TestCode:	Cyanide SW9014	BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561683		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Cyanide, Total	0.2730	0.010	0.2500		109	70	130				
Sample ID:	1705Q20-001GMSD	Client ID:		Units:	mg/L	Prep Date:	06/01/2017	Run No:	344640		
SampleType:	MSD	TestCode:	Cyanide SW9014	BatchID:	243607	Analysis Date:	06/01/2017	Seq No:	7561693		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Cyanide, Total	0.2830	0.010	0.2500		113	70	130	0.2730	3.60	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243633

Sample ID:	MB-243633	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771
Sample Type:	MLBK	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566789
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese	BRL	0.00500									
Sample ID:	LCS-243633	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771
Sample Type:	LCS	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566792
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese	0.08865	0.00500	0.1000		88.7	80	120				
Sample ID:	1705Q15-002DMS	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771
Sample Type:	MS	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566794
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese	0.1287	0.00500	0.1000	0.04800	80.7	75	125				
Sample ID:	1705Q15-002DMSD	Client ID:				Units:	mg/L	Prep Date:	06/05/2017	Run No:	344771
Sample Type:	MSD	TestCode:	Dissolved Metals by ICP/MS	SW6020B		BatchID:	243633	Analysis Date:	06/05/2017	Seq No:	7566795
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Manganese	0.1292	0.00500	0.1000	0.04800	81.2	75	125	0.1287	0.385	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243660

Sample ID:	MB-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MBLK	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566603
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	BRL	0.00020									
Sample ID:	LCS-243660	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	LCS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566606
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.004880	0.00020	0.0050		97.6	80	120				
Sample ID:	1705Q20-002AMS	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MS	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566608
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005527	0.00020	0.0050	0.0001346	108	70	130				
Sample ID:	1705Q20-002AMSD	Client ID:				Units:	mg/L	Prep Date:	06/06/2017	Run No:	344826
Sample Type:	MSD	TestCode:	Mercury, Total	SW7470A		BatchID:	243660	Analysis Date:	06/06/2017	Seq No:	7566609
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Mercury	0.005814	0.00020	0.0050	0.0001346	114	70	130	0.005527	5.06	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: R344266

Sample ID: MB-R344266	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MBLK	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7551989
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride BRL 1.00
 Fluoride BRL 0.200
 Nitrogen, Nitrate (As N) BRL 0.250
 Sulfate BRL 1.00

Sample ID: LCS-R344266	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: LCS	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7551988
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride 10.27 1.00 10.00 0.1782 101 90 110
 Fluoride 4.778 0.200 5.000 95.6 90 110
 Nitrogen, Nitrate (As N) 4.731 0.250 5.000 94.6 90 110
 Sulfate 25.54 1.00 25.00 0.3314 101 90 110

Sample ID: 1705Q20-010FMS	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MS	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552004
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride 10.75 1.00 10.00 0.3582 104 90 110
 Fluoride 4.747 0.200 5.000 94.9 90 110
 Nitrogen, Nitrate (As N) 4.638 0.250 5.000 92.8 90 110
 Sulfate 25.27 1.00 25.00 101 90 110

Sample ID: 1705Q20-010FMSD	Client ID:		Units: mg/L	Prep Date:	Run No: 344266
SampleType: MSD	TestCode: Inorganic Anions by IC	E300.0	BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552008
Analyte Result RPT Limit SPK value SPK Ref Val %REC Low Limit High Limit RPD Ref Val %RPD RPD Limit Qual					

Chloride 10.41 1.00 10.00 0.3582 101 90 110 10.75 3.17 20

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: R344266

Sample ID: 1705Q20-010FMSD	Client ID:				Units: mg/L	Prep Date:	Run No: 344266				
SampleType: MSD	TestCode: Inorganic Anions by IC E300.0				BatchID: R344266	Analysis Date: 05/26/2017	Seq No: 7552008				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Fluoride	4.831	0.200	5.000		96.6	90	110	4.747	1.75	20	
Nitrogen, Nitrate (As N)	4.698	0.250	5.000		94.0	90	110	4.638	1.28	20	
Sulfate	25.45	1.00	25.00		102	90	110	25.27	0.699	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: R344553

Sample ID:	MB-R344553	Client ID:				Units:	mg/L	Prep Date:	Run No: 344553		
SampleType:	MLBK	TestCode:	Chemical Oxygen Demand (COD)	E410.4		BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559642
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	BRL	10.0									
Sample ID:	LCS-R344553	Client ID:				Units:	mg/L	Prep Date:	Run No: 344553		
SampleType:	LCS	TestCode:	Chemical Oxygen Demand (COD)	E410.4		BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559643
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	538.3	10.0	500.0		108	90	110				
Sample ID:	1705Q15-002FMS	Client ID:				Units:	mg/L	Prep Date:	Run No: 344553		
SampleType:	MS	TestCode:	Chemical Oxygen Demand (COD)	E410.4		BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559664
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	387.2	12.5	375.0		103	90	110				
Sample ID:	1705R04-001CMS	Client ID:				Units:	mg/L	Prep Date:	Run No: 344553		
SampleType:	MS	TestCode:	Chemical Oxygen Demand (COD)	E410.4		BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559666
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	647.1	12.5	375.0	257.2	104	90	110				
Sample ID:	1705Q15-002FMSD	Client ID:				Units:	mg/L	Prep Date:	Run No: 344553		
SampleType:	MSD	TestCode:	Chemical Oxygen Demand (COD)	E410.4		BatchID:	R344553	Analysis Date:	06/02/2017	Seq No:	7559665
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chemical Oxygen Demand	395.8	12.5	375.0		106	90	110	387.2	2.17	30	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santeck Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: R344665

Sample ID:	MB-R344665	Client ID:				Units:	mg/L	Prep Date:	Run No: 344665		
SampleType:	MBLK	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344665	Analysis Date:	05/31/2017	Seq No:	7562367
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	BRL	1.00									
Sample ID:	LCS-R344665	Client ID:				Units:	mg/L	Prep Date:	Run No: 344665		
SampleType:	LCS	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344665	Analysis Date:	05/31/2017	Seq No:	7562366
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	24.68	1.00	25.00	0.3004	97.5	90	110				
Sample ID:	1705Q05-001AMS	Client ID:				Units:	mg/L	Prep Date:	Run No: 344665		
SampleType:	MS	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344665	Analysis Date:	05/31/2017	Seq No:	7562389
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	25.05	1.00	25.00		100	80	120				
Sample ID:	1705Q05-001AMSD	Client ID:				Units:	mg/L	Prep Date:	Run No: 344665		
SampleType:	MSD	TestCode:	Total Organic Carbon (TOC) by SM5310B			BatchID:	R344665	Analysis Date:	05/31/2017	Seq No:	7562390
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Organic Carbon, Total	25.08	1.00	25.00		100	80	120	25.05	0.120	20	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

APPENDIX F

LEACHATE FIELD LOG

FIELD SAMPLING LOG		WELL NO: Leachate
Location: Loudon County Landfill		Site: Matlock Bend
Client/Operator: Santek Waste Services, Inc.		Project No:
Purge Start: (Date) <u>5/25/17</u> (Time) <u>1345</u>	Purge End: (Date) <u>—</u> (Time) <u>—</u>	
Purged by: <u>RKerr</u>		
Depth Measurement Ref. Point* N/A ft		Well Casing ID: N/A

Equipment Used to Measure (Make, Model, etc)

DTW N/A pH YSI Cond. YSI T° YSI

Measure Well TD: N/A (-) Orig. DTW: N/A (=) Wtr. Col. Thick: N/A

(x) 2"=0.163 Gals./ft. (=) N/A Gals./Csg. Vol. (x) 3 Csg. Vol. (=) N/A Total Purge Gals.

GW elev. Ref. N/A ft. (-) DTW: N/A ft. = N/A ft.

Purge/Sample Method: Directly into bottles

Decon. Method: Field Appendix B

Purge Water Containerized? (No)

Average Purge Rate: N/A (gallons per minute)

Weather: cloudy (70 °F)

Actual Time	Vol. Purged (Gallons)	pH	SC (uS/cm)	Temp (°C)	Turbidity (NTU)		Comments
1345	—	7.60	9175	21.8	116		black, odor

Turbidity at metals sample collection: 116 NTU's

Comments: black, odor

*All Depths in Feet below Ref. Point on Wellhead, Generally Top of Casing (TOC) DTW= Depth to Water

LEACHATE ANALYTICAL RESULTS



ANALYTICAL ENVIRONMENTAL SERVICES, INC.

June 09, 2017

Robert Hudson
Santek Environmental Inc.
650 25th Street NW, Suite 100
Cleveland TN 37311

RE: Loudon County (Matlock Bend) Landfill

Dear Robert Hudson:

Order No: 1705Q24

Analytical Environmental Services, Inc. received 1 samples on May 26, 2017 2:41 pm for the analyses presented in following report.

No problems were encountered during the analyses. Additionally, all results for the associated Quality Control samples were within EPA and/or AES established limits. Any discrepancies associated with the analyses contained herein will be noted and submitted in the form of a project Case Narrative.

AES's accreditations are as follows:

-NELAC/Florida State Laboratory ID E87582 for analysis of Non-Potable Water, Solid & Chemical Materials, and Drinking Water Microbiology, effective 07/01/16-06/30/17.

State of Georgia, Department of Natural Resources ID #800 for analysis of Drinking Water Metals, effective 07/01/16-06/30/17 and Total Coliforms and E. coli, effective 04/25/17-04/24/20.

-NELAC/Louisiana Agency Interest No. 100818 for or analysis of Non-Potable Water and Solid & Chemical Materials, effective 07/01/16-06/30/17.

-AIHA-LAP, LLC Laboratory ID: 100671 for Industrial Hygiene samples (Organics, Metals, PCM Asbestos, Gravimetric), Environmental Lead (Paint, Soil, Dust Wipes, Air), and Environmental Microbiology (Fungal) Direct Examination, effective until 09/01/17.

These results relate only to the items tested. This report may only be reproduced in full.

If you have any questions regarding these test results, please feel free to call.

Sincerely,

Chris Pafford
Project Manager



ANALYTICAL ENVIRONMENTAL SERVICES, INC

3785 Presidential Parkway, Atlanta GA 30340-3704

AES TEL.: (770) 457-8177 / TOLL-FREE (800) 972-4889 / FAX: (770) 457-8188

CHAIN OF CUSTODY

Work Order: 1705Q24

Date: 5-26-17 Page 1 of 1

COMPANY: Santel Environmental Inc.		ADDRESS: 650 25th St NW, Ste 100 Cleveland, TN 37311		ANALYSIS REQUESTED								Visit our website www.aesatlanta.com to check on the status of your results, place bottle orders, etc.	No # of Containers				
PHONE: 423/303-7101		FAX:		TN App 1 VOC (8200)	TH App 1 VOC (601)	TL App Metals (1000)	DSS, AM	COD	TDS	HCl, NO ₃ , SO ₄	CN			TOC, NH ₃			
SAMPLED BY: J Muller, P.Warr		SIGNATURE:		PRESERVATION (See codes)								REMARKS					
#	SAMPLE ID	SAMPLED		Grab	Composite	Matrix (See codes)	H+I	I	N	I	S+I	F	I	NaOH S+I			
		DATE	TIME														
1	Leachate	5-26-17	1345	X		GW	2	2	1	1	1	1	1	1	1	11	
2																	
3																	
4																	
5																	
6																	
7																	
8																	
9																	
10																	
11																	
12																	
13																	
14																	
RELINQUISHED BY		DATE/TIME		RECEIVED BY		DATE/TIME		PROJECT INFORMATION								RECEIPT	
1: 5-26-17 1300		1: 5-26-17 1300		PROJECT NAME: London County (Mother Bend) Landfill										Total # of Containers	11		
2: 5-26-17 1300		2: 5-26-17 1300		PROJECT #:										Turnaround Time Request			
3: 5-26-17 1300		3: 5-26-17 1300		SITE ADDRESS: 21712 Hwy 72 N London, TN 37774										Standard 5 Business Days			
				SEND REPORT TO: Robert Hudson										2 Business Day Rush			
														Next Business Day Rush			
														Same Day Rush (auth req.)			
														Other			
SPECIAL INSTRUCTIONS/COMMENTS:		SHIPMENT METHOD		OUT / / VIA: IN / / VIA: CLIENT FedEx UPS MAIL COURIER GREYHOUND OTHER		INVOICE TO: (IF DIFFERENT FROM ABOVE)								STATE PROGRAM (if any): TA E-mail? <input checked="" type="checkbox"/> / N: Fax? <input checked="" type="checkbox"/> Y / <input type="checkbox"/> DATA PACKAGE: I <input checked="" type="checkbox"/> II <input type="checkbox"/> III <input type="checkbox"/> IV			

SAMPLES RECEIVED AFTER 3PM OR SATURDAY ARE CONSIDERED AS RECEIVED ON THE NEXT BUSINESS DAY; IF NO TAT IS MARKED ON COC AES WILL PROCEED AS STANDARD TAT.
 SAMPLES ARE DISPOSED OF 30 DAYS AFTER COMPLETION OF REPORT UNLESS OTHER ARRANGEMENTS ARE MADE.

MATRIX CODES: A = Air GW = Groundwater SE = Sediment SO = Soil SW = Surface Water W = Water (Blanks) DW = Drinking Water (Blanks) O = Other (specify)

PRESERVATIVE CODES: H+I = Hydrochloric acid + ice I = Ice only N = Nitric acid S+I = Sulfuric acid + ice S/M+I = Sodium Bisulfite/Methanol + ice O = Other (specify) NA = None

White Copy - Original; Yellow Copy - Client

Client: Santek Environmental Inc.
Project: Loudon County (Matlock Bend) Landfill
Lab ID: 1705Q24

Case Narrative**Sample Receiving Nonconformance:**

Samples 1705Q24-001C, -001E and -001H as received did not meet specified pH range for requested test methods 6020, 7470, 410.4, 350.1 and SM5310B of <2. Sample 1705Q24-001H did not meet specified pH range of >10 for method SW9014. Lab attempted to adjust pH at receipt using the maximum allowable amount of preservative, however, the required pH was not obtained. The laboratory proceeded with analysis per Robert Hudson via phone 05-26-17.

The turn around time on the Chain of Custody was listed as a 2 day rush, however the TAT was changed to standard per Robert Hudson via email 05-26-17

Ion Scan Analysis by Method 300.0:

Due to sample matrix, sample 1705Q24-001G required dilution during preparation and/or analysis resulting in elevated reporting limits.

Micro-extractable VOC Analysis by Method 8011:

Matrix spike duplicate analyses were not performed with Batch 243325 due to insufficient sample volume.

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Santek Environmental Inc.	Client Sample ID:	LEACHATE
Project Name:	Loudon County (Matlock Bend) Landfill	Collection Date:	5/25/2017 1:45:00 PM
Lab ID:	1705Q24-001	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
Total Organic Carbon (TOC) by SM5310B								
Organic Carbon, Total	465	20.0		mg/L	R344665	20	05/31/2017 10:45	JM
Total Metals by ICP/MS SW6020B								
Calcium	106	0.500		mg/L	243390	5	06/08/2017 15:01	JR
Iron	8.08	0.500		mg/L	243390	5	06/08/2017 15:01	JR
Magnesium	77.6	0.500		mg/L	243390	5	06/08/2017 15:01	JR
Potassium	342	25.0		mg/L	243390	50	06/08/2017 15:17	JR
Sodium	738	25.0		mg/L	243390	50	06/08/2017 15:17	JR
Residue, Dissolved (TDS) by SM2540C								
Residue, Dissolved (TDS)	3340	10		mg/L	243493	1	06/01/2017 11:40	BD
Nitrogen, Ammonia (as N) E350.1								
Nitrogen, Ammonia (As N)	975	100		mg/L	243443	500	05/31/2017 16:46	FS
MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011								
1,2-Dibromo-3-chloropropane	BRL	0.200		ug/L	243325	1	06/01/2017 02:00	AW
1,2-Dibromoethane	BRL	0.050		ug/L	243325	1	06/01/2017 02:00	AW
Surr: 4-Bromofluorobenzene	79.2	69.4-134	%REC	243325	1	06/01/2017 02:00	AW	
Mercury, Total SW7470A								
Mercury	BRL	0.00200		mg/L	243660	1	06/07/2017 09:50	AS
Inorganic Anions by IC E300.0								
Chloride	919	20.0		mg/L	R344266	20	05/26/2017 21:23	JM
Fluoride	BRL	80.0		mg/L	R344266	20	05/26/2017 21:23	JM
Nitrogen, Nitrate (As N)	BRL	200		mg/L	R344266	20	05/26/2017 21:23	JM
Sulfate	44.5	20.0		mg/L	R344266	20	05/26/2017 21:23	JM
Dissolved Metals by ICP/MS SW6020B								
Manganese	1.12	0.0100		mg/L	243633	1	06/05/2017 23:45	JR
Cyanide SW9014								
Cyanide, Total	BRL	0.200		mg/L	243607	1	06/01/2017 13:00	CG
Chemical Oxygen Demand (COD) E410.4								
Chemical Oxygen Demand	1170	100		mg/L	R344553	10	06/02/2017 11:00	LM
APPENDIX I VOLATILE ORGANICS SW8260B								
1,1,1,2-Tetrachloroethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
1,1,1-Trichloroethane	BRL	200		ug/L	243375	1	05/30/2017 15:59	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Analytical Environmental Services, Inc

Date: 9-Jun-17

Client:	Sautek Environmental Inc.	Client Sample ID:	LEACHATE
Project Name:	Loudon County (Matlock Bend) Landfill	Collection Date:	5/25/2017 1:45:00 PM
Lab ID:	1705Q24-001	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
							(SW5030B)	
1,1,2,2-Tetrachloroethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
1,1,2-Trichloroethane	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
1,1-Dichloroethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
1,1-Dichloroethene	BRL	7.0		ug/L	243375	1	05/30/2017 15:59	AR
1,2,3-Trichloropropane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
1,2-Dichlorobenzene	BRL	600		ug/L	243375	1	05/30/2017 15:59	AR
1,2-Dichloroethane	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
1,2-Dichloropropane	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
1,4-Dichlorobenzene	BRL	75		ug/L	243375	1	05/30/2017 15:59	AR
2-Butanone	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
2-Hexanone	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
4-Methyl-2-pentanone	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Acetone	47	10		ug/L	243375	1	05/30/2017 15:59	AR
Acrylonitrile	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Benzene	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
Bromochloromethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Bromodichloromethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Bromoform	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Bromomethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Carbon disulfide	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Carbon tetrachloride	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
Chlorobenzene	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Chloroethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Chloroform	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Chloromethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
cis-1,2-Dichloroethene	BRL	70		ug/L	243375	1	05/30/2017 15:59	AR
cis-1,3-Dichloropropene	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Dibromochloromethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Dibromomethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Ethylbenzene	BRL	700		ug/L	243375	1	05/30/2017 15:59	AR
Iodomethane	FRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Methylene chloride	ERL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
Styrene	BRL	100		ug/L	243375	1	05/30/2017 15:59	AR
Tetrachloroethene	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
Toluene	BRL	1000		ug/L	243375	1	05/30/2017 15:59	AR
trans-1,2-Dichloroethene	BRL	100		ug/L	243375	1	05/30/2017 15:59	AR
trans-1,3-Dichloropropene	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
trans-1,4-Dichloro-2-butene	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Trichloroethene	BRL	5.0		ug/L	243375	1	05/30/2017 15:59	AR
Trichlorofluoromethane	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR
Vinyl acetate	BRL	10		ug/L	243375	1	05/30/2017 15:59	AR

Qualifiers: * Value exceeds maximum contaminant level

E Estimated (value above quantitation range)

BRL Below reporting limit

S Spike Recovery outside limits due to matrix

H Holding times for preparation or analysis exceeded

Narr See case narrative

N Analyte not NELAC certified

NC Not confirmed

B Analyte detected in the associated method blank

< Less than Result value

> Greater than Result value

J Estimated value detected below Reporting Limit

Client:	Santek Environmental Inc.	Client Sample ID:	LEACHATE
Project Name:	Loudon County (Matlock Bend) Landfill	Collection Date:	5/25/2017 1:45:00 PM
Lab ID:	1705Q24-001	Matrix:	Groundwater

Analyses	Result	Reporting Limit	Qual	Units	BatchID	Dilution Factor	Date Analyzed	Analyst
APPENDIX I VOLATILE ORGANICS SW8260B								
(SW5030B)								
Vinyl chloride	BRL	2.0		ug/L	243375	1	05/30/2017 15:59	AR
Xylenes, Total	BRL	10000		ug/L	243375	1	05/30/2017 15:59	AR
Surr: 4-Bromofluorobenzene	96.3	66.1-129	%REC		243375	1	05/30/2017 15:59	AR
Surr: Dibromofluoromethane	95.7	83.6-123	%REC		243375	1	05/30/2017 15:59	AR
Surr: Toluene-d8	94.4	81.8-118	%REC		243375	1	05/30/2017 15:59	AR
APPENDIX I METALS SW6020B								
(SW3005A)								
Antimony	0.0306	0.00150		mg/L	243390	1	06/02/2017 04:13	JR
Arsenic	0.0613	0.00500		mg/L	243390	2	06/05/2017 19:03	JR
Barium	0.523	0.500		mg/L	243390	1	06/02/2017 04:13	JR
Beryllium	BRL	0.00100		mg/L	243390	1	06/02/2017 04:13	JR
Cadmium	BRL	0.00125		mg/L	243390	1	06/02/2017 04:13	JR
Chromium	0.163	0.0250		mg/L	243390	1	06/02/2017 04:13	JR
Cobalt	0.0743	0.0100		mg/L	243390	2	06/05/2017 19:03	JR
Copper	0.0396	0.0100		mg/L	243390	2	06/05/2017 19:03	JR
Lead	0.0201	0.00375		mg/L	243390	1	06/02/2017 04:13	JR
Nickel	0.255	0.0500		mg/L	243390	2	06/05/2017 19:03	JR
Selenium	BRL	0.0100		mg/L	243390	1	06/08/2017 16:58	JR
Silver	BRL	0.00250		mg/L	243390	1	06/02/2017 04:13	JR
Thallium	BRL	0.000500		mg/L	243390	1	06/02/2017 04:13	JR
Vanadium	0.0538	0.00500		mg/L	243390	1	06/02/2017 04:13	JR
Zinc	0.206	0.0200		mg/L	243390	2	06/05/2017 19:03	JR

Qualifiers:	* Value exceeds maximum contaminant level	E Estimated (value above quantitation range)
	BRL Below reporting limit	S Spike Recovery outside limits due to matrix
	H Holding times for preparation or analysis exceeded	Narr See case narrative
	N Analyte not NELAC certified	NC Not confirmed
	B Analyte detected in the associated method blank	< Less than Result value
	> Greater than Result value	J Estimated value detected below Reporting Limit

SAMPLE/COOLER RECEIPT CHECKLIST

1. Client Name: **Santek Environmental Inc.**AES Work Order Number: **1705Q24**2. Carrier: FedEx UPS USPS Client Courier Other _____

	Yes	No	N/A	Details	Comments
3. Shipping container/cooler received in good condition?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	damaged <input type="checkbox"/> leaking <input type="checkbox"/> other <input type="checkbox"/>	
4. Custody seals present on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
5. Custody seals intact on shipping container?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
6. Temperature blanks present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
7. Cooler temperature(s) within limits of 0-6°C? [See item 13 and 14 for temperature recordings.]	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Cooling initiated for recently collected samples / ice present <input type="checkbox"/>	
8. Chain of Custody (COC) present?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
9. Chain of Custody signed, dated, and timed when relinquished and received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
10. Sampler name and/or signature on COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
11. Were all samples received within holding time?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
12. TAT marked on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	If no TAT indicated, proceeded with standard TAT per Terms & Conditions. <input type="checkbox"/>	

13. Cooler 1 Temperature 3.0 °C Cooler 2 Temperature 5.0 °C Cooler 3 Temperature _____ °C Cooler 4 Temperature _____ °C

14. Cooler 5 Temperature _____ °C Cooler 6 Temperature _____ °C Cooler 7 Temperature _____ °C Cooler 8 Temperature _____ °C

15. Comments: _____

I certify that I have completed sections 1-15 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
16. Were sample containers intact upon receipt?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
17. Custody seals present on sample containers?	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>		
18. Custody seals intact on sample containers?	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>		
19. Do sample container labels match the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	incomplete info <input type="checkbox"/> illegible <input type="checkbox"/> no label <input type="checkbox"/> other <input type="checkbox"/>	
20. Are analyses requested indicated on the COC?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
21. Were all of the samples listed on the COC received?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	samples received but not listed on COC <input type="checkbox"/> samples listed on COC not received <input type="checkbox"/>	
22. Was the sample collection date/time noted?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
23. Did we receive sufficient sample volume for indicated analyses?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
24. Were samples received in appropriate containers?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
25. Were VOA samples received without headspace (< 1/4" bubble)?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		
26. Were trip blanks submitted?	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	listed on COC <input type="checkbox"/> not listed on COC <input checked="" type="checkbox"/>	

27. Comments: _____

I certify that I have completed sections 16-27 (dated initials).

AJ 5/26/17

	Yes	No	N/A	Details	Comments
28. Have containers needing chemical preservation been checked?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
29. Containers meet preservation guidelines?	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>		AS APPLICABLE
30. Was pH adjusted?	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>		See narrative

I certify that I have completed sections 28-30 (dated initials).

AJ 5/26/17

Client: Santek Environmental Inc.
Project Name: Loudon County (Matlock Bend) Landfill
Lab Order: 1705Q24

Dates Report

Lab Sample ID	Client Sample ID	Collection Date	Matrix	Test Name	TCLP Date	Prep Date	Analysis Date
1705Q24-001A	LEACHATE	5/25/2017 1:45:00PM	Groundwater	APPENDIX I VOLATILE ORGANICS	5/30/2017	12:22:00PM	05/30/2017
1705Q24-001B	LEACHATE	5/25/2017 1:45:00PM	Groundwater	MICRO-EXTRACTABLE VOCs	5/30/2017	3:30:00PM	06/01/2017
1705Q24-001C	LEACHATE	5/25/2017 1:45:00PM	Groundwater	APPENDIX I METALS	5/31/2017	10:54:00AM	06/02/2017
1705Q24-001C	LEACHATE	5/25/2017 1:45:00PM	Groundwater	APPENDIX I METALS	5/31/2017	10:54:00AM	06/05/2017
1705Q24-001C	LEACHATE	5/25/2017 1:45:00PM	Groundwater	APPENDIX I METALS	5/31/2017	10:54:00AM	06/08/2017
1705Q24-001C	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Total Metals by ICP/MS	5/31/2017	10:54:00AM	06/08/2017
1705Q24-001C	LEACHATE	5/25/2017 1:45:00PM	Groundwater	TOTAL MERCURY	6/6/2017	12:43:00PM	06/07/2017
1705Q24-001D	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Dissolved Metals by ICP/MS	6/5/2017	6:03:00PM	06/05/2017
1705Q24-001E	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Chemical Oxygen Demand (COD)			06/02/2017
1705Q24-001F	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Residue, Dissolved (TDS) by SM2540C	6/1/2017	11:40:00AM	06/01/2017
1705Q24-001G	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Inorganic Anions by IC			05/26/2017
1705Q24-001H	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Cyanide	6/1/2017	9:00:00AM	06/01/2017
1705Q24-001I	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Nitrogen, Ammonia (as N)	5/31/2017	3:45:00PM	05/31/2017
1705Q24-001I	LEACHATE	5/25/2017 1:45:00PM	Groundwater	Total Organic Carbon by SM5310B			05/31/2017

pH Adjustment Sheet

* Number of Pellets when adding NaOH

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243325

Sample ID:	MB-243325	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344377		
Sample Type:	MLBK	TestCode:	MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011	Batch ID:	243325	Analysis Date:	05/31/2017	Seq No:	7554693		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,2-Dibromo-3-chloropropane	BRL	0.040									
1,2-Dibromoethane	BRL	0.020									
Surf: 4-Bromofluorobenzene	5.044	0	5.000		101	69.4	134				
Sample ID:	LCS-243325	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344377		
Sample Type:	LCS	TestCode:	MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011	Batch ID:	243325	Analysis Date:	05/31/2017	Seq No:	7554694		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000		98.0	60	140				
1,2-Dibromoethane	0.09400	0.020	0.1000		94.0	60	140				
Surf: 4-Bromofluorobenzene	5.266	0	5.000		105	69.4	134				
Sample ID:	LCSD-243325	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344377		
Sample Type:	LCSD	TestCode:	MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011	Batch ID:	243325	Analysis Date:	05/31/2017	Seq No:	7554695		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,2-Dibromo-3-chloropropane	0.09800	0.040	0.1000		98.0	60	140	0.09800	0	20	
1,2-Dibromoethane	0.09600	0.020	0.1000		96.0	60	140	0.09400	2.11	20	
Surf: 4-Bromofluorobenzene	5.262	0	5.000		105	69.4	134	5.266	0	0	
Sample ID:	1705Q25-004BMS	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344377		
Sample Type:	MS	TestCode:	MICRO-EXTRACTABLE VOLATILE ORGANICS SW8011	Batch ID:	243325	Analysis Date:	05/31/2017	Seq No:	7554698		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,2-Dibromo-3-chloropropane	BRL	0.200	0.0999		102	51.3	144				
1,2-Dibromoethane	0.1019	0.050	0.0999		102	57.7	132				*
Surf: 4-Bromofluorobenzene	5.082	0.050	4.993		102	69.4	134				

Qualifiers: > Greater than Result value

< Less than Result value

B Analyte detected in the associated method blank

BRL Below reporting limit

E Estimated (value above quantitation range)

H Holding times for preparation or analysis exceeded

J Estimated value detected below Reporting Limit

N Analyte not NELAC certified

R RPD outside limits due to matrix

Rpt Lim Reporting Limit

S Spike Recovery outside limits due to matrix

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243375

Sample ID: MB-243375	Client ID:		Units: ug/L	Prep Date: 05/30/2017	Run No: 344215						
SampleType: MBLK	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B		BatchID: 243375	Analysis Date: 05/30/2017	Seq No: 7553698						
Analyte											
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1,1,2-Tetrachloroethane	BRL	5.0									
1,1,1-Trichloroethane	BRL	5.0									
1,1,2,2-Tetrachloroethane	BRL	5.0									
1,1,2-Trichloroethane	BRL	5.0									
1,1-Dichloroethane	BRL	5.0									
1,1-Dichloroethene	BRL	5.0									
1,2,3-Trichloropropane	BRL	5.0									
1,2-Dichlorobenzene	BRL	5.0									
1,2-Dichloroethane	BRL	5.0									
1,2-Dichloropropane	BRL	5.0									
1,4-Dichlorobenzene	BRL	5.0									
2-Butanone	BRL	50									
2-Hexanone	BRL	10									
4-Methyl-2-pentanone	BRL	10									
Acetone	BRL	50									
Acrylonitrile	BRL	5.0									
Benzene	BRL	5.0									
Bromochloromethane	BRL	5.0									
Bromodichloromethane	BRL	5.0									
Bromoform	BRL	5.0									
Bromomethane	BRL	5.0									
Carbon disulfide	BRL	5.0									
Carbon tetrachloride	BRL	5.0									
Chlorobenzene	BRL	5.0									
Chloroethane	BRL	10									
Chloroform	BRL	5.0									
Chloromethane	BRL	10									

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243375

Sample ID:	MB-243375	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344215		
Sample Type:	MBLK	TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	BatchID:	243375	Analysis Date:	05/30/2017	Seq No:	7553698		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
cis-1,2-Dichloroethene	BRL	5.0									
cis-1,3-Dichloropropene	BRL	5.0									
Dibromochloromethane	BRL	5.0									
Dibromomethane	BRL	5.0									
Ethylbenzene	BRL	5.0									
Iodomethane	BRL	10									
Methylene chloride	BRL	5.0									
Styrene	BRL	5.0									
Tetrachloroethene	BRL	5.0									
Toluene	BRL	5.0									
trans-1,2-Dichloroethene	BRL	5.0									
trans-1,3-Dichloropropene	BRL	5.0									
trans-1,4-Dichloro-2-butene	BRL	10									
Trichloroethene	BRL	5.0									
Trichlorofluoromethane	BRL	5.0									
Vinyl acetate	BRL	10									
Vinyl chloride	BRL	2.0									
Xylenes, Total	BRL	10									
Sur: 4-Bromofluorobenzene	47.67	0	50.00		95.3	66.1	129				
Sur: Dibromofluoromethane	48.17	0	50.00		96.3	83.6	123				
Sur: Toluene-d8	48.38	0	50.00		96.8	81.8	118				

Sample ID:	LCS-243375	Client ID:		Units:	ug/L	Prep Date:	05/30/2017	Run No:	344215		
Sample Type:	LCS	TestCode:	APPENDIX I VOLATILE ORGANICS SW8260B	BatchID:	243375	Analysis Date:	05/30/2017	Seq No:	7553697		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1-Dichloroethene	45.19	5.0	50.00		90.4	68	139				
Benzene	46.79	5.0	50.00		93.6	74	125				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243375

Sample ID:	LCS-243375	Client ID:	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B			Units:	ug/L	Prep Date:	05/30/2017	Run No:	344215
SampleType:	LCS					BatchID:	243375	Analysis Date:	05/30/2017	Seq No:	7553697
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Chlorobenzene	48.19	5.0	50.00		96.4	75.7	123				
Toluene	49.17	5.0	50.00		98.3	75.9	126				
Trichloroethene	47.32	5.0	50.00		94.6	70.6	129				
Sur: 4-Bromofluorobenzene	46.86	0	50.00		93.7	66.1	129				
Sur: Dibromofluoromethane	47.62	0	50.00		95.2	83.6	123				
Sur: Toluene-d8	49.02	0	50.00		98.0	81.8	118				
Sample ID:	1705K82-001AMS	Client ID:	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B			Units:	ug/L	Prep Date:	05/30/2017	Run No:	344215
SampleType:	MS					BatchID:	243375	Analysis Date:	05/30/2017	Seq No:	7553699
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1-Dichloroethene	56.31	5.0	50.00		113	64.3	149				
Benzene	54.09	5.0	50.00		108	71.6	132				
Chlorobenzene	55.82	5.0	50.00		112	73.1	126				
Toluene	54.84	5.0	50.00		110	72.5	135				
Trichloroethene	54.44	5.0	50.00		109	70.2	132				
Sur: 4-Bromofluorobenzene	46.08	0	50.00		92.2	66.1	129				
Sur: Dibromofluoromethane	48.58	0	50.00		97.2	83.6	123				
Sur: Toluene-d8	48.71	0	50.00		97.4	81.8	118				
Sample ID:	1705K82-001AMSD	Client ID:	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B			Units:	ug/L	Prep Date:	05/30/2017	Run No:	344215
SampleType:	MSD					BatchID:	243375	Analysis Date:	05/30/2017	Seq No:	7553700
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
1,1-Dichloroethene	52.48	5.0	50.00		105	64.3	149	56.31	7.04	30.8	
Benzene	53.07	5.0	50.00		106	71.6	132	54.09	1.90	20.7	
Chlorobenzene	53.42	5.0	50.00		107	73.1	126	55.82	4.39	26.6	
Toluene	53.70	5.0	50.00		107	72.5	135	54.84	2.10	23.2	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243375

Sample ID: 1705K82-001AMSD	Client ID:				Units: ug/L	Prep Date: 05/30/2017	Run No: 344215				
SampleType: MSD	TestCode: APPENDIX I VOLATILE ORGANICS SW8260B				BatchID: 243375	Analysis Date: 05/30/2017	Seq No: 7553700				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Trichloroethene	52.65	5.0	50.00		105	70.2	132	54.44	3.34	27.7	
Sur: 4-Bromofluorobenzene	48.18	0	50.00		96.4	66.1	129	46.08	0	0	
Sur: Dibromofluoromethane	49.02	0	50.00		98.0	83.6	123	48.58	0	0	
Sur: Toluene-d8	49.09	0	50.00		98.2	81.8	118	48.71	0	0	

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID: MB-243390	Client ID:		Units: mg/L	Prep Date: 05/31/2017	Run No: 344570
SampleType: MBLK	TestCode: APPENDIX I METALS	SW6020B	BatchID: 243390	Analysis Date: 06/02/2017	Seq No: 7559943
Analyte Result RPT Limit SPK value SPK Ref Val %REC					
Antimony	BRL	0.00600			
Arsenic	BRL	0.0100			
Barium	BRL	0.0200			
Beryllium	BRL	0.00400			
Cadmium	BRL	0.00500			
Chromium	BRL	0.0200			
Cobalt	BRL	0.0500			
Copper	BRL	0.0200			
Lead	BRL	0.0100			
Nickel	BRL	0.0400			
Selenium	BRL	0.0500			
Silver	BRL	0.00500			
Thallium	BRL	0.00200			
Vanadium	BRL	0.0500			
Zinc	BRL	0.0200			

Sample ID: MB-243390	Client ID:		Units: mg/L	Prep Date: 05/31/2017	Run No: 345018
SampleType: MBLK	TestCode: Total Metals by ICP/MS	SW6020B	BatchID: 243390	Analysis Date: 06/08/2017	Seq No: 7571535
Analyte Result RPT Limit SPK value SPK Ref Val %REC					
Calcium	BRL	0.100			
Iron	BRL	0.100			
Magnesium	BRL	0.100			
Potassium	BRL	0.100			
Sodium	BRL	0.500			

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	LCS-243390	Client ID:		TestCode:	APPENDIX I METALS	Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570
SampleType:	LCS		<th></th> <td>SW6020B</td> <th>BatchID:</th> <td>243390</td> <th>Analysis Date:</th> <td>06/02/2017</td> <th>Seq No:</th> <td>7559944</td>		SW6020B	BatchID:	243390	Analysis Date:	06/02/2017	Seq No:	7559944
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1049	0.00600	0.1000		105	80	120				
Arsenic	0.09720	0.0100	0.1000	0.0003020	96.9	80	120				
Barium	0.1059	0.0200	0.1000	0.0001990	106	80	120				
Beryllium	0.1004	0.00400	0.1000		100	80	120				
Cadmium	0.1004	0.00500	0.1000		100	80	120				
Chromium	0.1114	0.0200	0.1000	0.004256	107	80	120				
Cobalt	0.09718	0.0500	0.1000		97.2	80	120				
Copper	0.09508	0.0200	0.1000	0.001508	93.6	80	120				
Lead	0.1015	0.0100	0.1000		102	80	120				
Nickel	0.1033	0.0400	0.1000	0.002346	101	80	120				
Selenium	0.09930	0.0500	0.1000		99.3	80	120				
Silver	0.01025	0.00500	0.0100	0.00005200	102	80	120				
Thallium	0.1003	0.00200	0.1000		100	80	120				
Vanadium	0.09813	0.0500	0.1000	0.0004270	97.7	80	120				
Zinc	0.1082	0.0200	0.1000	0.003554	105	80	120				

Sample ID:	LCS-243390	Client ID:		TestCode:	Total Metals by ICP/MS	Units:	mg/L	Prep Date:	05/31/2017	Run No:	345018
SampleType:	LCS		<th></th> <td>SW6020B</td> <th>BatchID:</th> <td>243390</td> <th>Analysis Date:</th> <td>06/08/2017</td> <th>Seq No:</th> <td>7571536</td>		SW6020B	BatchID:	243390	Analysis Date:	06/08/2017	Seq No:	7571536
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	1.097	0.100	1.000	0.07192	103	80	120				
Iron	0.9963	0.100	1.000		99.6	80	120				
Magnesium	0.9162	0.100	1.000		91.6	80	120				
Potassium	0.9673	0.100	1.000		96.7	80	120				
Sodium	0.9071	0.500	1.000	0.03703	87.0	80	120				

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID:	1705Q20-006IMS	Client ID:		Units:	mg/L	Prep Date:	05/31/2017	Run No:	344570		
SampleType:	MS	TestCode:	APPENDIX I METALS	BatchID:	243390	Analysis Date:	06/02/2017	Seq No:	7559947		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1029	0.00600	0.1000	0.0008790	102	75	125				
Arsenic	0.09026	0.0100	0.1000	0.0005500	89.7	75	125				
Barium	0.2064	0.0200	0.1000	0.1040	102	75	125				
Beryllium	0.09809	0.00400	0.1000		98.1	75	125				
Cadmium	0.09740	0.00500	0.1000	0.0003680	97.0	75	125				
Chromium	0.1008	0.0200	0.1000	0.001539	99.3	75	125				
Cobalt	0.1025	0.0500	0.1000	0.01097	91.5	75	125				
Copper	0.08859	0.0200	0.1000	0.002790	85.8	75	125				
Lead	0.1018	0.0100	0.1000	0.0008580	101	75	125				
Nickel	0.1040	0.0400	0.1000	0.01205	92.0	75	125				
Selenium	0.09003	0.0500	0.1000	0.0003690	89.7	75	125				
Silver	0.009767	0.00500	0.0100	0.00006400	97.0	75	125				
Thallium	0.1013	0.00200	0.1000	0.0007370	101	75	125				
Vanadium	0.09545	0.0500	0.1000		95.4	75	125				
Zinc	0.09775	0.0200	0.1000	0.004953	92.8	75	125				

Sample ID:	1705Q20-006IMS	Client ID:		Units:	mg/L	Prep Date:	05/31/2017	Run No:	345018		
SampleType:	MS	TestCode:	Total Metals by ICP/MS	BatchID:	243390	Analysis Date:	06/08/2017	Seq No:	7571517		
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	13.16	0.100	1.000	12.27	89.0	75	125				
Iron	1.112	0.100	1.000	0.1392	97.3	75	125				
Magnesium	5.212	0.100	1.000	4.293	91.9	75	125				
Potassium	5.955	0.100	1.000	5.073	88.2	75	125				
Sodium	42.74	0.500	1.000	42.28	46.0	75	125				S

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

Client: Santek Environmental Inc.
 Project Name: Loudon County (Matlock Bend) Landfill
 Workorder: 1705Q24

ANALYTICAL QC SUMMARY REPORT

BatchID: 243390

Sample ID: 1705Q20-006IMSD	Client ID:				Units: mg/L	Prep Date: 05/31/2017	Run No: 344570				
SampleType: MSD	TestCode: APPENDIX I METALS	SW6020B			BatchID: 243390	Analysis Date: 06/02/2017	Seq No: 7559949				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Antimony	0.1011	0.00600	0.1000	0.0008790	100	75	125	0.1029	1.76	20	
Arsenic	0.08511	0.0100	0.1000	0.0005500	84.6	75	125	0.09026	5.87	20	
Barium	0.2115	0.0200	0.1000	0.1040	108	75	125	0.2064	2.44	20	
Beryllium	0.09513	0.00400	0.1000		95.1	75	125	0.09809	3.06	20	
Cadmium	0.09516	0.00500	0.1000	0.0003680	94.8	75	125	0.09740	2.33	20	
Chromium	0.09581	0.0200	0.1000	0.001539	94.3	75	125	0.1008	5.08	20	
Cobalt	0.09885	0.0500	0.1000	0.01097	87.9	75	125	0.1025	3.63	20	
Copper	0.08345	0.0200	0.1000	0.002790	80.7	75	125	0.08859	5.98	20	
Lead	0.1042	0.0100	0.1000	0.0008580	103	75	125	0.1018	2.33	20	
Nickel	0.09845	0.0400	0.1000	0.01205	86.4	75	125	0.1040	5.48	20	
Selenium	0.08619	0.0500	0.1000	0.0003690	85.8	75	125	0.09003	4.36	20	
Silver	0.009144	0.00500	0.0100	0.00006400	90.8	75	125	0.009767	6.59	20	
Thallium	0.1049	0.00200	0.1000	0.0007370	104	75	125	0.1013	3.49	20	
Vanadium	0.09432	0.0500	0.1000		94.3	75	125	0.09545	1.19	20	
Zinc	0.09047	0.0200	0.1000	0.004953	85.5	75	125	0.09775	7.74	20	

Sample ID: 1705Q20-006IMSD	Client ID:				Units: mg/L	Prep Date: 05/31/2017	Run No: 345018				
SampleType: MSD	TestCode: Total Metals by ICP/MS	SW6020B			BatchID: 243390	Analysis Date: 06/08/2017	Seq No: 7571523				
Analyte	Result	RPT Limit	SPK value	SPK Ref Val	%REC	Low Limit	High Limit	RPD Ref Val	%RPD	RPD Limit	Qual
Calcium	13.26	0.100	1.000	12.27	99.0	75	125	13.16	0.757	20	
Iron	1.094	0.100	1.000	0.1392	95.5	75	125	1.112	1.63	20	
Magnesium	5.413	0.100	1.000	4.293	112	75	125	5.212	3.78	20	
Potassium	6.059	0.100	1.000	5.073	98.6	75	125	5.955	1.73	20	
Sodium	44.83	0.500	1.000	42.28	255	75	125	42.74	4.77	20	S

Qualifiers:	>	Greater than Result value	<	Less than Result value	B	Analyte detected in the associated method blank
	BRL	Below reporting limit	E	Estimated (value above quantitation range)	H	Holding times for preparation or analysis exceeded
	J	Estimated value detected below Reporting Limit	N	Analyte not NELAC certified	R	RPD outside limits due to matrix
	Rpt Lim	Reporting Limit	S	Spike Recovery outside limits due to matrix		

LEACHATE CONTROL CHART

**LOUDON COUNTY
LEACHATE**

INORGANIC	APPENDIX I LIMITS	4-17-02	4-29-04	4-11-05	3-27-06	3-22-07	3-27-08	4-2-09	4-7-10	1-5-11	3-15-12	3-28-13	3-25-14	4-1-15	5-24-16	5-25-17	Leachate AVG
Antimony	6	6	6	6	6	6	6	6	60	6	6	8.75	60.00	6	8.23	30.60	15.17
Arsenic	50	50	224	168	79.3	50.7	50.0	50.0	500.0	50.0	50.0	69.7	500.0	69.6	116.0	61.3	139.24
Barium	2000	2000	2610	2790	2000	2000	2000	2000	20000	2000	2000	2000	2000	2000	687	523	3107.33
Beryllium	4	4	4	4	4	4	4	4	40	4	4	4	4	4	4	1	6.20
Cadmium	5	5	5	5	5	5	5	5	50	5	5	5	5	5	5	1.25	7.75
Chromium	100	100	106	145	100	100	100	100	1000	100	100	136	1000	230	584	163	270.93
Cobalt	6**	19.5	36.5	53.0	40.1	30.6	25.5	14.4	1000.0	37.2	10.0	87.1	100.0	82.6	151.0	74.3	117.45
Copper	800**	10	31.9	14.6	10	10	10	10	1000	10	10	15.9	100.0	25.3	88.3	39.6	92.37
Fluoride*	4	4	4	4	4	4	80	80	40	400	40	40	400	200	200	80	105.33
Lead	†15	50	57.1	50	50	50	15	15	150	15	15	15	150	30.4	116.0	20.1	53.24
Mercury	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2.00
Nickel	100	100	100	144	114	100	100	100	1000	100	100	258	1000	240	618	255	288.60
Selenium	10	10	10	10.5	20.2	12.2	21.3	10.0	100.0	12.8	10.0	14.1	100.0	13.1	69.7	10.0	28.26
Silver	50	50	50	50	50	50	50	50	500	50	50	50	500	50	5	2.5	103.83
Thallium	2	2	3.5	2	2	10.5	2.0	2.0	20.0	2.0	2.0	2.0	20.0	2.0	2.0	0.5	4.97
Vanadium	86**	10	55.4	34.3	14.2	14.2	11.4	10.0	100.0	25.5	10.0	48.5	108.0	101.0	158.0	53.8	50.29
Zinc	6000**	44.4	918	209	66.5	32.5	66.8	67.5	420	176	191	1640	922	512	770	206	416.11

*ALL DATA IN UG/L EXCEPT FLUORIDE (MG/L)

† = TREATMENT TECHNIQUE ACTION LEVEL

**EPA REGION 4 SCREENING LEVEL

4/7/10 reporting limits for some constituents are elevated due to a high dilution factor