

AGENDA

LOUDON COUNTY SOLID WASTE DISPOSAL COMMISSION

February 14, 2012

6:30 p.m.

LOUDON COUNTY COURTHOUSE ANNEX

Loudon, Tennessee

1. Call to Order
2. Approval of the Minutes – January 10, 2012
3. Items of Public Concern
4. Cash Activity Report
5. Operations Report
6. Attorney's Report
7. Chairman's Report
8. Other Items of Consideration
9. Adjourn

MONTHLY CASH REPORT

January OF 2012

CASH RECEIPTS:

Landfill Host Fees	<u>14,029.62</u>
Closure/Post Clo. Security Fees	<u>19,804.15</u>
Interest Received	<u>259.34</u>
Tire Grants	<u> </u>
Other: _____	<u> </u>

Total Monthly Revenue: 34,093.11

CASH DISBURSEMENTS:

Commissioner Meeting Pymts.	<u>350.00</u>
Commissioner Travel/Seminar	<u> </u>
Meeting Expense	<u> </u>
Legal Services	<u>2,362.60</u>
Audit/Accounting Services	<u>5,000.00</u>
Consultants	<u> </u>
Trustee's Commission	<u>338.34</u>
Debt Service/Loudon - Water Lines	<u> </u>
Santek-Tire Grant	<u> </u>
Engineering Services	<u> </u>
Office Supplies	<u> </u>
Building and Contents Insurance	<u> </u>
Other: <u>Contracted Services</u>	<u> </u>

Total Monthly Expense: 8,050.94

Change in Net Assets: 26,042.17



BEGINNING CASH BALANCE: \$ 2,170,545.42

CLOSURE RESERVES:	\$ <u>738,029.14</u>
Total Closure Reserves and General Account	\$ <u>2,196,587.59</u>
GENERAL ACCOUNT:	\$ <u>1,458,558.45</u>

ENDING CASH BALANCE: \$ 2,196,587.59

CHANGE IN CASH POSITION \$ 26,042.17



650 25th Street, N.W., Suite 100
Cleveland, Tennessee 37311
(423) 476-9160
Toll Free: (800) 467-9160
Fax: (423) 479-1952

Email: mail@santekenviro.com
Internet: www.santekenviro.com

Monthly Operations Report
Matlock Bend Landfill
February 14, 2012
Presented by:
Santek Environmental, Inc.

- I. OPERATIONS**
 - A. Tonnage Report
 - B. Customer Report
 - C. Materials Classification Report
 - D. Inspections
 - E. Tire Report
 - F. Quarterly Waste Origin Report
 - G. Quarterly State Surcharge and Inspection Fee Report

- II. ENGINEERING**
 - A. Remaining Airspace Utilization Schedule
 - B. Status of Topographic Aerial Survey and Drawings
 - C. Status of Major Permit Modification

- III. HOST & SECURITY FEES**

**LANDFILL TONNAGE VOLUME
MONTH ENDING -
JANUARY 2012**

MATLOCK BEND LANDFILL

MONTH	2011	2012	2011 TO 2012
JANUARY	12263.30	21228.22	8964.92
FEBRUARY	14311.55		
MARCH	21861.87		
APRIL	19200.92		
MAY	19189.17		
JUNE	18316.34		
JULY	17378.46		
AUGUST	25383.15		
SEPTEMBER	22528.42		
OCTOBER	21370.05		
NOVEMBER	25184.76		
DECEMBER	19804.15		
TOTAL	236792.14	21228.22	8,964.92

LOUDON COUNTY

MONTH	2011	2012	2011 TO 2012
JANUARY	435.27	455.80	20.53
FEBRUARY	404.63		
MARCH	474.86		
APRIL	466.94		
MAY	468.57		
JUNE	480.37		
JULY	470.47		
AUGUST	459.32		
SEPTEMBER	447.25		
OCTOBER	439.67		
NOVEMBER	470.12		
DECEMBER	502.73		
TOTAL	5520.20	455.80	20.53

LENOIR CITY

MONTH	2011	2012	2011 TO 2012
JANUARY	266.42	284.88	18.46
FEBRUARY	271.36		
MARCH	371.20		
APRIL	359.97		
MAY	360.17		
JUNE	365.29		
JULY	351.96		
AUGUST	334.38		
SEPTEMBER	450.84		
OCTOBER	325.24		
NOVEMBER	297.36		
DECEMBER	314.40		
TOTAL	4068.59	284.88	18.46

DAILY AVG FOR ANY
RUNNING 30 DAY
PERIOD
707.61

CITY OF LOUDON

MONTH	2011	2012	2011 TO 2012
JANUARY	323.05	360.21	37.16
FEBRUARY	321.96		
MARCH	402.55		
APRIL	394.02		
MAY	402.53		
JUNE	405.65		
JULY	419.74		
AUGUST	424.56		
SEPTEMBER	374.30		
OCTOBER	373.74		
NOVEMBER	357.31		
DECEMBER	375.50		
TOTAL	4574.91	360.21	37.16

WASTE SERVICES OF TN

MONTH	2011	2012	2011 TO 2012
JANUARY	4347.31	3697.81	-649.50
FEBRUARY	4637.87		
MARCH	6678.49		
APRIL	5450.54		
MAY	7030.55		
JUNE	6076.54		
JULY	6536.20		
AUGUST	7337.91		
SEPTEMBER	3318.35		
OCTOBER	3415.25		
NOVEMBER	4087.34		
DECEMBER	3386.00		
TOTAL	62302.35	3697.81	(649.50)

WASTE CONNECTIONS

MONTH	2011	2012	2011 TO 2012
JANUARY	49.15	0.00	-49.15
FEBRUARY	0.00		
MARCH	31.91		
APRIL	11.40		
MAY	100.53		
JUNE	7.70		
JULY	0.00		
AUGUST	13.09		
SEPTEMBER	0.00		
OCTOBER	17.41		
NOVEMBER	0.00		
DECEMBER	85.10		
TOTAL	316.29	0.00	(49.15)

**LANDFILL TONNAGE VOLUME
MONTH ENDING -
JANUARY 2012**

KIMBERLY CLARK - ASH

MONTH	2011		2012		2011 TO 2012
	2011	2012	2012	2012	
JANUARY	521.90		0.00		-521.90
FEBRUARY	0.00				
MARCH	809.09				
APRIL	755.23				
MAY	640.15				
JUNE	1124.46				
JULY	1176.65				
AUGUST	1053.96				
SEPTEMBER	57.68				
OCTOBER	723.97				
NOVEMBER	132.45				
DECEMBER	0.00				
TOTAL	6995.54		0.00		(521.90)

TATE & LYLE - SLUDGE

MONTH	2011		2012		2011 TO 2012
	2011	2012	2012	2012	
JANUARY	1447.96		1264.44		-183.52
FEBRUARY	2308.09				
MARCH	2691.51				
APRIL	1894.03				
MAY	2368.16				
JUNE	2083.81				
JULY	1775.29				
AUGUST	1870.47				
SEPTEMBER	1108.93				
OCTOBER	1080.24				
NOVEMBER	1389.93				
DECEMBER	1128.19				
TOTAL	21146.61		1264.44		(183.52)

PSC METALS INC

MONTH	2011		2012		2011 TO 2012
	2011	2012	2012	2012	
JANUARY	944.37		5439.68		4495.31
FEBRUARY	3499.07				
MARCH	5743.05				
APRIL	4352.13				
MAY	3551.34				
JUNE	3637.91				
JULY	2305.75				
AUGUST	4901.35				
SEPTEMBER	4784.14				
OCTOBER	4247.48				
NOVEMBER	4596.66				
DECEMBER	3740.92				
TOTAL	46304.17		5439.68		4,495.31

TATE & LYLE - ASH

MONTH	2011		2012		2011 TO 2012
	2011	2012	2012	2012	
JANUARY	1447.96		958.79		-489.17
FEBRUARY	756.49				
MARCH	2140.97				
APRIL	1896.27				
MAY	3055.98				
JUNE	2362.07				
JULY	2699.09				
AUGUST	3473.16				
SEPTEMBER	622.29				
OCTOBER	963.44				
NOVEMBER	830.44				
DECEMBER	808.75				
TOTAL	21056.91		958.79		(489.17)

Materials Classification Report
Matlock Bend Landfill
Monthly Tonnage Summaries

Material	January - 12	Unit
<u>MSW</u>		
MSW	5,242	Tons
<u>Special Waste</u>		
Other	13,527	Tons
Ash	1,127	Tons
Sludge	1,350	Tons
Total Special Waste	15,964	
Total Material	21,246	
% MSW	25%	
% Special Waste	75%	
 % Sludge	 6%	



**TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION
DIVISION OF SOLID WASTE MANAGEMENT
SOLID WASTE DISPOSAL FACILITY EVALUATION**

NAME OF SITE <i>London County Landfill</i>		REGISTRATION NUMBER <i>SNL 53-0203</i>		DATE <i>January 19, 2011</i>		
LOCATION (physical) <i>off Hwy 72 west of London</i>		PURPOSE <input checked="" type="checkbox"/> Complete <input type="checkbox"/> Follow-up <input type="checkbox"/> Complaint <input type="checkbox"/> Other				
OWNER/OPERATOR <i>Owner: London Co. S. W. Authority Operator: Suntek</i>		TYPE OF FACILITY <input checked="" type="checkbox"/> CLASS I <input type="checkbox"/> CLASS II <input type="checkbox"/> CLASS III <input type="checkbox"/> CLASS IV				
		V1	V2		V1	V2
Inadequate vector control	8010	___	___	Leachate improperly managed	8330	___
Access not limited to operating hours	8020	___	___	Inadequate leachate collection system	8340	___
Inadequate artificial or natural barrier	8030	___	___	Leachate observed at the site	8350	___
Inadequate information signs	8040	___	___	Leachate entering runoff	8360	___
Unsatisfactory access road(s)/parking area(s)	8050	___	___	Leachate entering a water course	8370	___
Certified personnel not present during operating hours	8060	___	___	Inadequate gas migration control system	8380	___
Unapproved salvaging of waste	8070	___	___	Inadequate maintenance of gas migration control system	8390	___
Evidence of open burning	8080	___	___	Potential for explosions or uncontrolled fires	8420	___
Inadequate fire protection	8090	___	___	Waste not confined to a manageable area	8430	___
Unsatisfactory litter control	8110	___	___	Improper spreading of waste	8440	___
Inadequate employee facilities	8120	___	___	Improper compacting of waste	8450	___
No communication devices	8130	___	___	Unsatisfactory initial cover	8460	___
Inadequate operating equipment	8140	___	___	Unsatisfactory intermediate cover	8470	___
Unavailability of backup equipment	8150	___	___	Unsatisfactory final cover	8480	___
Unavailability of cover material	8160	___	___	Excessive pooling of water	8490	___
Inadequate maintenance of runoff/runoff system(s)	8170	___	___	Unsatisfactory stabilization of cover	8510	___
Inadequate erosion control	8180	___	___	Dumping of waste into water	8520	___
Inadequate dust control	8190	___	___	Unsatisfactory records or reports	8530	___
Unauthorized waste accepted	8210	___	___	Groundwater monitoring system improperly maintained	8540	___
Unapproved special waste accepted	8220	___	___	Operation does not correspond with engineering plans	8570	___
Tires improperly handled	8230	___	___	Operation does not correspond with permit condition(s)	8580	___
Medical waste improperly handled	8240	___	___	Permit, plans, operating manual not available	8590	___
Dead animals improperly handled	8250	___	___	No operating scales	8610	___
Washout of solid waste	8270	___	___			
No permanent benchmark	8280	___	___			
Inadequate random inspection program	8290	___	___			
Mishandling of special waste	8300	___	___			
Buffer zone standard violated	8310	___	___			
Inadequate maintenance of leachate management system	8320	___	___			

COMMENTS: *A "bowl" has been created at the upper edge of the cell due to need to place MSW only on top of the liner and the greater abundance of industrial waste vs. MSW. Need to work the waste placement so the drains out as soon as possible. Work in all excavated "dirty" soil with waste as quickly as possible and cover. Smooth out all places on slope and cover well where leachate repair work was done. Make sure all shredder stuff has been worked in and covered by end of day.*

PERSON INTERVIEWED (Signature) <i>[Signature]</i>	INSPECTED BY (Signature) _____	
TITLE <i>MANAGER</i>	TITLE _____	
TIME OF DAY <i>2:30-1:30 PM</i>	WEATHER CONDITIONS <i>Partly cloudy, 40's</i>	COMPLIANCE DATE _____

With amount of waste received need to be doing more random inspections.

Distribution: Facility - White Field Office - Canary Central Office - XC

RDAs 2202 and 2499



**TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION
DIVISION OF SOLID WASTE MANAGEMENT
SOLID WASTE DISPOSAL FACILITY EVALUATION**

NAME OF SITE <i>Loudon County Landfill</i>		REGISTRATION NUMBER <i>SNL 53-0213</i>		DATE <i>February 72</i>			
LOCATION (physical) <i>Off Hwy R west of Loudon</i>		PURPOSE <input checked="" type="checkbox"/> Complete <input type="checkbox"/> Follow-up <input type="checkbox"/> Complaint <input type="checkbox"/> Other					
OWNER/OPERATOR <i>Owner: Loudon County S.W. Authority Operator: Sinker/Leng Higdon</i>		TYPE OF FACILITY <input checked="" type="checkbox"/> CLASS I <input type="checkbox"/> CLASS II <input type="checkbox"/> CLASS III <input type="checkbox"/> CLASS IV					
		V1	V2	V1	V2		
Inadequate vector control	8010	___	___	Leachate improperly managed	8330	___	___
Access not limited to operating hours	8020	___	___	Inadequate leachate collection system	8340	___	___
Inadequate artificial or natural barrier	8030	___	___	Leachate observed at the site	8350	___	___
Inadequate information signs	8040	___	___	Leachate entering runoff	8360	___	___
Unsatisfactory access road(s)/parking area(s)	8050	___	___	Leachate entering a water course	8370	___	___
Certified personnel not present during operating hours	8060	___	___	Inadequate gas migration control system	8380	___	___
Unapproved salvaging of waste	8070	___	___	Inadequate maintenance of gas migration control system	8390	___	___
Evidence of open burning	8080	___	___	Potential for explosions or uncontrolled fires	8420	___	___
Inadequate fire protection	8090	___	___	Waste not confined to a manageable area	8430	___	___
Unsatisfactory litter control	8110	___	___	Improper spreading of waste	8440	___	___
Inadequate employee facilities	8120	___	___	Improper compacting of waste	8450	___	___
No communication devices	8130	___	___	Unsatisfactory initial cover	8460	___	___
Inadequate operating equipment	8140	___	___	Unsatisfactory intermediate cover	8470	___	___
Unavailability of backup equipment	8150	___	___	Unsatisfactory final cover	8480	___	___
Unavailability of cover material	8160	___	___	Excessive pooling of water	8490	___	___
Inadequate maintenance of runoff/runoff system(s)	8170	___	___	Unsatisfactory stabilization of cover	8510	___	___
Inadequate erosion control	8180	___	___	Dumping of waste into water	8520	___	___
Inadequate dust control	8190	___	___	Unsatisfactory records or reports	8530	___	___
Unauthorized waste accepted	8210	___	___	Groundwater monitoring system improperly maintained	8540	___	___
Unapproved special waste accepted	8220	___	___	Operation does not correspond with engineering plans	8570	___	___
Tires improperly handled	8230	___	___	Operation does not correspond with permit condition(s)	8580	___	___
Medical waste improperly handled	8240	___	___	Permit, plans, operating manual not available	8590	___	___
Dead animals improperly handled	8250	___	___	No operating scales	8610	___	___
Washout of solid waste	8270	___	___				
No permanent benchmark	8280	___	___				
Inadequate random inspection program	8290	___	___				
Mishandling of special waste	8300	___	___				
Buffer zone standard violated	8310	___	___				
Inadequate maintenance of leachate management system	8320	___	___				
COMMENTS: <i>Site conditions are much improved, they have taken advantage of recent warmer, dry weather. The "hole" above the aeth. area has been eliminated and the site is shaped now so all of the surface runoff will drain off once the bank is graded and covered at the end of the day. No need to try to get the waste into a thicker lift and more compact area. Several rough areas have already been smoothed out and covered and they are working on this today.</i>							
PERSON INTERVIEWED (Signature) <i>[Signature]</i>				INSPECTED BY (Signature) <i>[Signature]</i>			
TITLE <i>MANAGER</i>				TITLE <i>Environmental Engineer</i>			
TIME OF DAY <i>12:15-1:00 PM</i>		WEATHER CONDITIONS <i>Sunny, 50s</i>		COMPLIANCE DATE			

Need to provide documentation that the new leachate tank has been tested. Based on analytical results may stop sampling the sediment pond unless leachate flows into it again.

RDAs 2202 and 2499

**2011-2012 Matlock Bend
Landfill Tire Report**

Month	Tonnage
Jul-11	17.06
Aug-11	30.5
Sep-11	21.45
Oct-11	39.07
Nov-11	13.12
Dec-11	37.99
Jan-12	29.86
Feb-12	
Mar-12	
Apr-12	
May-12	
Jun-12	
Total (tons)	189.05



TENNESSEE DEPARTMENT OF ENVIRONMENT & CONSERVATION
 DIVISION OF SOLID WASTE MANAGEMENT- SOLID WASTE ASSISTANCE
 401 Church Street, 5th Floor
 Nashville, TN 37243-1535
QUARTERLY REPORT FOR LANDFILLS, INCINERATORS & TRANSFER STATIONS
ORIGIN OF CLASS I MUNICIPAL SOLID WASTE

The following information shall be provided in accordance with TCA 68-211-862 which states:
 (a) The owner or operator of each Class I municipal solid waste disposal facility or incinerator or transfer station required to remit a surcharge under § 68-211-835(d) shall be responsible for keeping an accurate written record of all amounts and county of origin of solid waste, measured in tons, received at the facility. This information shall be submitted to the department.
 (b) Measurement in tons of solid waste received shall be accomplished by one (1) or more of the following methods:
 (1) The provision of stationary or portable scales at the disposal facility or incinerator or transfer station for weighing incoming waste; or
 (2) Implementation of contractual or other arrangements for the use of scales at a location other than the disposal facility, incinerator, or transfer station for weighing all waste destined for disposal at the facility.

Year: 2011

Quarter:
 Check one: January-March April-June July-September October-December

Facility Name: MATLOCK BEND LANDFILL

Facility Type:
 Check one: Disposal Facility Incinerator Transfer Station

Facility ID #: SNL 53-1030203 Advertised Tipping Fee _____

Facility Site Address (include zip code):

21712 HWY 72 NORTH
 LOUDON, TN 37774

Facility Mailing Address (include zip code):

650 25TH STREET NW
 SUITE 100
 CLEVELAND, TN 37311

Facility Point of Contact:

Name: LEVI HIGDON/RAY STEWART/JAMIE MILLER
 Title: SITE MANAGER/CONTROLLER/STAFF ACCOUNTANT
 Phone Number: (423) 476-9160
 Fax Number: (423) 339-5664
 E-mail: jmillers@santekenviro.com

County of Waste Origin or Transfer Station from which Received	Disposal Facility/Incinerator to which Transferred (if applicable)	Amount of Waste Received at Facility (tons)
PLEASE	INCLUDE ALL OUT-OF-STATE	WASTE
LOUDON CO, TN		52,280.01
BRADLEY CO, TN		2.72
KNOX CO, TN		12,147.20
MCMINN CO, TN		6.83
MONROE CO, TN		2.50
ROANE CO, TN		1,912.53
RHEA CO, TN		7.16

Contact Signature: Jamie Miller

Date: 1/27/12



TENNESSEE DEPARTMENT OF ENVIRONMENT & CONSERVATION
DIVISION OF SOLID WASTE MANAGEMENT- SOLID WASTE ASSISTANCE
401 Church Street, 5th Floor
Nashville, TN 37243-1535
QUARTERLY REPORT FOR LANDFILLS, INCINERATORS & TRANSFER STATIONS
ORIGIN OF CLASS I MUNICIPAL SOLID WASTE

WARREN CO, TN	7,177.57
Contact Signature: Jamie Miller	Date: 1/27/12



DEPARTMENT OF ENVIRONMENT AND CONSERVATION
 DIVISION OF Solid Waste Management- SWA
 Quarterly Solid Waste Surcharge and Facility Inspection Fee Report

(Type or print. See reverse for instructions)

Facility ID Number:
 SNL 53-103-0203

For Quarter Ending
 December 31, 2011

Facility Name and Address:
 Matlock Bend Landfill
 Santek Environmental
 650 25th St, NW, Suite 100
 Cleveland, TN 37311
 (Change if incorrect)

1. Facility Location
 21712 Hwy 72 North
 Loudon, TN 37774

2. Facility Owner/Operator
 Loudon County / Santek Environmental Inc

3. Telephone No.
 (423) 476-9160 ext 3013

4. Amount of waste received during each month of reporting period (in tons):

First month of quarter	<u>21370.05</u>
Second month of quarter	<u>25184.76</u>
Third month of quarter	<u>19804.15</u>

5. Total tons of waste received during reporting period: 66358.96

6(a). Surcharge: Total tons 66358.96 X \$0.90 = \$ 59723.06
 (This fee to begin on July 01, 2007)

(b). Deduct 1% if paid on or before due date Less \$ 597.23
 (This deduction to begin on July 01, 2007)

Total Surcharge \$ 59125.83

7. Facility Inspection Fee: Total tons 66358.96 X \$0.35 = \$ 23225.64

8. Outstanding debit or credit \$ Ø

9. Total due \$ 82351.47

Make check or money order payable to the Treasurer, State of Tennessee. Payments are due January 31, April 30, July 31, and October 31.

10. I certify that the information in this report is true and correct.
Jamie Miller 1/26/12

Matlock Bend Landfill 2012 Airspace Projection / Construction Schedule

DATE	REMAINING AIRSPACE ¹ (CY)	MONTHLY TONNAGE	ACTUAL / PROJECTED ²	UTILIZATION FACTOR	MONTHLY VOLUME CONSUMED (CY)	ENDING MONTHLY REMAINING AIRSPACE (CY)
		22,072		1.35		
Oct. 2, 2011	562,069	-	-	-	-	-
Oct. 3-31, 2011	-	21,122	A	1.35	28,514	533,555
November	-	25,185	A	1.35	33,999	499,556
December	-	19,804	A	1.35	26,736	472,820
January ' 12	-	21,228	A	1.35	28,658	444,162
February	-	22,072	P	1.35	29,797	414,365
March	-	22,072	P	1.35	29,797	384,568
April	-	22,072	P	1.35	29,797	354,770
May	-	22,072	P	1.35	29,797	324,973
June	-	22,072	P	1.35	29,797	295,176
July	-	22,072	P	1.35	29,797	265,379
August	-	22,072	P	1.35	29,797	235,582
September	-	22,072	P	1.35	29,797	205,784
October	-	22,072	P	1.35	29,797	175,987
November	-	22,072	P	1.35	29,797	146,190
December	-	22,072	P	1.35	29,797	116,393

¹ = Remaining airspace based on Oct. 2, 2011 aerial survey.

Full Date - Module F & G

April-2013

² = Projected tonnages are based on a 3 month average per Matt Dillard on 6-2-09.

³ = Utilization rate based on the annual utilization rate per October 27, 2008 construction meeting (Avg. Utilization = 1.46 cy/ton)

Tonnage for Past 3 Months

November	25,185
December	19,804
January	21,228
Average	22,072

cc: Matt
Rob
Kenny F.
Cheryl
Ron
Chris
Levi
David M.
Jason



650 25th Street, N.W., Suite 100
Cleveland, Tennessee 37311
(423)476-9160
Toll Free: (800)467-9160
Fax: (423)479-1952

Email: mail@santekenviro.com
Internet: www.santekenviro.com

February 14, 2012

Loudon County Solid Waste Disposal Commission
100 River Road
P.O. Box 351
Loudon, TN 37774

Dear Steve:

Pursuant to Section 10.6 and 10.7 of the Sanitary Landfill Operation Agreement between Loudon and Santek as of July 1, 2007, Santek agreed to pay the Commission a host fee and security fee as defined in the Agreement. The following recap reflects the calculation for the period January 1, 2012 to January 31, 2012:

Host Fees (Greater of below) –

Total Tip Fees Billed	\$347,485.31
Host Fee Percentage	4.00%
	<u>\$ 13,899.41</u>
Minimum Fee	<u>\$ 10,652.00</u>

Security Fees (Greater of below) –

Total Tonnage Received	21,228.22
Rate per ton	\$ 1.00
Total	<u>\$ 21,228.22</u>

Total Tip Fees Billed	\$347,485.31
Security Fee Percentage	5.00%
	<u>\$ 17,374.27</u>

Our checks in payment of the above fees have been remitted to the above address for the Commission. Should you have any questions or need additional information, please let me know.

Sincerely,

Ray D. Stewart
Assistant V.P. of Finance

Landfill Solutions Under
Local Government's Authority.