

**LOUDON COUNTY GOVERNMENT  
SURPLUS PROPERTY AUTHORITY  
July 21, 2025**

**MEMBERS**

Commissioner Adam Waller  
Commissioner Will Jenkins  
Commissioner Chase Randolph  
Commissioner Joe Morrison  
Mayor Buddy Bradshaw  
Purchasing Director Matt Kleinschmidt

**AGENDA**

**1. Sheriff's Office**

- a. 2010 DRS Fermont Generator**
- b. Mitsubishi Mini Cab Truck**
- c. 2000 Miller Electric Arc Welder**
- d. 2009 Kawasaki Diesel Motorcycles**
- e. 1997 Military Cargo Trailer**
- f. 2008 Military Cargo Trailer**
- g. 2002 Sea Ray Boat**
- h. 2016 Dodge Charger**
- i. 2014 Dodge Charger**
- j. 2012 Dodge Charger**

**2. Senior Center**

- a. Workout Equipment**

## GovDeals Generic Inspection Form

Inventory ID: <u>16228TN00007</u>	Asset Number	Anticipated Sale Price: <u>\$5000</u>
Short Description: <u>GENERATOR SET, DIESEL FUELED TACTICAL QUIET</u>		
Year <u>2010</u>	Manufacturer <u>DRS VERMONT</u>	Model <u>MEP-804B</u>

Please fill in or check if apply Long Description:

This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☒ The Condition is Unknown

☒ Hours: 21.9 This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # FZ 64008

Repairs needed: UNKNOWN CONDITION - NO APPARENT EXTERNAL DAMAGE

Description of Use

<u>120/208V 3PH</u>	<u>AMPS - 52.26</u>	<u>MODE 1 (50/60 HERTZ)</u>
<u>240/416V 3PH</u>	<u>DRY WT - 1885 LB</u>	<u>SIZE 15 (15 KW)</u>

Color WOODLAND CAMO ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: 69.7 Width/Depth: Feet: \_\_\_\_\_ Inches: 35.7 Height: Feet: \_\_\_\_\_ Inches: 55.0

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

TRAILER MOUNTED - SEE PHOTOS

Location of Asset: <u>LOUDON COUNTY SHERIFF'S OFFICE</u>
For more information contact: <u>ANDREW SLEMP - ASLEMP@LCSOTN.ORG</u>






# GovDeals Vehicle Inspection Form

Inventory ID: <u>15281TN00007</u>	Asset Number:	Fair Market Value: <u>\$1000</u>																	
Short Description: Year <u>1990s</u> Make <u>MITSUBISHI</u> Model <u>MINI CAB - MINI TRUCK</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr> <td>1</td><td>✓</td><td>4</td><td>F</td><td>S</td><td>V</td><td>0</td><td>0</td><td>T</td><td>A</td><td>U</td><td>0</td><td>0</td><td>3</td><td>1</td><td>6</td><td>2</td> </tr> </table>		1	✓	4	F	S	V	0	0	T	A	U	0	0	3	1	6	2	Title Restriction: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <u>NO TITLE</u>
1	✓	4	F	S	V	0	0	T	A	U	0	0	3	1	6	2			
Mileage/Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr> <td>3</td><td>4</td><td>1</td><td>1</td><td>0</td> </tr> </table>		3	4	1	1	0	Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____												
3	4	1	1	0															
Long Description:																			
This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only																			
Engine- Type: _____ L, V <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <u>4 CYCLE ENGINE</u>																			
Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> is in unknown condition																			
Repairs needed: _____																			
This vehicle was maintained every _____ <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles																			
Date Removed From Service: <u>2020</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection																			
Transmission: <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual <u>3</u> Speed																			
Transmission Condition: <input type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is Unknown Condition																			
Repairs Needed: _____																			
Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>WHITE</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____																			
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat _____ Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4																			
Major Damage to: _____																			
Additional Damage: _____																			
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions																			
Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes																			
Interior: Color <u>GRAY</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather																			
Damage to Seats: <u>SEATS ARE TORN IN PLACES</u>																			
Damage to Dash/Floor: _____																			
Radio: <input type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD																			
<input type="checkbox"/> AC (Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown) <input type="checkbox"/> No AC Air Bags <input type="checkbox"/> drivers side <input type="checkbox"/> dual																			
<input type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control																			
Power: <input type="checkbox"/> Windows <input type="checkbox"/> Door Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats																			
Additional Equipment: <u>SPRINKLER / CONTENTS OF TRUCK BED NOT INCLUDED</u>																			
Manufacturer _____ Model _____ Serial # _____																			
Location of Asset: <u>LOUISE COUNTY SHERIFF'S OFFICE</u>																			
For more information contact: <u>ANDREW SLEMP - ASLEMP@LC50TN.ORG</u>																			
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			



Liquidity Services Brands

About Us | Buy | Sell | FAQ | Contact Us |  View Canada

**GovDeals**<sup>®</sup>  
A Liquidity Services Marketplace

⌕ Ei

Categories  
Search Assets

Location Search

Closing Today

New

Home / Transportation / Passenger Vehicles / Vehicles, Miscellaneous / Lot# 2664-32

1 / 1



## MINI TRUCK

**\$726.00 USD** (18 Bids)

Closed:

(May 29, 2015 05:15 PM EDT)



# GovDeals Generic Inspection Form

Inventory ID: 16228TN00008 Asset Number \_\_\_\_\_ Anticipated Sale Price: ~ \$ 5000

Short Description: ELECTRIC ARC WELDING MACHINE  
Year 2000 Manufacturer MILLER ELECTRIC MFG CO. Model BIG 40 DIESEL

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☒ The Condition is Unknown

☒ Hours: 6.5 This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # LA265159

Repairs needed: UNKNOWN CONDITION - HAS NOT BEEN USED

Description of Use TRAILER - MOUNTED

ENGINE-DRIVEN WELDER KNOWN FOR ITS ROBUST AND INDUSTRIAL DESIGN AND PERFORMANCE. LOW SPEED INDUSTRIAL ENGINE.

Color GREEN ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: 64 1/2 Width/Depth: Feet: \_\_\_\_\_ Inches: 24 5/8 Height: Feet: \_\_\_\_\_ Inches: 48-3/4

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition


Description: \_\_\_\_\_

Comments:

Location of Asset: LOUDON COUNTY SHERIFF'S OFFICE

For more information contact: ANDREW SIEMPA ASLEMP@LCSOTN.ORG







122-44530-LESSO

Inventory ID:

LESSO M1030 A

Asset Number:

Fair Market Value:

\$ 6100

Short Description:

Year 2009

Make KAWASAKI

Model M1030 M1

VIN:

J K A K L E A 1 4 Y A 0 5 8 4 3 8

Title Restriction: ☐ Y ☐ N

Mileage/Odometer:

0 2 1 8 . 5

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs ☒ Does Not Run ☐ For Parts OnlyEngine- Type:      L, V      ☐ Gas ☒ Diesel Engine (MULTI-FUEL JP8)Engine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown conditionRepairs needed: VEHICLE DOES NOT RUN AT PRESENTThis vehicle was maintained every      ☐ Days ☐ Hours ☐ MilesDate Removed From Service: 2023 Maintenance Records: ☐ Available ☒ Not Available For InspectionTransmission: ☐ Automatic ☒ Manual      SpeedTransmission Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown ConditionRepairs Needed:     Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:     

Exterior:

Color: GREEN/DIGITALWindows: ☐ No Cracked Glass ☐ Cracked     Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: ☐ Low      ☐ Flat      Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4Major Damage to:     Additional Damage:     Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No ImpressionsEmergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color      ☐ Cloth ☐ Vinyl ☐ LeatherDamage to Seats: NONEDamage to Dash/Floor:     Radio: ☐ Stock or ☐ Brand & Model:      ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags ☐ drivers side ☐ dual☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate ControlPower: ☐ Windows ☐ Door Locks ☐ Steering ☐ SeatsAdditional Equipment:     Manufacturer     Model     Serial #     Location of Asset: LOUDON COUNTY SHERIFF'S OFFICEFor more information contact: ANDREW SLEMP - ASLEMP@LCSO.TH.ORG

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.








(17V) 17654  
(1P) M1030M1  
(USMC REG #) 598808

VIN # JKAKLEA14YAD58438  
NSN 2340-01-530-9371  
RE-MANUFACTURE DATE 09/2009  
CONTRACT NUMBER M67854-04-D-5057/0002







122-44530-LESSO

SHERIFF'S OFFICE INSPECTION FORM

Inventory ID:

LESSO M1030 B

Asset Number:

Fair Market Value:

\$ 6000

Short Description:

Year 2007

Make KAWASAKI

Model M1030M1

VIN:

J K A K L E A 1 3 3 0 A 0 4 4 1 4

Title Restriction: ☐ Y ☐ N

Mileage/Odometer:

0 1 3 0 . 2

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs ☒ Does Not Run ☐ For Parts OnlyEngine- Type:      L, V      ☐ Gas ☒ Diesel Engine (MULTI-FUEL JP8)Engine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown conditionRepairs needed: VEHICLE DOES NOT RUN AT PRESENTThis vehicle was maintained every      ☐ Days ☐ Hours ☐ MilesDate Removed From Service: 2023Maintenance Records: ☐ Available ☒ Not Available For InspectionTransmission: ☐ Automatic ☒ Manual      SpeedTransmission Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown ConditionRepairs Needed:     Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:     

Exterior:


Color: GREEN / DIGITALWindows: ☐ No Cracked Glass ☐ Cracked     Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: ☐ Low      ☐ Flat      Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4Major Damage to:     Additional Damage:     Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No ImpressionsEmergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color      ☐ Cloth ☐ Vinyl ☐ LeatherDamage to Seats: NONEDamage to Dash/Floor:     Radio: ☐ Stock or ☐ Brand & Model:      ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags ☐ drivers side ☐ dual☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate ControlPower: ☐ Windows ☐ Door Locks ☐ Steering ☐ SeatsAdditional Equipment:     Manufacturer     Model     Serial #     Location of Asset: LOUDON COUNTY SHERIFF'S OFFICEFor more information contact: ANDREW SLEMP - ASLEMP@LCSOTN.ORG

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.





122-44530-LESSO

INSPECTION FORM

Inventory ID: <u>LESSO M1030C</u>	Asset Number:	Fair Market Value: \$ <u>6000</u>																	
Short Description: Year <u>2006</u> Make <u>KAWASAKI</u> Model <u>M1030M1</u>																			
VIN: <table border="1"><tr><td>J</td><td>K</td><td>A</td><td>K</td><td>L</td><td>E</td><td>A</td><td>I</td><td>S</td><td>3</td><td>D</td><td>A</td><td>0</td><td>4</td><td>4</td><td>1</td><td>5</td></tr></table>		J	K	A	K	L	E	A	I	S	3	D	A	0	4	4	1	5	Title Restriction: <input type="checkbox"/> Y <input type="checkbox"/> N
J	K	A	K	L	E	A	I	S	3	D	A	0	4	4	1	5			
Mileage/Odometer: <table border="1"><tr><td>0</td><td>0</td><td>8</td><td>8</td><td>.</td><td>2</td></tr></table>		0	0	8	8	.	2	Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____											
0	0	8	8	.	2														
Long Description: This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>  L, V  </u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine ( <u>MULTI-FUEL TP8</u> ) Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> is in unknown condition Repairs needed: <u>VEHICLE DOES NOT RUN AT PRESENT</u> This vehicle was maintained every _____ <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles Date Removed From Service: <u>2023</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection <b>Transmission:</b> <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual <u>  </u> Speed Transmission Condition: <input type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is Unknown Condition Repairs Needed: _____ <b>Drivetrain:</b> <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: _____ <b>Exterior:</b> Color: <u>GREEN / DIGITAL</u> Windows: <input type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____ Minor: <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <u>  </u> <input type="checkbox"/> Flat <u>  </u> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 Major Damage to: _____ Additional Damage: _____ Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes <b>Interior:</b> Color _____ <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>NONE</u> Damage to Dash/Floor: _____ Radio: <input type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input type="checkbox"/> AC (Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown) <input type="checkbox"/> No AC Air Bags <input type="checkbox"/> drivers side <input type="checkbox"/> dual <input type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input type="checkbox"/> Windows <input type="checkbox"/> Door Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats <b>Additional Equipment:</b> _____ Manufacturer _____ Model _____ Serial # _____ Location of Asset: <u>LOUDON COUNTY SHERIFF'S OFFICE</u> For more information contact: <u>ANDREW SLEMP - ASLEMP@LCSOTN.ORG</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			







Inventory ID:

LESSO M1030D

Asset Number:

Fair Market Value:

\$6000

Short Description:

Year 2007

Make KAWASAKI

Model M1030M1

VIN:

J K A K L E A I 8 3 D A 0 6 7 3 9

Title Restriction: ☐ Y ☐ N

Mileage/Odometer:

0054.6

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs ☒ Does Not Run ☐ For Parts OnlyEngine- Type:      L, V ☐ Gas ☒ Diesel Engine (MULTI-FUEL TPS)Engine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown conditionRepairs needed: VEHICLE DOES NOT RUN AT PRESENT -This vehicle was maintained every      ☐ Days ☐ Hours ☐ MilesDate Removed From Service: 2023 Maintenance Records: ☐ Available ☒ Not Available For InspectionTransmission: ☐ Automatic ☒ Manual      SpeedTransmission Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown ConditionRepairs Needed:     Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:     Exterior: Color: GREEN / DIGITAL Windows: ☐ No Cracked Glass ☐ Cracked     Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: ☐ Low      ☐ Flat      Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4Major Damage to:     Additional Damage:     Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No ImpressionsEmergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holesInterior: Color      ☐ Cloth ☐ Vinyl ☐ LeatherDamage to Seats: NONEDamage to Dash/Floor:     Radio: ☐ Stock or ☐ Brand & Model:      ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags ☐ drivers side ☐ dual☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate ControlPower: ☐ Windows ☐ Door Locks ☐ Steering ☐ SeatsAdditional Equipment:     Manufacturer      Model      Serial #     Location of Asset: LOUDON COUNTY SHERIFF'S OFFICEFor more information contact: ANDREW SLEMP - ASLEMP@LCSO.TN.ORG

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.





## GovDeals Generic Inspection Form

Inventory ID: <u>13304TN009</u>	Asset Number	Anticipated Sale Price: <u>\$ 1500</u>
Short Description: <u>MILITARY CARGO TRAILER</u>		
Year <u>1997</u>	Manufacturer	Model <u>M1101</u>

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ DaysSerial # 03970Repairs needed: CONDITION OF WIRING / LIGHTS UNKNOWN

Description of Use

M1101 MILITARY CARGO TRAILER3400 LB GVWRColor WOODLAND CAMO / GREEN ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: 11 Inches: 3 Width/Depth: Feet: \_\_\_\_\_ Inches: 88 Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: LOUDON COUNTY SHERIFF'S OFFICEFor more information contact: ANDREW SLEMPA A SLEMPA @ LC50TN.0124





# GovDeals Generic Inspection Form

Inventory ID: <u>16228TN00063</u>	Asset Number	Anticipated Sale Price: <u>\$ 2500</u>
Short Description: <u>MILITARY CARGO TRAILER</u>		
Year <u>2008</u>	Manufacturer	Model <u>M1101</u>

Please fill in or check if apply Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # 21981

Repairs needed: CONDITION OF WIRING UNKNOWN

Description of Use

M1101 MILITARY CARGO TRAILER - HAS LED LIGHTS.

3400 LB GVWR

Color DESERT TAN ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: 11 Inches: 3 Width/Depth: Feet: \_\_\_\_\_ Inches: 88 Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Location of Asset: LOUISIANA COUNTY SHERIFF'S OFFICE

For more information contact: ANDREW SLEMP - ASLEMP@LCSOTN-0126





## GovDeals Vehicle Inspection Form

Inventory ID: \_\_\_\_\_

Asset Number: \_\_\_\_\_

Fair Market Value: \_\_\_\_\_

Short Description:

Year 2002Make SEA RAYModel V1305VIN: 

H	0	L	#			S	E	R	V	1	3	0	5	G	1	0	2
---	---	---	---	--	--	---	---	---	---	---	---	---	---	---	---	---	---

Title Restriction: ☐ Y ☐ NMileage/Odometer: 

--	--	--	--	--	--

Odometer Accurate ☐ Y ☐ N: \_\_\_\_\_

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs ☒ Does Not Run ☐ For Parts OnlyEngine- Type: L, V 8 ☒ Gas ☐ Diesel EngineEngine Condition: ☐ Runs ☒ Needs repair ☒ is in unknown condition

Repairs needed: \_\_\_\_\_

This vehicle was maintained every \_\_\_\_\_ ☐ Days ☐ Hours ☐ MilesDate Removed From Service: 9.01.2023 Maintenance Records: ☐ Available ☐ Not Available For InspectionTransmission: ☐ Automatic ☐ Manual SpeedTransmission Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

Drivetrain: ☐ 2 Wheel Drive ☐ 4 Wheel Drive Condition: \_\_\_\_\_

Exterior:

Color: WHITEWindows: ☐ No Cracked Glass ☐ CrackedMinor: ☐ Dents ☐ Scratches ☐ DingsTire Condition: ☐ Low ☐ Flat Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4

Major Damage to: \_\_\_\_\_

Additional Damage: \_\_\_\_\_

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No ImpressionsEmergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color WHITE☐ Cloth ☒ Vinyl ☐ LeatherDamage to Seats: YesDamage to Dash/Floor: YesRadio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No ACAir Bags ☐ drivers side ☐ dual☐ Cruise Control☐ Tilt Steering☐ Remote Mirrors☐ Climate ControlPower: ☐ Windows ☐ Door Locks ☐ Steering ☐ Seats

Additional Equipment: \_\_\_\_\_

Manufacturer \_\_\_\_\_

Model \_\_\_\_\_

Serial # \_\_\_\_\_

Location of Asset: LCSOFor more information contact: CWADEN@LCSOTN.ORG

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.











## GovDeals Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
---------------	---------------	--------------------

Short Description:  
Year 2016      Make DODGE      Model CHARGER

VIN: 

2	C	3	C	D	X	A	T	4	G	H	3	4	7	4	5	6
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

      Title Restriction: ☐ Y ☐ N

Mileage/Odometer: 

1	4	7	7	4	8
---	---	---	---	---	---

      Odometer Accurate ☐ Y ☐ N: \_\_\_\_\_

Long Description:  
This Vehicle: ☐ Starts ☒ Starts with a Boost    &    ☐ Runs ☐ Does Not Run ☐ For Parts Only  
Engine- Type: 5.7 L, V 8    ☒ Gas ☐ Diesel Engine  
Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition  
Repairs needed: OIL CONSUMPTION  
This vehicle was maintained every 3,000    ☐ Days ☐ Hours ☒ Miles  
Date Removed From Service: 5.13.2026    Maintenance Records: ☐ Available ☒ Not Available For Inspection  
Transmission: ☒ Automatic    ☐ Manual    Speed  
Transmission Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition  
Repairs Needed: \_\_\_\_\_  
Drivetrain: ☒ 2 Wheel Drive    ☐ 4 Wheel Drive    Condition: \_\_\_\_\_

Exterior:      Color: WHITE      Windows: ☒ No Cracked Glass    ☐ Cracked  
Minor: ☒ Dents    ☒ Scratches    ☒ Dings    Tire Condition: ☒ Low    ☐ Flat    Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4  
Major Damage to: \_\_\_\_\_  
Additional Damage: \_\_\_\_\_  
Decals: ☐ None    ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain    ☐ No Impressions  
Emergency equip: ☐ None    ☒ Has been removed & ☒ There are holes in the exterior    ☐ There are no holes

Interior:      Color: BLACK      ☒ Cloth ☒ Vinyl ☐ Leather  
Damage to Seats: \_\_\_\_\_  
Damage to Dash/Floor: \_\_\_\_\_  
Radio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_    ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD  
☒ AC (Condition: ☒ Cold ☐ Unknown)    ☐ No AC      Air Bags ☐ drivers side ☒ dual  
☐ Cruise Control    ☒ Tilt Steering    ☐ Remote Mirrors    ☐ Climate Control  
Power: ☒ Windows    ☒ Door Locks    ☒ Steering    ☒ Seats

Additional Equipment: \_\_\_\_\_  
Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

Location of Asset: LC50  
For more information contact: CWALDEN@LC50TN.ORG  
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.







## GovDeals Vehicle Inspection Form

Inventory ID:

Asset Number:

Fair Market Value:

Short Description:

Year 2014Make DODGEModel CHARGER

VIN:

2	C	3	C	D	X	A	T	X	E	H	3	4	9	1	5	8
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Title Restriction: ☐ Y ☐ N

Mileage/Odometer:

2	0	8	1	2	8
---	---	---	---	---	---

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs ☐ Does Not Run ☐ For Parts OnlyEngine- Type: 5.7 L, V 8 ☒ Gas ☐ Diesel EngineEngine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown conditionRepairs needed: HAS BAD MODULESThis vehicle was maintained every 3,000 ☐ Days ☐ Hours ☒ MilesDate Removed From Service: 5.13.2025 Maintenance Records: ☐ Available ☒ Not Available For InspectionTransmission: ☒ Automatic ☐ Manual SpeedTransmission Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: \_\_\_\_\_

Exterior:

Color: WHITEWindows: ☒ No Cracked Glass ☐ Cracked \_\_\_\_\_Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: ☒ Low ☐ Flat \_\_\_\_\_ Hubcaps ☐ 1 ☐ 2 ☐ 3 ☐ 4

Major Damage to: \_\_\_\_\_

Additional Damage: \_\_\_\_\_

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No ImpressionsEmergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior:

Color BLACK☒ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: \_\_\_\_\_

Damage to Dash/Floor: \_\_\_\_\_

Radio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags ☐ drivers side ☒ dual☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate ControlPower: ☒ Windows ☒ Door Locks ☒ Steering ☒ Seats

Additional Equipment: \_\_\_\_\_

Manufacturer \_\_\_\_\_

Model \_\_\_\_\_

Serial # \_\_\_\_\_

Location of Asset: LC50For more information contact: CWALDEN@LC50TN.ORG

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.







## GovDeals Vehicle Inspection

Inventory ID:	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2012</u> Make <u>DODGE</u> Model <u>CHARGER</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center;"><tr><td>2</td><td>C</td><td>3</td><td>C</td><td>D</td><td>X</td><td>A</td><td>T</td><td>5</td><td>C</td><td>H</td><td>Z</td><td>5</td><td>8</td><td>8</td><td>2</td><td>8</td></tr></table>		2	C	3	C	D	X	A	T	5	C	H	Z	5	8	8	2	8	Title Restriction: <input type="checkbox"/> Y <input type="checkbox"/> N
2	C	3	C	D	X	A	T	5	C	H	Z	5	8	8	2	8			
Mileage/Odometer: <table border="1" style="display: inline-table; text-align: center;"><tr><td>2</td><td>0</td><td>8</td><td>9</td><td>0</td><td>2</td></tr></table>		2	0	8	9	0	2	Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____											
2	0	8	9	0	2														
Long Description:																			
This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only																			
Engine- Type: <u>5.7 L V 8</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine																			
Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition																			
Repairs needed: _____																			
This vehicle was maintained every <u>3,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles																			
Date Removed From Service: <u>9.01.2023</u> Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection																			
Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual _____ Speed																			
Transmission Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition																			
Repairs Needed: _____																			
Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>WHITE</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____																			
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat _____ Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4																			
Major Damage to: _____																			
Additional Damage: _____																			
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions																			
Emergency equip: <input type="checkbox"/> None <input checked="" type="checkbox"/> Has been removed & <input checked="" type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes																			
Interior: Color <u>BLACK</u> <input checked="" type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather																			
Damage to Seats: _____																			
Damage to Dash/Floor: _____																			
Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD																			
<input type="checkbox"/> AC (Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown) <input type="checkbox"/> No AC Air Bags <input type="checkbox"/> drivers side <input checked="" type="checkbox"/> dual																			
<input type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control																			
Power: <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Seats																			
Additional Equipment: _____																			
Manufacturer _____ Model _____ Serial # _____																			
Location of Asset: <u>LCSO</u>																			
For more information contact: <u>DWALDEN@LCSOTN.ORG</u>																			
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			







Cost in 2007  
\$ 2,699.00

GovDeals Generic Inspection Form

Inventory ID: <u>LCSC-6600</u>	Asset Number	Anticipated Sale Price:
Short Description: <u>Stand up Elliptical - Corporate HRT Elliptical</u>		
Year <u>2007</u>	Manufacturer <u>Vision X 6600 Dual Action</u>	Model <u>Vis-X 6600 HRT5</u>

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days -- As Needed

Serial # VEP000706090888

Repairs needed: Small Right hand handlebar end is broken off - covered w/ tennis ball

Description of Use

Used daily Monday - Friday Senior Ctr.

Color Gray/Black ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☒ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_



Cost in 2006  
\$2,199.00

GovDeals Generic Inspection Form

Inventory ID: Senior Citizens  
LCSC-2650-1

Asset Number

Anticipated Sale Price:

Short Description: Reclumbent Bike - (19 yrs old)

Year 2006

Manufacturer Vision Fitness

Model HRT R2650

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days (As Needed)

Serial # \_\_\_\_\_

Repairs needed: Bottom seat has 2 cracks in it

Description of Use

Used Monday - Friday at Senior Ctr. daily

Color Black/Gray ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☒ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_



Cost in 2017  
\$ 3,327.60

GovDeals Generic Inspection Form

Inventory ID: <u>LCSC-CTM7071801W00048</u>	Asset Number	Anticipated Sale Price:
Short Description: <u>Treadmill</u>		
Year <u>2017</u>	Manufacturer <u>Matrix</u>	Model <u>T3X-05</u>

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days As Needed

Serial # CTM 7071801W00048

Repairs needed: \_\_\_\_\_

(15% Incline) Speed Range: 5-12mph One Button Start - 120V Elec Plug - LED display

Senior Center, gym Monday - Friday, used daily  
Max User Weight: 400 lbs / Running Belt 60" x 20" / 84.6" x 33.5" x 56"

Color Black/Gray ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☒ Plastic ☐ Wood ☒ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_

Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_



2017  
\$3,327.50

# GovDeals Generic Inspection Form

Inventory ID: LC9C-CTM7071801W00043	Asset Number	Anticipated Sale Price:
Short Description: <u>Treadmill</u>		
Year <u>2017</u>	Manufacturer <u>Matrix</u>	Model <u>T-3X-05-C</u>

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days As Needed

Serial # CTM 7071801W00043

Repairs needed: \_\_\_\_\_

< 0-15% Incline > < Speed Range .5 - 12mph > One Button start (120V Plug)  
Description of Use

Monday - Friday used at Senior Center daily  
Emergency safety clip / LED display / Running Area 60" x 20" / Max User Weight: 400lbs

Color Black / Gray ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☒ Plastic ☐ Wood ☒ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: 84.6" 33.5" 56" Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_

Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments: \_\_\_\_\_

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_



# GovDeals Generic Inspection Form

Inventory ID: LCSC-958 Senior Ctr.

Asset Number

Anticipated Sale Price:

Short Description: 4 Stack Multi Station - (19 yrs. old)

Year \_\_\_\_\_ Manufacturer Legend Fitness.com

Model \_\_\_\_\_

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days (As Needed)

Serial # \_\_\_\_\_

Repairs needed: None

Description of Use

Used daily Monday-Friday weight lifting multi station

Color White <sup><Blockseats></sup> ☐ Cloth ☒ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:


Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_









Quiet Please  
Yoga  
in Session



